

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS/MSG22008195/DWY3E2**Date:** 21/11/2022REFERENCE

Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd.	Policy No:	1001953188
Claimant Vehicle No :	SMY3493E	Insured Vehicle No :	FBP3207T
Date of Loss:	23/08/2022	Nature of Claim:	TP
		Claim No:	282946

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SMY3493E	Engine No:	L15B6020034
Make & Model:	HONDA SHUTTLE, 1.5 G CVT SENSING (A)	Chassis No:	GK82100020
Reg. Date:	01/03/2021 (Man. Year: 2019)	Odometer:	34992 km
Colour:	Silver		
Engine Capacity:	1496 cc		
Market Value/New Car Price:	N/A		
Sum Insured (\$\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	185/60 R15	Rear Tyre Size:	185/60 R15
Front Left Side:	Yokohama 5 mm	Rear Left Side:	Yokohama 5 mm
Front Right Side:	Yokohama 5 mm	Rear Right Side:	Yokohama 5 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	4,422.40	438.04	3,984.36	90.09
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,220.00	800.00	2,420.00	75.16
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (\$\$)	7,642.40	1,238.04	6,404.36	83.80
+ GST 7.00/7.00% (\$\$)	534.97	86.66	448.31	83.80
Nett Amount (\$\$)	8,177.37	1,324.70	6,852.67	83.80

INSPECTION

Date of Assignment:	25/08/2022	JWG International Pte Ltd (HQ)
Date Inspected:	31/08/2022 Inspected At:	Blk 10, Ang Mo Kio Ind Park 2A,, #03-08 AMK
		AutoPoint
		Singapore 568047
Estimated Period of Repair:	2.0 days	

Adjuster: BRYAN TANI**Manager:** XinYu

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

(FOR MANDATE ONLY)

REPAIR DETAILS

Reference

Part Source:	(Last Synchronised: 21 Nov 2022)	
Parts:	N/A	HONDA SHUTTLE 1.5 G CVT SENSING (A) (Model not available in database)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SMY3493E)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*WING MIRROR RH	Broken	893.00 FL	*547.55 FL
2	1		*WING MIRROR COVER RH	Not Necessary	201.00 FL	*- FL
3	1		*WING MIRROR GLASS RH	Not Necessary	105.00 FL	*- FL
4	1		*FRONT FENDER HYBRID EMBLEM LH	Not fitted	1,000.00 FL	*- FL
5	1		*FRONT DOOR RH	Repair	240.00 FL	*- FL
6	1		*FRONT DOOR WEATHERSTRIP RH	Not Necessary	281.00 FL	*- FL
7	1		*FRONT DOOR WINDOW MOULDING RH	Not Necessary	140.00 FL	*- FL
8	1		*FRONT DOOR BLACK PLASTIC RH	Not Necessary	99.00 FL	*- FL
9	1		*REAR DOOR RH	Repair	1,830.00 FL	*- FL
10	1		*REAR DOOR WINDOW MOULDING RH	Not Necessary	140.00 FL	*- FL
11	1		*REAR DOOR BLACK PLASTIC RH	Not Necessary	99.00 FL	*- FL
12	1		*RIM COVER	Not Necessary	300.00 FS	*- FS
13	1		*FRONT DOOR INNER TRIMBOARD CLIPS	Not Necessary	50.00 FS	*- FS
14	1		*REAR DOOR INNER TRIMBOARD CLIPS	Not Necessary	50.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	5,428.00	547.55
- List Item Discount on L Items 20.00/20.00% (\$\$)	1,005.60	109.51
Total Parts (\$\$)	4,422.40	438.04

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO REMOVE ALL INTERIOR UPHOLSTERLY ITEMS TO FACILIATE REPAIRS	New	300.00	0.00
2	TO REMOVE & PANEL BEAT ALL DAMAGED ABOVE PARTS & PANELS	New	800.00	300.00
3	TO RESPRAY NEW PAINTWORK FOR ALL DAMAGED AREAS	New	1,000.00	500.00
4	TO CONDUCT COMPUTERIZED WHEEL ALIGNMENT	New	120.00	0.00
5	TO RNR REAR DOOR MECHANISM TO FACILITATE REPAIRS	New	250.00	0.00
6	TO CHECK & RE-FIX ALL ELECTRICAL WIRINGS	New	200.00	0.00
7	TO COMPUTERIZE DIAGNOSE FAULT CODES & CONTROL UNITS. RESET ALL MEMORIES TO FACTORY DEFAULT SETTINGS	New	300.00	0.00
8	TO RNR FRONT DOOR MECHANISM TO FACILITATE REPAIRS	New	250.00	0.00
Gross Labour Cost (\$\$)			3,220.00	800.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >