



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

## ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SME 9713L

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
<b><u>REPLACEMENT OF PARTS</u></b>				
1	REAR TOP PANEL	DISTORTED	1,188.70	1,188.70
2	REAR TOP PANEL MOULDING @\$69.30	NOT NECESSARY	138.60	-
1	REAR TOP INNER LINING	DEFORMED	627.70	627.70
1	REAR TOP PANEL INNER PANEL	DENTED	226.30	226.30
1	FRONT WINDSCREEN GLASS MOULDING TOP	NECESSARY	38.80	38.80
1	FRONT WINDSCREEN GLASS MOULDING BOTTOM	NECESSARY	50.70	50.70
1	FRONT WINDSCREEN GLASS SIDE MOULDING	NECESSARY	15.60	15.60
1	REAR FENDER LH	TO REPAIR SEE LABOUR	812.30	-
1	REAR FENDER RH	TO REPAIR SEE LABOUR	812.30	-
1	REAR LAMP LH	CUT	321.10	321.10
1	REAR LAMP RH	CUT	321.10	321.10
1	REAR BOOT COVER LAMP LH	CUT	139.60	139.60
1	REAR BOOT COVER LAMP RH	CUT	139.60	139.60
1	REAR WINDSCREEN GLASS	SHATTERED	932.10	932.10
1	REAR WINDSCREEN LOWER SIDE MOULDING	NECESSARY	35.10	35.10
3	REAR WINDSCREEN LOWER SIDE MOUNTING @\$33.40	NECESSARY	100.20	100.20
1	REAR BOOT CIVIC PLATE	NECESSARY	23.40	23.40
1	REAR BOOT LOGO	NECESSARY	19.00	19.00
1	REAR BOOT I-VTEC PLATE	NECESSARY	22.50	22.50
2	REAR FENDER SIDE MOULDING @\$68.30	NOT NECESSARY	136.60	-
1	REAR CAMERA	NOT NECESSARY	486.80	-
1	SPEAKER TRAY COMP (REAR) (ADDITIONAL)	CUT	394.80	394.80
	LESS 20% DISCOUNT		-1,396.58	-919.26
			5,586.32	3,677.04
<b><u>SPECIAL NETT ITEMS</u></b>				
1	FRONT WINDSCREEN SEALANT (SN)	NECESSARY	65.00	65.00
1	REAR WINDSCREEN SEALANT (SN)	NECESSARY	65.00	65.00
1	REAR FENDER WINDSCREEN SEALANT (SN)	NOT NECESSARY	65.00	-
1	REAR WINDSCREEN SOLAR FILM (SN) (ADDITIONAL)	NECESSARY	200.00	200.00

Report Ref No. CS/MSG22008196/AGcy3e2



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	PRIVATE HIRE STICKER (SN) (ADDITIONAL)	NECESSARY	160.00	60.00
			555.00	390.00
	<b>LABOUR</b>			
	TO DISMANTLE & REPLACE DAMAGE PARTS, PANEL BEAT WHERE NECESSARY. INCLUSIVE OF THE REPAIR OF REAR FENDER LH AND REAR FENDER RH.		1,500.00	800.00
	TO PUTTY, APPLY PRIMER & SPRAY PAINT ON THE AFFECTE PORTION.		1,600.00	800.00
	TO REMOVE AND REFIX FRONT AND REAR WINDSCREEN.		240.00	240.00
	TO REMOVE SIDE REAR FENDER GLASS BOTH SIDE.		160.00	120.00
	TO REMOVE CAR CUSHION AND ROOF TOP LINING.		250.00	200.00
	TO CHECK WIRING FUNCTIONS.		100.00	30.00
			3,850.00	2,190.00
<b>GRAND TOTAL</b>			<b>9,991.32</b>	<b>6,257.04</b>
<b>RECOMMENDED COST OF REPAIRS</b>				<b>6,257.04</b>

Report Ref No. CS/MSG22008196/AGcy3e2

XING GUO QIANG

M.MATAI, AMSAE-A

Automotive Assessor

ANG BRYAN TANI

Automotive Assessor / Investigator

**DISCLAIMER OF LIABILITY TO THIRD PARTIES:-** This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.