

**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

**VEHICLE DAMAGE INSPECTION REPORT****Our File No:** CS/CTI22008198/KNY3Q2**Date:** 08/11/2022**REFERENCE**

Handling Insurer: China Taiping Insurance (Singapore) Pte. Ltd. Policy No: DMPCSNA00170752201

**Claimant Vehicle No :** SMF8907X **Insured Vehicle No :** SMS380Z

Date of Loss: 19/08/2022 Nature of Claim: TP Claim No: SNM22D205954/C02/TAYHP

**DESCRIPTION & IDENTIFICATION OF VEHICLE**

Reg No: **SMF8907X**

Make & Model: MERCEDES-BENZ E200, 1.8 CGI (A) Engine No: 27186030003010

Reg. Date: 30/09/2009 (Man. Year: 2009) Chassis No: WDD2120482A073916

Colour: Metallic Black Odometer: 132039 km

Engine Capacity: 1796 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): **Market Value/New Car Price**

**CONDITION OF VEHICLE AT THE TIME OF SURVEY**

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

**CONDITION OF TYRES**

Front Tyre Size: 245/35Z R19 Rear Tyre Size: 275/30Z R19

Front Left Side: Questy 6 mm Rear Left Side: Questy 6 mm

Front Right Side: Questy 6 mm Rear Right Side: Questy 6 mm

*The above values represent the remaining tyre treads depth*

<b>COST OF CLAIMS</b>	<b>Repairer's</b>	<b>Adjuster's</b>	<b>Difference</b>	<b>Diff %</b>
Parts	2,127.00	1,980.00	147.00	6.91
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,150.00	950.00	200.00	17.39
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Calculated Gross Total (S\$)</b>	<b>3,277.00</b>	<b>2,930.00</b>	<b>347.00</b>	<b>10.59</b>
<b>Approved Total (Overridden) (S\$)</b>		<b>2,300.00</b>		
<b>(S\$)</b>	3,277.00	2,300.00	977.00	29.81
<b>+ GST 7.00/7.00% (S\$)</b>	229.39	161.00	68.39	29.81
<b>Nett Amount (S\$)</b>	<b>3,506.39</b>	<b>2,461.00</b>	<b>1,045.39</b>	<b>29.81</b>

**INSPECTION**

Date of Assignment: 06/10/2022 Present Location: Cheng Hoe Motor Pte Ltd (Yishun)

Date Inspected: 03/10/2022 Inspected At: Cheng Hoe Motor Pte Ltd (Yishun)  
Blk 1019 #01-374/382, Yishun Industrial Park A  
Singapore 768761

Estimated Period of Repair: 3.0 days

**Adjuster:** KENNETH KONG**Manager:** HUEY YON

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

REPAIR DETAILS

Reference		
Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 08 Nov 2022)
Parts:	143	MERCEDES-BENZ E200 1.8 CGI (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SMF8907X)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*1 PC REAR BUMPER	Buckled	860.00 F	*860.00 F
2	1		*1 PC REAR BUMPER LOWER TRIM	Bent	350.00 F	*350.00 F
3	1		*1 PC REAR BUMPER LOWER BRACE BAR LH	Serviceable	16.00 F	*- F
4	1		*1 PC REAR BUMPER LOWER BRACE BAR RH	Serviceable	16.00 F	*- F
5	1		*1 PC REAR BUMPER REINFORCEMENT	Bent	480.00 F	*480.00 F
6	1		*2 PCS REAR PDC SENSORS @145/PC	Shorted	290.00 F	*290.00 F
7	1		*1 PC REAR PDC SENSOR WIRE HARNESS	Serviceable	115.00 F	*- F
Total Parts (S\$)						2,127.00 1,980.00

F=Franchise part.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b>Labour Items</b>				
1	TO REPAIR BOOTLID,REAR END PANEL,REPLACE DAMAGED PARTS AND REALIGN THE SAME	New	500.00	400.00
2	PUTTY & RESPRAY REAR BUMPER,TRIM,BOOTLID,REAR END PANEL	New	600.00	500.00
3	RESET ECU / REPROGRAMME REVERSE SENSOR	New	50.00	50.00
<b>Gross Labour Cost (\$\$)</b>			<b>1,150.00</b>	<b>950.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >