

ASS. REC. BY:

REF:

A/G / 22 008200 / Ke

C

Kenneth

ASSIGNMENT

From:

Date:

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No:

at Workshop m/s

of

Insured:

Policy No.

Claims No.

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

Bal. or Market Value:

IDAC Accident Rpt:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

04 days

Res.: Yes or No

Lum Sum:

20 %

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date:

Person Contacted:

Vehicle: IN / OUT

Veh No:

SLU 41820

Yr Regn:

11 / 17

Type: M/Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

NIS Qashgai

c.c

1197

Colour

N Black

A/C:

Insured / Std / NI / NA

Sp. Reading

125787

T/Radio:

Insured / Std / NI / NA

Eng/No:

C/No:

SJNF EAJ 114-2004917

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Mod: Nil / S/Rim / STD / A/Rim or

Tyre Size:

F:

R:

215/60R17

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
TOYO / YOKO or

Front

Rear

R/Bal.

9

mm

R/Bal.

9

mm

L/Bal.

9

mm

L/Bal.

9

mm

D.O.A.

13/8/22

D.O.I.

18/8/2022

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

23/8 21 Rm 84850L Carbur

Date/Time, File Pass to?

☐

: Prel. Report

1)

Date/Time, File Return to?

☐

: Final Report

2)

Days Of Repair:

Resurvey No. of Trip:

Survey Fee:

Transportation

S + R.S. \$

Fines

Others

TOTAL

Add Fee:

☐

: Site Insp (\$

☐

: Interview (\$

☐

Tech Invs (\$

☐

Weekend (\$

Report Format :

Lump Sum / I.B.I: (\$

源摩哆廠

GUAN MOTOR WORKS

Business Regn. No: 08102600E

176 Sin Ming Drive #02-03 Sin Ming Autocare Singapore 575721 Tel: 6453 6111 Fax: 6453 8292 H/P: 9742 6003

REPAIR ESTIMATE FOR SLU4182D

Not Withheld
 11/11/18 4850/12
 Resurvey After Paint

4 days

No.	Qty	List Items	
1	1	Front bumper	\$ Bu 737.50 X
2	1	Front bumper RH fog lamp cover	\$ Sn 119.30 X
3	1	Front bumper RH fog lamp	\$ Pu 306.20 X
4	1	Front bumper RH side retainer	\$ Di 35.30
5	1 set	Front bumper clips	\$ Ru 40.00
6	1	Front bumper inner foam	\$ CM 236.70
7	1	Front bumper inner reinforcement	\$ R 817.70 X
8	1	RH headlamp (LED) 3243	\$ mycm 3,496.30
9	1	Front grille assy	\$ CM 525.50
10	1	Front grille "NISSAN" logo	\$ Ru 118.70
11	1	Front bonnet	\$ R 1,167.40 X
12	1	Front RH fender	\$ R 738.90 X
13	1	Front RH fender wheel arch garnish 510.60	\$ Bu 584.20
14	1	Front RH fender wheel arch garnish clips	\$ Ru 40.00
15	1	Front RH fender under shield	\$ Sn 138.80 X
16	1 set	Front fender under shield clips	\$ Ru 40.00 X
			\$ 9,142.50
17	1	Front Number Plate 5000	\$ 914.25
		Less 10%	\$ 8,228.25
		Total :	\$ 8,228.25

Labour

1	Labour Charges for remove/refit, panel beating, cutting welding and replacement of damages.	\$ 800.00 500
2	To putty and spray Spray Paintings charges.	\$ 800.00 600
3	To check wirings & lightings.	\$ 40.00 200
4	To remove, refit A/c condenser, radiator and etc..., including refill of A/c gas.	\$ Ru 140.00 X
5	To supply and apply anti rust treatment.	\$ Ru 80.00 X
	Total :	\$ 1,860.00

Total Parts and Labour : \$ 10,088.25

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature: