

## **LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

## ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. PA 8539R

Qty	Description of Parts	Condition	Estimate By Workshop (\$))	Our Adjusted (\$)
	REPLACEMENT OF PARTS			
1	REAR BUMPER	BUCKLED	2,200.00	1,800.00
1	REAR REINFORCEMENT PANEL	NOT NECESSARY	1,250.00	-
1	REAR RHS PANEL	BENT	1,700.00	1,450.00
2	REAR WINDSCREEN WEATHERSTRIP @\$300.00	NECESSARY	600.00	224.90
1	REAR TAIL LAMP (LHS)	CRACKED	480.00	449.20
1	REAR EMERGENCY DOOR (ADDITIONAL)	BENT	2,900.00	2,500.00
	LESS 25% DISCOUNT		-	-1,606.03
			9,130.00	4,818.07
	SPECIAL NETT ITEMS			
1	REAR BUMPER REVERSE SENSOR (SN)	NOT WORKING	380.00	220.00
2	SEALANT @\$26.00 (SN)	NECESSARY	52.00	52.00
			432.00	272.00
	<u>LABOUR</u>			
	SPRAY PAINTING ON REAR AFFECTED PORTION WITH ARTWORK.		1,600.00	900.00
	LABOUR & MISC. CHARGES: TO REMOVE THE AFFECTED PARTS & ALL RELEVANT ATTACHMENT & FITTINGS TO COMMENCE REPAIRS; CUT & WELD THE NECESSARY PARTS AS LISTED ABOVE; PANEL BEAT & RESHAPES THE AFFECTED AREAS; REPLACE THE DAMAGED COMPONENTS, REINSTALL & REALIGN ALL NECESSARY PARTS.		2,400.00	1,000.00
	LABOUR & MISC. CHARGES: TO REMOVE THE AFFECTED PARTS & ALL RELEVANT ATTACHMENT & FITTINGS TO COMMENCE REPAIRS; CUT & WELD THE NECESSARY PARTS AS LISTED ABOVE; PANEL BEAT & RESHAPES THE AFFECTED AREAS; REPLACE THE DAMAGED COMPONENTS, REINSTALL & REALIGN ALL NECESSARY PARTS. (ADDITIONAL)		400.00	300.00
			4,400.00	2,200.00
	GRAND TOTAL		13,962.00	7,290.07



Page No.:2 of 2

RECOMMENDED COST OF LUMP SUM REPAIRS	5,850.00
(TO ITS PRE-ACCIDENT CONDITION) (CONFIRMED)	

Report Ref No. CS/INC22008201/Rvy3e2

MOHAMMED RASUL BIN MOHD YUNUS

**Automotive Assessor** 

K.K.LAU CPT(RET)

BEng(Hons),B.Bus,MBA,PEng,PE, MInstAEA,MASME,MIRTE

**REGD Auto Consultant-SAE, Licensed Appraiser**