



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SLK 4761K

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
<u>REPLACEMENT OF PARTS</u>				
1	BOOT	BENT	1,200.00	950.40
1	BOOT LOCK	DISTORTED	800.00	301.30
1	REAR BUMPER	BUCKLED	800.00	800.00
1	FENDER LEFT	TO REPAIR SEE LABOUR	600.00	-
1	FENDER RIGHT	TO REPAIR SEE LABOUR	600.00	-
1	EXHAUST PIPE	TO REPAIR SEE LABOUR	350.00	-
1	BUMPER BRACKET LEFT	SERVICEABLE	350.00	-
1	BUMPER BRACKET RIGHT	SERVICEABLE	350.00	-
1	TAILLIGHT LEFT	MTG CRACKED	550.00	425.00
1	TAIL LIGHT RIGHT	MTG CRACKED	550.00	425.00
1	SPARE TYRE HOLDER	TO REPAIR SEE LABOUR	1,200.00	-
1	WEATHERSTRIP	CUT	60.00	60.00
1	END PANEL GARNISH	MTG DISTORTED	400.00	258.10
1	END PANEL METAL	BENT	400.00	400.00
1	REFLECTOR LIGHT LEFT	CRACKED	380.00	152.00
	LESS 25% DISCOUNT		-	-942.95
			8,590.00	2,828.85
<u>SPECIAL NETT ITEMS</u>				
4	REVERSE SENSOR x2 (SN)	DENTED	650.00	200.00
1	CAR PLATE (SN) }	CRACKED	50.00	45.00
1	CAR PLATE BRACKET (SN) }	CRACKED	50.00	-
			750.00	245.00
<u>LABOUR</u>				
	CHECKING OF WIRING, LIGHTING AND RESETTING.		300.00	20.00
	REMOVE AND REPLACE DAMAGED PARTS.		350.00	60.00
	APPLY UNDERCOATING ON REPAIRED AND REPLACED PANEL.		800.00	60.00

Report Ref No. CS/INC22008202/Kny3m4



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	WORKMANSHIP TO DISMANTLE ABOVE DAMAGED PARTS, REPAIRS INCLUDING CUT AND WIELD, REALIGN BODY STRUCTURE. INCLUSIVE OF THE REPAIR OF FENDER LEFT, FENDER RIGHT, EXHAUST PIPE AND SPARE TYRE HOLDER.		1,200.00	600.00
	RESPRAY INCLUDING POLISHING AND WAXING ON THE CHANGED BODY PARTS, REPAIRED PORTORTIONS WHERE CONSITENT TO THE ACCIDENT.		1,000.00	600.00
			3,650.00	1,340.00
GRAND TOTAL			12,990.00	4,413.85
RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION) (CONFIRMED)				3,500.00

Report Ref No. CS/INC22008202/Kny3m4

KONG SENG CHEONG

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or replying on this Report, in whole or in part, does so at his or her own risk.