

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CC3/AIG22008205/KPA3Q2**Date:** 04/11/2022REFERENCE

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	7210050494
Claimant Vehicle No :	SHC5282J	Insured Vehicle No :	SCP9998S
Date of Loss:	20/05/2022	Nature of Claim:	TP
		Claim No:	2302682778SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SHC5282J		
Make & Model:	TOYOTA PRIUS, 1.8 5DR HATCHBACK (A)	Engine No:	2ZR2H33941
Reg. Date:	30/11/2020 (Man. Year: 2020)	Chassis No:	JTDKB3FU803093119
Colour:	Metallic Pearl White/Red	Odometer:	202297 km
Engine Capacity:	1798 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	195/65 R15	Rear Tyre Size:	195/65 R15
Front Left Side:	Wanli 7 mm	Rear Left Side:	Firenza 8 mm
Front Right Side:	Wanli 7 mm	Rear Right Side:	Firenza 8 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	4,643.37	679.05	3,964.32	85.38
Miscellaneous Items	0.00	0.00	0.00	
Labour	4,380.00	430.00	3,950.00	90.18
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	9,023.37	1,109.05	7,914.32	87.71
+ GST 7.00/7.00% (S\$)	631.64	77.63	554.01	87.71
Nett Amount (S\$)	9,655.01	1,186.68	8,468.33	87.71
Global Sum Settlement (S\$)		0.00		

INSPECTION

Date of Assignment:	22/08/2022		
Date Inspected:	22/08/2022	Inspected At:	Trans-cab Auto Services Pte Ltd No 2 Ang Mo Kio Street 63 Singapore 569111
Estimated Period of Repair:	2.0 days		

Adjuster: KENNETH KONG**Manager:** CHEW HSIAO TONG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*COVER ,FRONT BUMPER	Buckled	521.00 FL	*521.00 FL
2	1		*BRACKET ,FRONT BUMPER EXTENSION MOUNTING	Serviceable	110.50 FL	*- FL
3	1		*COVER ,FRONT BUMPER HOLE ,LH	Missing	30.20 FL	*30.20 FL
4	1		*ABSORBER ,FRONT BUMPER ENERGY	Serviceable	80.20 FL	*- FL
5	1		*REINFORCEMENT SUB-ASSY ,FRONT BUMPER	Repair	716.60 FL	*- FL
6	1		*MOULDING FRONT BUMPER SIDE ,LH	Cracked	95.60 FL	*95.60 FL
7	1		*BRACKET ,FRONT BUMPER SIDE ,LH	Serviceable	59.30 FL	*- FL
8	1		*GRILLE SUB-ASSY ,RADIATOR	Serviceable	422.50 FL	*- FL
9	1		*GRILLE ,RADIATOR LOWER NO.1	Dented	178.60 FL	*178.60 FL
10	1		*FENDER SUB-ASSY ,FRONT LH	Repair	977.80 FL	*- FL
11	1		*FRONT FENDER EMBLEM LH	Not Necessary	54.60 FL	*- FL
12	1		*UNIT ASSY ,HEADLAMP LH	Serviceable	2,637.60 FL	*- FL
13	1		*FRT FENDER CLIP	Not Necessary	65.00 FS	*- FS
14	1		*SET FRONT FENDER LINER CLIP	Not Necessary	75.00 FS	*- FS
15	1		*SET FRONT BUMPER CLIP	Necessary	90.00 FS	*60.00 FS
F=Franchise part. S=SpcNett. L=ListItemDisc.						
Sub Total (\$\$)					6,114.50	885.40
- List Item Discount on L Items 25.00/25.00% (\$\$)					1,471.13	206.35
Total Parts (\$\$)					4,643.37	679.05
Report was unsubmitted during this print-out.						

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	PANEL BEATING ,KNOCKING AND STRAIGHTENING THE NECESSARY PORTION,REMOVE AND RENEWAL OF PARTS ,ADJUST AND REALIGN THE SAME	New	1,600.00	200.00
2	TO REMOVE AND REFIT INTERIOR FITTINGS,TRIMINGS,GARNISH,FITTINGS AND OTHER ,TO ENABLE REPAIR	New	380.00	0.00
3	TO RUST-PROOFING AND APPLY UNDERCOAT OF THE AFFECTED AREAS	New	240.00	0.00
4	TO CHECK STEERING GEOMETRY AND COMPUTER WHEEL ALIGNMENT	New	220.00	0.00
5	PUTTY AND SPRAY PAINTING OF THE AFFECTED PORTION	New	1,600.00	220.00
6	TO TRANSFER OF TIRE ,RIM AND ON WHEEL BALANCING	New	170.00	0.00
7	TO CHECK ELECTRICAL LIGHTING CONCERNED	New	170.00	10.00
Gross Labour Cost (\$)			4,380.00	430.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >