

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS/CTI22008208/DCY3Q2**Date:** 13/09/2022**REFERENCE**

Handling Insurer: China Taiping Insurance (Singapore) Pte. Ltd. Policy No: DMHCSNW00012302203

Claimant Vehicle No : SMN5454M **Insured Vehicle No :** SLK5273X

Date of Loss: 22/08/2022 Nature of Claim: TP Claim No: SNM22D205905/C02/TANKL

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SMN5454M**

Make & Model: HYUNDAI AD AVANTE, 1.6 GLS S (A) Engine No: G4FGKU110557

Reg. Date: 29/03/2019 (Man. Year: 2019) Chassis No: KMHD841CMKU879543

Colour: Grey Odometer: 56518 km

Engine Capacity: 1591 cc

Market Value/New Car Price: N/A

Sum Insured (\$\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 205/55 R16 Rear Tyre Size: 205/55 R16

Front Left Side: Kumho 5 mm Rear Left Side: Kumho 5 mm

Front Right Side: Kumho 5 mm Rear Right Side: Kumho 5 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	4,768.20	1,683.44	3,084.76	64.69
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,920.00	430.00	1,490.00	77.60
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Nett Amount (\$\$)	6,688.20	2,113.44	4,574.76	68.40

INSPECTION

Date of Assignment: 25/08/2022

Date Inspected: 25/08/2022 Inspected At: Alfred Auto Services & Supplies (HQ)
Blk 5035, Ang Mo Kio Ave 3, #01-351, Ang Mo Kio Industrial Park 2
Singapore 569538

Estimated Period of Repair: 2.0 days

Adjuster: BRYAN TANI**Manager:** CELINE FONG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source: MRM-SG Version: 1.0 (Last Synchronised: 12 Sep 2022)

Parts: 143 HYUNDAI AD AVANTE 1.6 GLS S (A) (Catalogue:Merimen Singapore 1.0)

Labour: Repairer's (Price-denominated Standard List)

Print Code: (Unsubmitted, no print-code for SMN5454M)

Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT RH DOOR	Dented	1,998.00 F	*1,831.10 FL
2	2		*FRONT RH DOOR HINGE	Bent	90.00 F	*90.00 FL
3	1		*FRONT RH DOOR STOPPER	Serviceable	38.00 F	*- FL
4	1		*FRONT RH DOOR WEATHER SLIP	Serviceable	296.00 F	*- FL
5	1		*FRONT RH DOOR TRIM BOARD	Not Necessary	786.10 F	*- FL
6	1		*FRONT RH DOOR HANDLE	Not Necessary	167.80 F	*- FL
7	1		*FRONT RH DOOR LOCK	Not Necessary	297.40 F	*- FL
8	1		*FRONT RH DOOR TRIM	Not Necessary	796.90 F	*- FL
9	1		*SET FRONT RH DOOR CHANNEL STICKER	Necessary	298.00 F	*183.20 FL
					Sub Total (\$\$)	4,768.20 2,104.30
					- List Item Discount on L Items 0.00/20.00% (\$\$)	0.00 420.86
					Total Parts (\$\$)	4,768.20 1,683.44

F=Franchise part. L=ListItemDisc.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO REMOVE & REFIT ALL WIRING & CHECK	New	120.00	30.00
2	TO KNOCKING STRAIGHTENING REPAIR & RENEW ALL ACCIDENT AFFECTED AREA	New	800.00	200.00
3	TO RESPRAY PAINTING INNER PILLAR ,DOOR HOUSING OUTER DOOR ,FENDER & ALL ACCIDENT AFFECTED AREA	New	1,000.00	200.00
Gross Labour Cost (\$\$)			1,920.00	430.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >