

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. FBQ 6474M

Qty	Description of Parts	Condition	Estimate By Workshop (\$))	Our Adjusted (\$)
	REPLACEMENT OF PARTS			
1	OHLINS SUSPENSION (FRONT FORK)	BENT	385.00	385.00
1	CRASH BAR (HANDLE BAR)	BENT	180.00	180.00
1	RIZOMA SIDE MIRRORS	CUT	85.00	85.00
1	FRONT & REAR SIGNAL LIGHTS	CUT	136.00	136.00
1	BOX & RACK	NOT NECESSARY	380.00	-
1	STEERING CONE	NECESSARY	220.00	80.00
1	FORK OIL SEAL	NECESSARY	160.00	60.00
1	HEADLIGHT BRACKET	NOT NECESSARY	90.00	-
1	BELLY PAN	BROKEN	65.00	65.00
1	CARBURETOR SERVICE	NOT NECESSARY	100.00	-
1	YUASA BATTERY	NOT NECESSARY	110.00	-
1	SPEED METER ASSEMBLY	NOT NECESSARY	580.00	-
1	YOSHIMURA EXHAUST & HEADER	BENT	880.00	880.00
1	HUGGER	NOT NECESSARY	95.00	-
1	RIMS	CUT	600.00	550.00
1	HEADLIGHT	NOT NECESSARY	138.00	-
1	NUMBER PLATE	NOT NECESSARY	20.00	-
1	H4 BULB	NOT NECESSARY	22.00	-
1	SWING ARM BUSH	NOT NECESSARY	150.00	-
	LESS 10% DISCOUNT		-	-242.10
			4,396.00	2,178.90
	<u>LABOUR</u>			
	COVER SET REFURBISH & SPRAY PAINT.		780.00	200.00
	RESPRAY RIMS.		350.00	200.00
	FORK PRESS (LABOUR).		320.00	100.00
	TOWING.		150.00	80.00
	WIRING.	NOT NECESSARY	200.00	-
	SWING ARM RE-ALIGNMENT.	NOT NECESSARY	420.00	-
	CHASSIS REPAIR.		450.00	200.00

Report Ref No. CS3/GRB21007566/Eny3e2-1



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$))	Our Adjusted (\$)
	LABOUR.		500.00	300.00
			3,170.00	1,080.00
	GRAND TOTAL		7,566.00	3,258.90

RECOMMENDED COST OF LUMP SUM REPAIRS		2,600.00
(TO ITS PRE-ACCIDENT CONDITION)		

Report Ref No. CS3/GRB21007566/Eny3e2-1



Automotive Assessor



ANG BRYAN TANI

Automotive Assessor / Investigator