

**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

**VEHICLE DAMAGE INSPECTION REPORT****Our File No:** CS/CTI22008218/RQY3Q2**Date:** 19/09/2022**REFERENCE**

Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd.	Policy No:	DMPCSNW00220332100	
<b>Claimant Vehicle No :</b>	SHA8416G	<b>Insured Vehicle No :</b>	SMJ377G	
Date of Loss:	24/08/2022	Nature of Claim:	TP	Claim No: SNM22D205967/C02/TANCHC

**DESCRIPTION & IDENTIFICATION OF VEHICLE**

Reg No:	<b>SHA8416G</b>		Engine No:	G4LEKU296332
Make & Model:	HYUNDAI AE IONIQ HEV, 1.6 DCT (A)		Chassis No:	KMHC851CVKU164576
Reg. Date:	02/07/2019 (Man. Year: 2019)		Odometer:	250801 km
Colour:	Yellow			
Engine Capacity:	1580 cc			
Market Value/New Car Price:	N/A			
Sum Insured (\$\$):	<b>Market Value/New Car Price</b>			

**CONDITION OF VEHICLE AT THE TIME OF SURVEY**

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

**CONDITION OF TYRES**

Front Tyre Size:	195/65 R15	Rear Tyre Size:	195/65 R15
Front Left Side:	ATREZZO 6 mm	Rear Left Side:	ATREZZO 6 mm
Front Right Side:	ATREZZO 6 mm	Rear Right Side:	ATREZZO 6 mm

*The above values represent the remaining tyre treads depth*

<b>COST OF CLAIMS</b>	<b>Repairer's</b>	<b>Adjuster's</b>	<b>Difference</b>	<b>Diff %</b>
Parts	3,543.20	1,506.64	2,036.56	57.48
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,200.00	530.00	2,670.00	83.44
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Calculated Gross Total (\$\$)</b>	<b>6,743.20</b>	<b>2,036.64</b>	<b>4,706.56</b>	<b>69.80</b>
<b>Approved Total (Overridden) (\$\$)</b>		<b>1,600.00</b>		
<b>(\$\$)</b>	6,743.20	1,600.00	5,143.20	76.27
<b>+ GST 7.00/7.00% (\$\$)</b>	472.02	112.00	360.02	76.27
<b>Nett Amount (\$\$)</b>	<b>7,215.22</b>	<b>1,712.00</b>	<b>5,503.22</b>	<b>76.27</b>

**INSPECTION**

Date of Assignment:	26/08/2022	
Date Inspected:	25/08/2022	Inspected At: 31 CORPORATION ROAD
Estimated Period of Repair:	3.0 days	Repairer: Ding Automotive Pte Ltd (SIN MING)

**Adjuster:** MOHD RASUL**Manager:** SHIAU CHAN

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

REPAIR DETAILS

Reference		
Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 19 Sep 2022)
Parts:	143	HYUNDAI AE IONIQ HEV 1.6 DCT (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SHA8416G)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER COVER	Scratched	430.90 FL	*430.90 FL
2	1		*FRONT LH BUMPER RETAINER	Serviceable	28.00 FL	*- FL
3	1		*FRONT LH BUMPER SIDE SUPPORT BRACKET	Serviceable	12.00 FL	*- FL
4	1		*FRONT BUMPER ENERGY ABSORBER	Serviceable	86.90 FL	*- FL
5	1		*FRONT BUMPER CENTER UPPER MOULDING	Cracked	141.10 FL	*141.10 FL
6	1		*FRONT LH BUMPER FOG LAMP COVER	Serviceable	93.00 FL	*- FL
7	1		*FRONT LH HEADLAMP	Scratched	1,198.80 FL	*1,198.80 FL
8	1		*FRONT END MODULE CARRIER	Serviceable	949.30 FL	*- FL
9	1		*FRONT LH FENDER PANEL	Serviceable	588.80 FL	*- FL
10	1		*FRONT LH FENDER LINER	Serviceable	114.70 FL	*- FL
11	1		*FRONT LH FENDER EMBLEM	Not Necessary	26.60 FL	*- FL
12	1		*FRONT LH WHEEL RIM COVER	Not Necessary	346.40 FL	*- FL
13	1		*SET FRONT BUMPER CLIP	Necessary	55.00 FS	*30.00 FS
14	1		*SET FRONT BUMPER RIVET	Necessary	50.00 FS	*30.00 FS
15	1		*FRONT BUMPER MOULDING CLIP	Necessary	50.00 FS	*30.00 FS
16	1		*SET FRONT FENDER LINER CLIP	Not Necessary	55.00 FS	*- FS
17	1		*RADIATOR COOLANT	Not Necessary	120.00 FS	*- FS
					Sub Total (S\$)	4,346.50 1,860.80
					- List Item Discount on L Items 20.00/20.00% (S\$)	803.30 354.16
					Total Parts (S\$)	3,543.20 1,506.64

F=Franchise part. S=SpcNett. L=ListItemDisc.

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b>Labour Items</b>				
1	TO STRAIGHTEN AND PANEL BEAT OF ACCIDENT AFFECTED AREA	New	1,200.00	200.00
2	TO RUST PROOFING OF THE AFFECTED AREA	New	170.00	0.00
3	TO DIAGNOSTIC CHECK WIRING AND LIGHTING SYSTEM AND CLEAR FAULT CODE	New	240.00	0.00
4	TO READJUST AND REALIGN HEADLAMP AIM	New	100.00	30.00
5	TO CONDUCT TYRE BALANCING AND WHEEL ALIGNMENT	New	120.00	0.00
6	TO VACUUM AND TOPUP A/C GAS FOR A/C CONDENSER	New	150.00	0.00
7	TO REMOVE AND REFIT A/C CONDENSER ,RADIATOR AND OTHER NECESSARY ITEM TO ENABLE BODYWORK REPAIR	New	220.00	0.00
8	TO RESPRAY FRONT BUMPER	New	250.00	200.00
9	TO RESPRAY FRONT BUMPER CENTER UPPER MOULDING	New	250.00	100.00
10	TO RESPRAY FRONT BUMPER FOG LAMP COVER	New	250.00	0.00
11	TO RESPRAY FRONT FENDER PANEL	New	250.00	0.00
<b>Gross Labour Cost (\$\$)</b>			<b>3,200.00</b>	<b>530.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >