

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com;cs-a@lkkauto.com;admin-a@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS/CTI22008223/UVY3M4**Date:** 17/04/2023**REFERENCE**

Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd.	Policy No:	DMPCSNW00117932201		
Claimant Vehicle No :	JVB6190	Insured Vehicle No :	SML5274B		
Date of Loss:	18/08/2022	Nature of Claim:	TP	Claim No:	SNM22D205808/C02/TANCHC

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	JVB6190	Engine No:	G3P8E021862
Make & Model:	YAMAHA Y16ZR, 155cc	Chassis No:	PMYUG1510N0017542
Reg. Date:	02/03/2022 (Man. Year: 2022)	Odometer:	10593 km
Colour:	Multi-colour		
Engine Capacity:	155 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	90-80-17	Rear Tyre Size:	120/70-17
Front Left Side:	Maxxis 6 mm	Rear Left Side:	Metzeler 6 mm
Front Right Side:	0 mm	Rear Right Side:	0 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	5,887.50	2,364.80	3,522.70	59.83
Miscellaneous Items	0.00	0.00	0.00	
Labour	880.00	280.00	600.00	68.18
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	6,767.50	2,644.80	4,122.70	60.92
Approved Total (Overridden) (S\$)		2,100.00		
Nett Amount (S\$)	6,767.50	2,100.00	4,667.50	68.97

INSPECTION

Date of Assignment:	30/08/2022		
Date Inspected:	25/08/2022	Inspected At:	EROFIA MOTOR TRADING PTE LTD 1 KAKI BUKIT AVENUE 6 #02-62 SINGAPORE 417883
Estimated Period of Repair:	4.0 days		

Adjuster: MARCUS CHUA**Manager:** VERON CHEN*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

REPAIR DETAILS

Reference		
Part Source:	(Last Synchronised: 17 Apr 2023)	
Parts:	N/A	YAMAHA Y16ZR 155cc (Model not available in database)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for JVB6190)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	2		*FRONT FORK TUBE ASSY	Not Necessary	640.00 FL	*- FL
2	1		*FORK UNDER BRACKET	Not Necessary	185.00 FL	*- FL
3	1		*FRONT RIM	Not Necessary	385.00 FL	*- FL
4	1		*FRONT RIM BEARING	Not Necessary	90.00 FL	*- FL
5	1		*FRONT RIM SHAFT	Not Necessary	75.00 FL	*- FL
6	1		*FRONT BRAKE DISC	Not Necessary	155.00 FL	*- FL
7	1		*BRAKE MASTER PUMP	Cut	485.00 FL	*305.00 FL
8	1		*BRAKE MASTER PUMP BRACKET	Cracked	95.00 FL	*95.00 FL
9	1		*HANDLE-BAR	Bent	128.00 FL	*128.00 FL
10	1		*HANDLE-BAR END	Damaged	136.00 FL	*38.00 FL
11	1		*SET HAND GRIP	Cut	68.00 FL	*40.00 FL
12	1		*THROTTLE CABLE	Damaged	155.00 FL	*155.00 FL
13	1		*STARTER SWTICH	Cracked	195.00 FL	*195.00 FL
14	1		*HEADLAMP COVER - MATT (FRONT)	Cut	115.00 FL	*115.00 FL
15	1		*HEADLAMP COVER - MATT (BACK)	Cut	135.00 FL	*135.00 FL
16	1		*FRONT INNER COVER (KEY SIDE)	Cut	120.00 FL	*80.00 FL
17	1		*FRONT COVER - MATT	Cut	185.00 FL	*150.00 FL
18	1		*BASKET	Cut	125.00 FL	*125.00 FL
19	1		*SIDE MIRROR	Broken	128.00 FL	*128.00 FL
20	1		*SET FAIRING ASSY	Cut	580.00 FL	*480.00 FL
21	1		*FRONT FOOTREST BRACKET	Repair	186.00 FL	*- FL
22	1		*FRONT FOOTREST O/S	Bent	128.00 FL	*58.00 FL
23	1		*BRAKE PEDAL	Repair	58.00 FL	*- FL
24	2		*REAR FOOTREST	Not Necessary	80.00 FL	*- FL
25	1		*REAR FOOTREST BRACKET	Not Necessary	178.00 FL	*- FL
26	1		*EXHAUST ASSY	Repair	485.00 FL	*- FL
27	1		*EXHAUST PROTECTOR	Cut	115.00 FL	*90.00 FL
28	1		*EXHAUST PIPE AND COVER	Cut	55.00 FL	*55.00 FL
29	1		*SET NUMBER PLATE	Front Necessary	38.00 FS	*10.00 FS
30	2		*FORK OILS	Not Necessary	30.00 FS	*- FS
31	2		*FORK OIL SEALS	Not Necessary	56.00 FS	*- FS
32	1		*SET STEERING CONE	Not Necessary	90.00 FS	*- FS
33	1		*SET STICKER	Not Necessary	95.00 FS	*- FS
34	1		*REAR BOX	Cut	480.00 FS	*220.00 FS
35	1		*REAR BOX BRACKET	Not Necessary	180.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (S\$)	6,434.00	2,602.00
- List Item Discount on L Items 10.00/10.00% (S\$)	546.50	237.20
Total Parts (S\$)	5,887.50	2,364.80

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO PROVIDE TOWING SERVICE (LOD) S\$50.00 (NPA)	New	0.00	0.00
2	TO CHECK WIRING AND RESET HEADLAMP FOCUSING	New	80.00	0.00
3	TO PROVIDE LABOUR	New	420.00	280.00
4	TO REPAIR BODY FRAME	New	380.00	0.00
Gross Labour Cost (\$\$)			880.00	280.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >