

## **LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

PRE-REPAIR INSPECTION REPORT					
	SOMPO INSURAN	F	Ref:	CS3/SMO22008224/Uqy3m4	
	50 RAFFLES PLAC SINGAPORE LAND	E #03-03 O TOWERSINGAPORE 048623	[	Date:	06/09/2022
			(	Code:	SMO
1.	Policy Particulars :- (THIRD PARTY CLAIM)				
	Insured Veh.	YN 7250D	Veh. Inspected		FBR 3257M
	Policy No.	D22MTPCVE000221	Coverage (\$)		0.00
	Claim No.	CMTD2202935/THE	Excess (\$)		0.00
	Assign From	GRACE TEO	Assign Date		25/08/2022
2. Vehicle Particulars & Condition					
	Make & Model	YAMAHA XMAX300	c.c		292
	Engine No.	HIDDEN	Year of Reg.		2020
	Chassis No.	MH3SH0847LK009684	Colour		BLUE
	Odometer	27243 KM	Steering		IN ORDER
	Brakes	IN ORDER	Modification		SPORTS RIM
	General	GOOD			
3. Conditions of Tyres					
		Size	Make		Balance
	R/H Front Tyre	120/70-15	BRIDGESTONE		6 mm
	L/H Front Tyre				mm
	R/H Rear Tyre	140/70-14	BRIDGESTONE		6 mm
	L/H Rear Tyre				mm
4.	Description of Damages				
	THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION & N/S BODY.				
5.	General Information				
	Accident Date	23/08/2022	Inspect Date / T	ime	26/08/2022 ( 10:40 AM )
	Survey held at	GP MOTORING PTE LTD			
		282 MACPHERSON ROAD SINGAPORE 348607			
5a.	Remarks				
	A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION. THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE. C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS. D) THE ESTIMATED REPAIR COST OF THE DAMAGED VEHICLE IS IN THE REGION OF \$3,000-\$4,000				
5b.	Estimate Days of Repair				
	ESTIMATED NORM	MAL PERIOD FOR REPAIR:	4	4 Worki	ng Days

Report Ref No. CS3/SMO22008224/Uqy3m4

Inspected By

CHUA KANG SENG

K.K.LAU CPT(RET)

**Licensed Appraiser** 

 $BEng(Hons), B. Bus, MBA, PEng, PE, \, MInstAEA, MASME, MIRTE$ 

REGD Auto Consultant-SAE, Licensed Appraiser