

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS/ICS22008227/GVY3M4**Date:** 06/02/2023REFERENCE

Handling Insurer: ECICS Limited Policy No:

Claimant Vehicle No : SLR4179E **Insured Vehicle No :** SKD9893D

Date of Loss: 17/08/2022 Nature of Claim: TP Claim No: DMPC2200371H/ST

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SLR4179E**

Make & Model: TOYOTA PRIUS HYBRID, 1.8 S (A) Engine No: 2ZR8034568

Reg. Date: 15/08/2017 (Man. Year: 2017) Chassis No: ZVW508054595

Colour: Silver Odometer: 165634 km

Engine Capacity: 1797 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 195/65 R15 Rear Tyre Size: 195/65 R15

Front Left Side: Arivo 6 mm Rear Left Side: Arivo 6 mm

Front Right Side: Arivo 6 mm Rear Right Side: Arivo 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	19,339.22	2,897.55	16,441.67	85.02
Miscellaneous Items	0.00	0.00	0.00	
Labour	6,250.00	1,870.00	4,380.00	70.08
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	25,589.22	4,767.55	20,821.67	81.37
Approved Total (Overridden) (S\$)		3,800.00		
(S\$)	25,589.22	3,800.00	21,789.22	85.15
+ GST 8.00/8.00% (S\$)	2,047.14	304.00	1,743.14	85.15
Nett Amount (S\$)	27,636.36	4,104.00	23,532.36	85.15

INSPECTION

Date of Assignment: 25/08/2022

Date Inspected: 26/08/2022 Inspected At: BIFROST AUTO PTE LTD
8 KAKI BUKIT AVENUE 4
#01-49 PREMIER @ KAKI BUKIT
SINGAPORE 415875

Estimated Period of Repair: 5.0 days

Adjuster: XING GUO QIANG**Manager:** VERON CHEN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 02 Feb 2023)
Parts:	144	TOYOTA PRIUS HYBRID 1.8 S (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SLR4179E)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR TAILGATE	Bent	1,126.60 FL	*1,126.60 FL
2	1		*REAR TAILGATE LOCK	Not Necessary	457.90 FL	*- FL
3	1		*REAR TAILGATE COVER TRIM BOARD	Not Necessary	254.40 FL	*- FL
4	1		*REAR TAILGATE TRIM BOARD, CENTRE	Not Necessary	159.60 FL	*- FL
5	1		*REAR TAILGATE TRIM BOARD, SIDE RH	Not Necessary	92.50 FL	*- FL
6	1		*REAR TAILGATE TRIM BOARD, SIDE LH	Not Necessary	92.50 FL	*- FL
7	1		*REAR TAILGATE TRIM BOARD REAR	Not Necessary	360.80 FL	*- FL
8	1		*REAR TAILGATE WEATHERSTRIP	Torn	365.20 FL	*365.20 FL
9	1		*REAR TAILGATE OUTER GARNISH	Not Necessary	896.30 FL	*- FL
10	1		*REAR TAILGATE EMBLEM	Not Necessary	52.90 FL	*- FL
11	1		*REAR TAILGATE PRIUS EMBLEM	Not Necessary	60.80 FL	*- FL
12	1		*REAR TAILGATE HYBRID SYNERGY DRIVE EMBLEM	Not Necessary	52.40 FL	*- FL
13	1		*REAR TAILGATE LOCK STRIKER	Not Necessary	98.70 FL	*- FL
14	1		*REAR WINDSCREEN GLASS C/W MOULDING	Not Necessary	1,778.30 FL	*- FL
15	1		*REAR WINDSCREEN GLASS C/W MOULDING LOWER	Not Necessary	1,569.70 FL	*- FL
16	1		*REAR TAILGATE SPOILER	Not Necessary	953.70 FL	*- FL
17	1		*REAR BUMPER	Deformed	499.90 FL	*499.90 FL
18	1		*REAR BUMPER LOWER COVER	Deformed	552.60 FL	*379.00 FL
19	1		*REAR BUMPER UNDER SIDE COVER RH	Not Necessary	232.00 FL	*- FL
20	1		*REAR BUMPER UNDER SIDE COVER LH	Not Necessary	232.00 FL	*- FL
21	1		*REAR BUMPER UNDER SIDE COVER CENTRE	Not Necessary	552.60 FL	*- FL
22	1		*REAR BUMPER TOWING COVER	Cut	82.70 FL	*61.00 FL
23	1		*REAR BUMPER SIDE RETAINER RH	Not Necessary	94.80 FL	*- FL
24	1		*REAR BUMPER SIDE RETAINER LH	Not Necessary	94.80 FL	*- FL
25	1		*REAR BUMPER ARM RH	Not Necessary	139.60 FL	*- FL
26	1		*REAR BUMPER ARM LH	Not Necessary	139.60 FL	*- FL
27	1		*REAR BUMPER REINFORCEMENT	Bent	318.80 FL	*318.80 FL
28	1		*REAR BUMPER SIDE SEAL RH	Not Necessary	148.40 FL	*- FL
29	1		*REAR BUMPER SIDE SEAL LH	Not Necessary	148.40 FL	*- FL
30	1		*REAR WIRING ASSEMBLY	Not Necessary	582.40 FL	*- FL
31	1		*REAR TAILLAMP ASSEMBLY UPPER RH	Not Necessary	557.90 FL	*- FL
32	1		*REAR TAILLAMP ASSEMBLY UPPER LH	Not Necessary	557.90 FL	*- FL
33	1		*REAR TAILLAMP ASSEMBLY LOWER RH	Not Necessary	548.40 FL	*- FL
34	1		*REAR TAILLAMP ASSEMBLY LOWER LH	Not Necessary	548.40 FL	*- FL
35	1		*REAR TAILLAMP QUARTER PANEL RH	Not Necessary	216.00 FL	*- FL
36	1		*REAR TAILLAMP QUARTER PANEL LH	Not Necessary	216.00 FL	*- FL
37	1		*REAR END PANEL	Buckled	602.10 FL	*602.10 FL
38	1		*REAR END PANEL TOP GARNISH	Broken	165.80 FL	*165.80 FL
39	1		*REAR SPARE TYRE PANEL	Not Necessary	667.70 FL	*- FL
40	1		*REAR SPARE TYRE PANEL TOP BOARD	Not Necessary	101.40 FL	*- FL
41	1		*REAR SPONGE TOOL BOX CENTRE	Not Necessary	186.20 FL	*- FL
42	1		*REAR SPONGE TOOL BOX TRIM RH	Not Necessary	398.00 FL	*- FL
43	1		*REAR SPONGE TOOL BOX TRIM LH	Not Necessary	398.00 FL	*- FL
44	1		*REAR SPARE TYRE PANEL SIDE RH	Not Necessary	287.30 FL	*- FL
45	1		*REAR SPARE TYRE PANEL SIDE LH	Not Necessary	287.30 FL	*- FL
46	1		*REAR FENDER RH	Not Necessary	836.70 FL	*- FL

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
47	1		*REAR FENDER LH	Not Necessary	836.70 FL	*- FL
48	1		*REAR FENDER INNER TRIM RH	Not Necessary	387.70 FL	*- FL
49	1		*REAR FENDER INNER TRIM LH	Not Necessary	387.70 FL	*- FL
50	1		*REAR FENDER INNER COWLING RH	Not Necessary	174.20 FL	*- FL
51	1		*REAR FENDER INNER COWLING LH	Not Necessary	174.20 FL	*- FL
52	1		*SMART TRANSMITTER KEY	Broken	447.10 FL	*165.00 FL
53	1		*REAR EXHAUST PIPE	Not Necessary	1,163.40 FL	*- FL
54	1		*REAR EXHAUST MOUNTING	Not Necessary	40.70 FL	*- FL
55	1		*REAR EXHAUST INSULATOR	Not Necessary	314.60 FL	*- FL
56	1		*REAR NUMBER PLATE	Not Necessary	50.00 FS	*- FS
57	1		*SET REAR BUMPER CLIPS	Necessary	50.00 FS	*30.00 FS
58	1		*SET REAR TAILLAMP CLIPS	Not Necessary	50.00 FS	*- FS
59	1		*SET REAR FENDER INNER TRIM CLIPS	Not Necessary	50.00 FS	*- FS
60	1		*SET REAR END PANEL TOP GARNISH CLIPS	Necessary	50.00 FS	*15.00 FS
61	1		*SET REAR FENDER INNER COWLING CLIPS	Not Necessary	40.00 FS	*- FS
62	1		*SET REAR TAILGATE INNER TRIM BOARD CLIPS	Not Necessary	60.00 FS	*- FS
63	1		*REAR TAILGATE SEALANT	Not Necessary	150.00 FS	*- FS
64	1		*REAR TAILLAMP QUARTER PANEL SEALANT	Not Necessary	120.00 FS	*- FS
65	1		*REAR END PANEL SEALANT	Necessary	150.00 FS	*30.00 FS
66	1		*REAR SPARE TYRE PANEL SEALANT	Not Necessary	150.00 FS	*- FS
67	1		*REAR FENDER RH SEALANT	Not Necessary	150.00 FS	*- FS
68	1		*REAR FENDER LH SEALANT	Not Necessary	150.00 FS	*- FS
69	1		*REAR WINDSCREEN GLASS UPPER SEALANT	Necessary	150.00 FS	*40.00 FS
70	1		*REAR TAILGATE GLASS LOWER SEALANT	Necessary	150.00 FS	*20.00 FS
71	1		*SET REAR BUMPER REVERSE SENSOR	Not Necessary	250.00 FS	*- FS
72	1		*SET REAR TAILGATE REVERSE CAMERA	Not Necessary	550.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	25,012.30	3,818.40
- List Item Discount on L Items 25.00/25.00% (\$\$)	5,673.08	920.85
Total Parts (\$\$)	19,339.22	2,897.55

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO PANEL BEAT, REMOVE & REFIX PARTS	New	2,400.00	800.00
2	TO SPRAY PAINT AFFECTED AREAS	New	1,800.00	600.00
3	WIRING & BULB CHECK	New	100.00	30.00
4	TO REMOVE & REFIX REAR WINDSCREEN GLASS UPPER	New	150.00	120.00
5	TO REMOVE & REFIX REAR WINDSCREEN GLASS LOWER	New	150.00	60.00
6	TO TRANSFER REAR TAILGATE MECHANISM	New	150.00	60.00
7	TO REMOVE & REFIX REAR TAILGATE REVERSE CAMERA	New	150.00	40.00
8	TO REMOVE & REFIX REAR BUMPER REVERSE SENSOR	New	120.00	40.00
9	TO REMOVE & REFIX REAR EXHAUST PIPE TO FACILITATE REPAIRS	New	150.00	0.00
10	TO APPLY ANTI RUST ON AFFECTED PARTS	New	150.00	60.00
11	TO REMOVE & REFIX INTERIOR UPHOLSTRY TO FACILITATE REPAIRS	New	150.00	60.00
12	TO REMOVE & REFIX FUEL TANK TO FACILITATE REPAIRS	New	200.00	0.00
13	TO CONDUCT WATER LEAK TEST	New	100.00	0.00
14	TO SEND FOR DIAGNOSTIC AND RESET CONTROL UNIT. PROGRAMMING & CALIBRATION	New	480.00	0.00
Gross Labour Cost (S\$)			6,250.00	1,870.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >