

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com; cs-a@lkkauto.com; admin-a@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CC3/AIG22008230/APA3Q2
Date: 07/03/2023**REFERENCE**

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	
Claimant Vehicle No :	SMT1233D	Insured Vehicle No :	SNF3211R
Date of Loss:	22/08/2022	Nature of Claim:	TP
		Claim No:	8119220851SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SMT1233D		
Make & Model:	AUDI A3, 999cc SEDAN TFSI S TRONIC (LED) (A)	Engine No:	CHZC35697
Reg. Date:	27/03/2020 (Man. Year: 2019)	Chassis No:	WAUZZZ8V8LA006450
Colour:	Black	Odometer:	34120 km
Engine Capacity:	999 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	205/55 R16	Rear Tyre Size:	205/55 R16
Front Left Side:	Bridgestone 6 mm	Rear Left Side:	Bridgestone 6 mm
Front Right Side:	Bridgestone 6 mm	Rear Right Side:	Bridgestone 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	4,372.00	1,853.60	2,518.40	57.60
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,352.00	1,602.00	750.00	31.89
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	6,724.00	3,455.60	3,268.40	48.61
+ GST 8.00/8.00% (S\$)	537.92	276.45	261.47	48.61
Nett Amount (S\$)	7,261.92	3,732.05	3,529.87	48.61
+ Loss of Use (3.0 x S\$50.00/day) (S\$)		150.00		
+ Doc/Search Fee (S\$)		7.45		
Nett Liability (S\$)		3,889.50		

INSPECTION

Date of Assignment:	30/08/2022		
Date Inspected:	30/08/2022	Inspected At:	Premium Automobiles Pte Ltd (HQ) 55 UBI ROAD 1 Singapore 408699
Estimated Period of Repair:	3.0 days		

Adjuster: ADRIAN LING**Manager:** CHEW HSIAO TONG*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER	Deformed	2,317.00 FS	*1,853.60 FS
2	2		*REAR BUMPER GUIDE SECTION -LH /RH	Not Necessary	36.00 FS	*- FS
3	1		*REAR BUMPER SPOILER	Not Necessary	264.00 FS	*- FS
4	2		*REAR BUMPER LOCKING MECHANISM	Not Necessary	67.00 FS	*- FS
5	2		*REAR BUMPER REFLECTOR -LH /RH	Not Necessary	92.00 FS	*- FS
6	1		*REAR BUMPER REINFORCEMENT BEAM	Not Necessary	642.00 FS	*- FS
7	2		*REAR BUMPER BRACKET -LH/RH	Not Necessary	63.00 FS	*- FS
8	2		*REAR PARKING AID SENSOR -INNER /OUTER	Not Necessary	531.00 FS	*- FS
9	4		*REAR PARKING AID SEAL RING	Not Necessary	10.00 FS	*- FS
10	1		*SUNDRIES	Not Necessary	350.00 FS	*- FS

F=Franchise part. S=SpcNett.

Total Parts (S\$) 4,372.00 1,853.60

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO REMOVE AND TRANSFER REAR PARKING AID	New	360.00	360.00
2	TO DISMANTLE AND RENEW REAR BUMPER RE-ORGANIZE CRASH MANAGEMENT COMPONENTS REINSTALL ALL PARTS REMOVED	New	900.00	500.00
3	TO RESPRAY REAR BUMPER	New	900.00	550.00
4	TO CARRY OUT DIAGNOSTIC CHECK	New	192.00	192.00
			Gross Labour Cost (\$\$)	2,352.00
				1,602.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >