

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com; cs-a@lkkauto.com; admin-a@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS/EG122008231/ACY3Q2**Date:** 16/05/2023**REFERENCE**

Handling Insurer: ERGO Insurance Pte. Ltd.

Policy No:

Claimant Vehicle No : GBC2323R**Insured Vehicle No :** GBJ7073S

Date of Loss: 24/08/2022

Nature of Claim:

TP

Claim No: CDMCG22001748

DESCRIPTION & IDENTIFICATION OF VEHICLEReg No: **GBC2323R**

Make & Model: TOYOTA DYNA 150 MANUAL 3SEATER, 3.0 D (M)

Engine No: 1KD1957699

Reg. Date: 02/11/2009 (Man. Year: 2009)

Chassis No: JTFAT35Y20K200952

Colour: Blue

Odometer: 427545 km

Engine Capacity: 2982 cc

Market Value/New Car Price:

N/A

Sum Insured (S\$): **Market Value/New Car Price****CONDITION OF VEHICLE AT THE TIME OF SURVEY**

General Condition: Steering (Serviceable):

Yes

Footbrake (Serviceable):

Yes

Handbrake (Serviceable): Yes Engine Modification:

No

Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 195 R15C

Rear Tyre Size: 155 R12C

Front Left Side: GREEN-MAX 6 mm

Rear Left Side: GREEN-MAX 6 mm

Front Right Side: GREEN-MAX 6 mm

Rear Right Side: GREEN-MAX 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	7,064.33	2,873.40	4,190.93	59.33
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,260.00	1,200.00	1,060.00	46.90
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	9,324.33	4,073.40	5,250.93	56.31
Approved Total (Overridden) (S\$)		3,200.00		
(S\$)	9,324.33	3,200.00	6,124.33	65.68
+ GST 8.00/8.00% (S\$)	745.95	256.00	489.95	65.68
Nett Amount (S\$)	10,070.28	3,456.00	6,614.28	65.68

INSPECTION

Date of Assignment: 25/08/2022

Date Inspected: 25/08/2022 Inspected At:

Ryder Auto Pte Ltd (HQ)

2 Kaki Bukit Ave 2, #02-19 AutoHub @ Kaki Bukit
Singapore 417921

Estimated Period of Repair: 5.0 days

Adjuster: ADRIAN LING**Manager:** CELINE FONG*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

REPAIR DETAILS

Reference		
Part Source:	(Last Synchronised: 16 May 2023)	
Parts:	N/A	TOYOTA DYNA 150 MANUAL 3SEATER 3.0 D (M) (Model not available in database)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for GBC2323R)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR TAIL GATE	Dented	1,584.57 FL	*1,137.00 FL
2	1		*REAR TAIL GATE 70KM/H STICKER	Necessary	20.00 FS	*15.00 FS
3	1		*REAR TAIL GATE 13 PAX STICKER	Necessary	20.00 FS	*15.00 FS
4	2		*REAR TAIL GATE O/S & N/S LOCK	Not Necessary	80.00 FL	*- FL
5	1		*REAR TAIL GATE O/S & N/S LOCK HANDLE	Not Necessary	97.80 FL	*- FL
6	4		*REAR TAIL GATE HINGES	Bent	60.00 FL	*60.00 FL
7	4		*REAR TAIL GATE HINGES PINS	Not Necessary	20.00 FL	*- FL
8	1		*REAR TAIL GATE LOWER PANEL	Dented	455.20 FL	*455.20 FL
9	2		*REAR TAIL GATE O/S & N/S RUBBER STOPPER	Not Necessary	40.00 FL	*- FL
10	2		*REAR TAIL GATE O/S & N/S RUBBER STOPPER BRACKET	Not Necessary	90.00 FL	*- FL
11	1		*REAR TAIL GATE STEP	Bent	500.00 FS	*250.00 FS
12	2		*REAR O/S & N/S RAILING (NPA)	Not Necessary	0.00 FL	*- FL
13	2		*REAR O/S & N/S TAIL LAMP	Cracked	540.00 FL	*540.00 FL
14	2		*REAR O/S & N/S TAIL LAMP PANEL	Bent	220.00 FL	*220.00 FL
15	1		*REAR END PANEL	Repeated	510.40 FL	*- FL
16	1		*REAR ALUMNIUM COVER	Not Necessary	400.00 FS	*- FS
17	1		*REAR FLOOR ALUMINIUM	Not Necessary	800.00 FS	*- FS
18	10		*RIVETS	Necessary	10.00 FS	*10.00 FS
19	1		*EXHAUST	Bent	765.00 FL	*530.00 FL
20	4		*REAR EXHAUST PIPE MOUNTING	Damaged	24.00 FL	*24.00 FL
21	1		*REAR REG NO.PLATE BRACKET	Bent	120.00 FS	*120.00 FS
22	1		*REAR REGN NO.PLATE GARNISH	Deformed	20.00 FS	*20.00 FS
23	1		*REAR REGN NO.PLATE	Missing	35.00 FS	*35.00 FS
24	1		*REAR SPARE WHEEL BRACKET	Damaged	798.80 FL	*245.00 FL
25	1		*REAR SPARE TYRE RIM(BIG)	Not Necessary	600.00 FL	*- FL
26	1		*REAR SPARE TYRE (BIG)	Not Necessary	200.00 FS	*- FS
27	1		*REAR SPARE TYRE RIM (SMALL)	Not Necessary	500.00 FL	*- FL
28	1		*REAR SPARE TYRE (SMALL)	Not Necessary	150.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	8,660.77	3,676.20
- List Item Discount on L Items 25.00/25.00% (\$\$)	1,596.44	802.80
Total Parts (\$\$)	7,064.33	2,873.40

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO DISMANTLE REAR PORTION ,STRAIGHTEN ,CUTTING & WELDING	New	1,200.00	600.00
2	TO SPRAY PAINTING	New	600.00	400.00
3	TO REMOVE AND REPLACE REAR CANOPY	New	80.00	0.00
4	TO REMOVE & REPLACE REAR TAIL GATE ALUMINIUM COVER	New	100.00	40.00
5	TO REMOVE & REFIT EXHAUST	New	120.00	80.00
6	TO CHECK WIRING	New	80.00	30.00
7	TO RE SEAL ANTI RUST	New	80.00	50.00
Gross Labour Cost (\$\$)			2,260.00	1,200.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >