



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SDH 3338S

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
<u>REPLACEMENT OF PARTS</u>				
1	FRONT FENDER RH	TO REPAIR SEE LABOUR	990.00	-
1	FRONT DOOR RH	DENTED	1,809.00	1,809.00
3	FRONT DOOR INNER SPONGE RH@\$65/-	GRAZED	195.00	195.00
1	FRONT DOOR WING MIRROR RH	CRACKED	1,148.00	1,148.00
1	FRONT DOOR WING MIRROR SIGNAL RH	GRAZED	169.00	169.00
1	FRONT DOOR WING MIRROR W/SIGNAL OUTER COVER RH	CRACKED	226.00	226.00
1	FRONT DOOR OUTER HANDLE RH	SERVICEABLE	579.00	-
1	FRONT DOOR OUTER HANDLE END RH	SERVICEABLE	86.00	-
1	FRONT DOOR REGULATOR GEAR & MOTOR ASSY RH	FAULTY	618.00	618.00
1	FRONT DOOR INNER TRIM BOARD	SERVICEABLE	1,800.00	-
1	FRONT DOOR WEATHERSTRIP RH	NECESSARY	207.00	207.00
1	FRONT DOOR TOP HINGE RH	TO REPAIR SEE LABOUR	135.00	-
1	FRONT DOOR BOTTOM HINGE RH	TO REPAIR SEE LABOUR	151.00	-
1	ROCKER PANEL CHROME MOULDING RH	GRAZED	125.00	125.00
	LESS 10% DISCOUNT		-	-449.70
			8,238.00	4,047.30
<u>SPECIAL NETT ITEMS</u>				
1	SET FRONT DOOR INNER TRIM BOARD CLIP (SN)	NECESSARY	40.00	40.00
			40.00	40.00
<u>LABOUR</u>				
	LABOUR CHARGE TO REMOVE-REFIT, PANEL BEAT, STRAIGHTEN, RE-ALIGN AND REPAIR OF FRONT RH FENDER, FRONT RH DOOR, FRONT RH DOOR WING MIRROR AND OTHERS RELEVANT ACCIEDNT DAMAGES. INCLUSIVE OF THE REPAIR OF FRONT FENDER RH, FRONT DOOR TOP HINGE RH AND FRONT DOOR BOTTOM HINGE RH.		1,000.00	300.00
	TO CHECK WIRINGS AND LIGHTINGS.		50.00	30.00
	TO SUPPLIED AND APPLIED ANTI RUST TREATMENT TO AFFECTED PANELS.		120.00	30.00

Report Ref No. CS3/LPC22005489/Kvy3m4-1



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	TO TRANSFER RH DOOR FITTINGS AND ATTACHMENTS.		80.00	60.00
	TO PUTTY AND SPRAY PAINTING CHARGES.		900.00	380.00
			2,150.00	800.00
GRAND TOTAL			10,428.00	4,887.30
RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)				3,900.00

Report Ref No. CS3/LPC22005489/Kvy3m4-1

KONG SENG CHEONG

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.