

ASS. REC BY: T. J. M.

REF:

CC4/USM2200824/Tp93

ASSIGNMENT

From: _____ Date: _____

Estimated cost: _____

OD / TP / IS / TP RES / OD RES / EVA / INV / MV

To Inspect/Vehicle No: _____

at Workshop m/s _____

of _____

Insured: _____

Policy No. _____

Claims No. _____

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

☒	☐
N/S	O/S
☐	☐

Bal. or Market Value: \$84K

IDAC Accident Report: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: _____ days Res.: Yes or No

Lum Sum: _____ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: Raymond Vehicle: IN / OUT

Veh No: SW 6135E Yr Regn: 2018, July

Type: M/Car / M/Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Honda HRV C.C. 1496

Colour: Silver A/C: Insured / Std / NI / NA

Sp. Reading: 109907 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: SHMR418106X204208

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size: F: 215/60R16

R: _____

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front _____ Rear _____

R/Bal. 6 mm R/Bal. 6 mm

L/Bal. 6 mm L/Bal. 6 mm

D.O.A. _____ D.O.I. 20/8/22

Survey held at SC Auto

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

Frt n/s

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time _____ Action / Instruction _____

Date/Time, File Pass to?

☐ : Preli. Report

1) _____

☐ : Final Report

Date/Time, File Return to?

2) _____

Report Format: _____

Lump Sum / L.B.K. () _____

Days Of Repair: _____

Resurvey No. of Trip: _____

Add Fee: ☐ : Site Insp (\$ _____)

☐ : Interview (\$ _____)

☐ : Tech. rvs (\$ _____)

☐ : Weekend (\$ _____)

Survey Fee:

Transportation:

____ S + RS. ____ SI.

Photos

Others

TOTAL



SC AUTO INDUSTRIES (S) PTE LTD

51 Senoko Road, Singapore 758133

T 65 6758 2222 F 65 6257 6931

E sales@scauto.com.sg

scauto.com.sg

Co. Reg. No. 199800107D

M/S AXA INSURANCE PTE LTD
9 NORTH BUONA VISTA DRIVE,
#18-01/06, TOWER 1 THE METROPOLIS
Insured NURUL ATIQA BINTE SABTU
Policy SI22V09087/VPC/R01

ESTIMATE BILL

GST Reg. No: 199800107D

Date: 25/8/2022

Our Case Ref.

Accident Date 22/8/2022

Damaged Vehicle No: SMW6135E

S/no	Description	QTY	Price	Amount	Remark
Replaced Parts					
1	FRONT BUMPER	1 PC	\$ 895.50	\$ 895.50	de -
2	FRONT HEADLIGH LH	1 PC	\$ 995.50	\$ 995.50	eng -
3	FRONT BUMPER SIDE RETAINER LH	1 PC	\$ 98.00	\$ 98.00	de?
4	BONNET	1 PC	\$ 1,565.30	\$ 1,565.30	x
5	FRONT GRILLE BASE	1 PC	\$ 1,250.00	\$ 1,250.00	?
6	FRONT GRILLE OUTER MOULDING	1 PC	\$ 850.00	\$ 850.00	?
7	FRONT GRILLE LOWER CHROME	1 PC	\$ 425.00	\$ 425.00	x
8	SUNDRIES		\$ 200.00	\$ 200.00	* 20
LABOUR CHARGES					
1	LABOUR TO REMOVE AND CHECK FRONT BUMPER WIRE HARNESS.		\$ 500.00	\$ 500.00	80.
2	LABOUR TO REMOVE AND REINSTALL FRT BUMPER, BONNET, FRT FENDER LH AND FRT HEADLIGHT LH.		\$ 2,500.00	\$ 2,500.00	400.
3	LABOUR TO RESPRAY FRT BUMPER, BONNET, FRT FENDER LH		\$ 2,500.00	\$ 2,500.00	600
4	LABOUR TO CARRY OUT DIAGNOSTIC CHECK		\$ 250.00	\$ 250.00	80

TOTAL \$12,029.30

Tanji 97495749
WP 26/8/22 @ 2200
P/P Rising before paint
3-4 days
Tanji @ Iskandar

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: