

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CC4/AIS22008245/UPA3Q2**Date:** 16/01/2023REFERENCE

Handling Insurer:	Allianz Insurance Singapore Pte. Ltd.	Policy No:	SP2000562906
Claimant Vehicle No :	SJB6793B	Insured Vehicle No :	SMR2338P
Date of Loss:	19/08/2022	Nature of Claim:	TP
		Claim No:	202222006292

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SJB6793B		
Make & Model:	MITSUBISHI LANCER, 2.0 MIVEC L GT (M)	Engine No:	4B11BB7345
Reg. Date:	21/01/2008 (Man. Year: 2007)	Chassis No:	JMYSNCY4A8U000742
Colour:	Black	Odometer:	230047 km
Engine Capacity:	1998 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	225/40 R18	Rear Tyre Size:	225/40 R18
Front Left Side:	Goodyear 6 mm	Rear Left Side:	Goodyear 6 mm
Front Right Side:	Goodyear 6 mm	Rear Right Side:	Goodyear 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	1,763.80	950.20	813.60	46.13
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,175.00	1,070.00	1,105.00	50.80
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	3,938.80	2,020.20	1,918.60	48.71
Approved Total (Overridden) (S\$)		1,600.00		
(S\$)	3,938.80	1,600.00	2,338.80	59.38
+ GST 7.00/7.00% (S\$)	275.72	112.00	163.72	59.38
Nett Amount (S\$)	4,214.52	1,712.00	2,502.52	59.38
+ Loss of Use (3.0 x S\$60.00/day) (S\$)		180.00		
Nett Liability (S\$)		1,892.00		

INSPECTION

Date of Assignment:	25/08/2022		
Date Inspected:	31/08/2022	Inspected At:	Jin Auto Services Pte Ltd (Defu) Blk 14 Defu Lane 10, #01-410/412 Singapore 539195
Estimated Period of Repair:	4.0 days		

Adjuster: MARCUS CHUA**Manager:** CHEW HSIAO TONG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 16 Jan 2023)
Parts:	143	mitsubishi LANCER 2.0 MIVEC L GT (M) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SJB6793B)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER	Distorted	815.00 FL	*815.00 FL
2	10		*REAR BUMPER CLIPS	Necessary	50.00 FL	*50.00 FL
3	1		*REAR BUMPER TOW COVER	Torn	29.00 FL	*29.00 FL
4	1		*REAR BUMPER RED REFLECTOR -RH	Not Necessary	28.00 FL	*- FL
5	1		*REAR BUMPER RED REFLECTOR -LH	Not Necessary	28.00 FL	*- FL
6	1		*END PANEL	Repair	506.00 FL	*- FL
7	1		*END PANEL TOP GARNISH	Not Necessary	169.00 FL	*- FL
8	1		*REAR BOOTLID (NPA)	Repair	0.00 FL	*- FL
9	1		*REAR BOOTLID WEATHERSTRIP (RUBBER)	Not Necessary	186.00 FL	*- FL
10	1		*SPARETYRE PANEL (NPA)	Not Necessary	0.00 FL	*- FL
11	1		*SET REVERSE SENSOR	Shorted	280.00 FS	*200.00 FS
12	1		*REAR NUMBER PLATE	Bent	35.00 FS	*35.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	2,126.00	1,129.00
- List Item Discount on L Items 20.00/20.00% (\$\$)	362.20	178.80
Total Parts (\$\$)	1,763.80	950.20

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	SPRAY PAINTING	New	1,200.00	600.00
2	LABOUR CHARGE	New	780.00	400.00
3	LABOUR FOR REVERSE SENSOR	New	80.00	50.00
4	TUFF COAT	New	80.00	0.00
5	WIRING	New	35.00	20.00
Gross Labour Cost (S\$)			2,175.00	1,070.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >