

**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

**VEHICLE DAMAGE INSPECTION REPORT****Our File No:** CC4/AIS22008246/RPA3Q2**Date:** 16/01/2023**REFERENCE**

Handling Insurer:	Allianz Insurance Singapore Pte. Ltd.	Policy No:	SP2002210955
<b>Claimant Vehicle No :</b>	SLV8538E	<b>Insured Vehicle No :</b>	SLE9183C
Date of Loss:	24/08/2022	Nature of Claim:	TP
		Claim No:	202222006328

**DESCRIPTION & IDENTIFICATION OF VEHICLE**

Reg No:	<b>SLV8538E</b>		
Make & Model:	NISSAN ALMERA, 1.5 5MT AIRBAG 2WD 4DR (A)	Engine No:	HR15929391D
Reg. Date:	30/05/2016 (Man. Year: 2016)	Chassis No:	MNTBBAN17Z0005590
Colour:	Grey	Odometer:	266100 km
Engine Capacity:	1498 cc		
Market Value/New Car Price:	N/A		
Sum Insured (\$\$):	<b>Market Value/New Car Price</b>		

**CONDITION OF VEHICLE AT THE TIME OF SURVEY**

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

**CONDITION OF TYRES**

Front Tyre Size:	195/65 R15	Rear Tyre Size:	195/65 R15
Front Left Side:	Yokohama 6 mm	Rear Left Side:	Yokohama 6 mm
Front Right Side:	Yokohama 6 mm	Rear Right Side:	Yokohama 6 mm

*The above values represent the remaining tyre treads depth*

<b>COST OF CLAIMS</b>	<b>Repairer's</b>	<b>Adjuster's</b>	<b>Difference</b>	<b>Diff %</b>
Parts	3,179.00	3,058.00	121.00	3.81
Miscellaneous Items	475.00	410.00	65.00	13.68
Labour	2,680.00	2,110.00	570.00	21.27
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Calculated Gross Total (\$\$)</b>	<b>6,334.00</b>	<b>5,578.00</b>	<b>756.00</b>	<b>11.94</b>
<b>Approved Total (Overridden) (\$\$)</b>		<b>4,450.00</b>		
<b>(\$\$)</b>	6,334.00	4,450.00	1,884.00	29.74
<b>+ GST 7.00/7.00% (\$\$)</b>	443.38	311.50	131.88	29.74
<b>Nett Amount (\$\$)</b>	<b>6,777.38</b>	<b>4,761.50</b>	<b>2,015.88</b>	<b>29.74</b>
<b>Global Sum Settlement (\$\$)</b>		<b>0.00</b>		

**INSPECTION**

Date of Assignment:	26/08/2022	Present Location:	Wah Hong Motors & Credit Pte Ltd (HQ)
Date Inspected:	26/08/2022	Inspected At:	Wah Hong Motors & Credit Pte Ltd (HQ)
			38 Toh Guan Road East, #01-57, Enterprise Hub
			Singapore 608581
Estimated Period of Repair:	8.0 days		

**Adjuster:** MOHD RASUL**Manager:** CHEW HSIAO TONG

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

## REPAIR DETAILS

### Reference

<b>Part Source:</b>	MRM-SG	Version: 1.0 (Last Synchronised: 16 Jan 2023)
<b>Parts:</b>	143	NISSAN ALMERA 1.5 5MT AIRBAG 2WD 4DR (A) (Catalogue:Merimen Singapore 1.0)
<b>Labour:</b>	Repairer's	(Price-denominated Standard List)
<b>Print Code:</b>	(Unsubmitted, no print-code for SLV8538E)	
<b>Validity:</b>	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
<b>Further Info:</b>	Items/values not in reference catalogue are prefixed with an asterisk *.	

### Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		<b>*Boot lid</b> (WCP)	Bent	450.00 F	*450.00 F
2	1		<b>*Boot lid hinge RH/LH@2*\$70</b> (WCP)	Bent	140.00 F	*140.00 F
3	1		<b>*Boot lid lock</b> (WCP)	Bent	60.00 F	*60.00 F
4	1		<b>*Boot lid logo badge</b> (WCP)	Not Necessary	40.00 F	*- F
5	1		<b>*Boot lid emblem Almera</b> (WCP)	Necessary	40.00 F	*40.00 F
6	1		<b>*Boot lid weather stripe</b> (WCP)	Necessary	60.00 F	*60.00 F
7	1		<b>*End panel</b> (WCP)	Bent	230.00 F	*230.00 F
8	1		<b>*End panel top garnish</b> (WCP)	Deformed	100.00 F	*100.00 F
9	1		<b>*Tail lamp RH/LH@2*\$150</b> (WCP)	Cracked	300.00 F	*300.00 F
10	1		<b>*Rear fender RH</b> (WCP)	Buckled	750.00 F	*750.00 F
11	1		<b>*Rear reinforcement beam RH/LH@2*\$70</b> (WCP)	N/S Not Necessary / O/S Bent	140.00 F	*70.00 F
12	1		<b>*Rear bumper</b> (WCP)	Cut	280.00 F	*280.00 F
13	1		<b>*Rear bumper side retainer RH/LH@2*\$35</b> (WCP)	Necessary	70.00 F	*70.00 F
14	1		<b>*Spare tyre top cover</b> (WCP)	Deformed	230.00 F	*230.00 F
15	1		<b>*Rear fender LH (Repair refer to labour)</b> (NPA) (WCP)	Repair	0.00 F	*- F
16	1		<b>*Rear floor panel (Repair refer to labour)</b> (NPA)(WCP)	Repair	0.00 F	*- F

F=Franchise part.

<b>Sub Total (\$)</b>	<b>2,890.00</b>	<b>2,780.00</b>
<b>+ Margin on L,N Items 10.00/10.00% (\$)</b>	289.00	278.00
<b>Total Parts (\$)</b>	<b>3,179.00</b>	<b>3,058.00</b>

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

No	Qty	Particulars	Repairer's	Amount
<b>Miscellaneous Items</b>				
1	1	<b>Boot lid insulator clips</b> (NECESSARY)	25.00	25.00
2	1	<b>End panel sealant</b> (NECESSARY)	60.00	40.00
3	1	<b>Rear bumper clips</b> (NECESSARY)	35.00	30.00
4	1	<b>Rear car plate with holder</b> (CRACKED)	35.00	35.00
5	1	<b>Rear fender RH sealant</b> (NECESSARY)	60.00	40.00
6	1	<b>Rear reverse sensor</b> (CRACKED)	200.00	200.00
7	1	<b>Rear windscreen sealant</b> (NECESSARY)	60.00	40.00
<b>Sub Total (\$\$)</b>			<b>475.00</b>	<b>410.00</b>

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b>Labour Items</b>				
1	To remove the affected parts & fittings to commence repairs; panel beat & reshape the affected areas and replace the damaged parts and components	New	1,200.00	1,000.00
2	To supply paint materials, expandable items & putty, respray paint on parts replaced & repaired	New	1,000.00	800.00
3	To remove and refix wiring system at accident damaged area and check for all electrical proper function	New	60.00	30.00
4	To remove and replace rear reverse sensor	New	100.00	40.00
5	To remove and refit rear seat in order to repair	New	100.00	60.00
6	To remove and refit upholster garnish & roofs lining in order to repair	New	100.00	60.00
7	To remove and refit rear windscreen	New	120.00	120.00
<b>Gross Labour Cost (\$\$)</b>			<b>2,680.00</b>	<b>2,110.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >