

Your Ref: 2021 - 89

Date: 01st Sep 2022

Our Ref: CS1/SCD22008248/Kqy3m4

M/s Singapore Civil Defence Force (MHA05)

91 Ubi Ave 4

Singapore 408827

(The Motor Claims Department)

Attn: Ralf Tay Gim Chye

Dear Sir / Madam,

EVALUATION REPORT (PAPER SURVEY) OF ACCIDENT VEHICLE NO: SHA 7663R

INSURED VEHICLE: QX 1225J

ACCIDENT DATE: 01/10/2021

We thank you for your instruction on 23/08/2022.

We acknowledge receipt of the following documents:-

- a) Automobile Inspection Report of SHA 7663R from M/s Vicom Ltd.
- b) Singapore Accident Statement and Police Report of Vehicles SHA 7663R.
- c) Colour damaged vehicle photographs of SHA 7663R.
- d) Tax Invoice from M/s ComfortDelGro Engineering Pte Ltd.

Based on the documents received from you, we have evaluated the damages of the vehicle and have the following comments:-

1. Information Recorded: -

Registration Number	: SHA7663R
Make & Model	: Hyundai AE Ioniq Hev FL 1.6 DCT
Chassis Number	: KMHC851CVLU189584
Year of Registration	: 2020
Engine Capacity	: 1580 cc

2. We recommend that the repairs of the entire damage require about 2 (Two) working days to complete.
3. We hereby provide our recommendations on the cost of repair to the damaged vehicle as stated in the following page.



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SHA 7663R

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<u>REPLACEMENT OF PARTS</u>			
1	REAR BUMPER	DEFORMED	459.40	459.40
1	REAR BUMPER CENTRE MOULDING	SNAPPED	451.25	451.25
1	REAR TOWING COVER	SNAPPED	98.80	98.80
10	REAR BUMPER CLIPS	NECESSARY	22.00	22.00
1	REAR BUMPER LOWER MOULDING	SNAPPED	47.50	47.50
1	REAR BUMPER STAY LH	DENTED	138.10	138.10
1	REAR BUMPER BEAM	REUSE	398.80	-
1	REAR BUMPER SIDE BRACKET	REUSE	55.80	-
1	BOOT LID IONIQ EMBLEM	NOT NECESSARY	31.30	-
1	BOOT LID HYBRID EMBLEM	NOT NECESSARY	24.30	-
	LESS 20% DISCOUNT		-345.45	-243.41
			1,381.80	973.64
	<u>SPECIAL NETT ITEMS</u>			
1	BOOT LID COMFORT & TEL NO. STICKER (SN)	NOT NECESSARY	60.00	-
1	BOOT LID APP STICKER (SN)	NOT NECESSARY	40.00	-
1	REAR BUMPER REVERSE SENSOR (SN)	MALFUNCTION	180.00	180.00
1	REAR BUMPER RUBBER MAT (SN)	NECESSARY	50.00	50.00
2	REAR FENDER ADVERTISEMENT LOGO RH/LH (SN)	NECESSARY	200.00	200.00
1	BOOT LID ADVERTISEMENT LOGO (SN)	NOT NECESSARY	50.00	-
			580.00	430.00
	<u>LABOUR</u>			
	LABOUR CHARGES.		750.00	350.00
	SPRAY PAINTING CHARGES.		600.00	250.00
	REMOVE/ REFIX REVERSE SENSOR.		80.00	60.00
			1,430.00	660.00
	GRAND TOTAL		3,391.80	2,063.64



RECOMMENDED COST OF REPAIRS			2,063.64
-----------------------------	--	--	-----------------

Report Ref No. CS1/SCD22008248/Kqy3m4

A handwritten signature in black ink, appearing to be 'KSC'.

KONG SENG CHEONG

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.