



**VICOM LTD**

385 Sin Ming Drive Singapore 575718

Mainline (65) 6458 4555  
Facsimile (65) 6458 1040

www.vicom.com.sg  
Company Registration No: 198100320K

## TAX INVOICE

COMFORTDELGRO ENGINEERING PTE LTD  
#205 Braddell Road  
Blk C Ext 1 3rd Level  
Singapore 579701

ATTN : MOTOR CLAIMS DEPT.

VEHICLE No. : SHA7663R  
ACCIDENT DATE : 01/10/2021  
LAIM No. : 305489062

GST REG No. : M9-0000652-A  
CUSTOMER ID : VACC0013  
INVOICE No. : LY013626  
INVOICE DATE : 13/10/2021  
PAYMENT TERM : 30 Days Credit

DESCRIPTION	QTY	UNIT PRICE (SG\$)	AMOUNT (SG\$)
Photographs	28	1.00	\$ 28.00
Transportation	1	50.00	\$ 50.00
VAC Assessment Fee	1	155.00	\$ 155.00

REMARKS	GROSS AMOUNT	\$	233.00
CTPL	GST @ 7%	\$	16.31
	INVOICE AMOUNT	\$	249.31

This is a computer generated TAX INVOICE  
No signature required

Cheque should be made payable to '**VICOM LTD**'.

**Sin Ming**  
385 Sin Ming Drive Singapore 575718  
Tel: (65) 6455 5358 Fax: (65) 6455 8638

**Bukit Batok**  
511 Bukit Batok St 23 Singapore 659545  
Tel: (65) 6560 3312 Fax: (65) 6569 0722

**Kaki Bukit**  
23 Kaki Bukit Ave 4 Singapore 415933  
Tel: (65) 6741 6697 Fax: (65) 6749 2305

COMFORTDELGRO ENGINEERING PTE LTD  
#205 Braddell Road  
Blk C Ext 1 3rd Level  
Singapore 579701



VICOM LTD  
385 Sin Ming Drive Singapore 575718

Mainline (65) 6458 4555  
Facsimile (65) 6458 1040

www.vicom.com.sg  
Company Registration No: 198100320K

## SURVEY REPORT

GENERAL INFORMATION			
VAC Ref. No.	: 570646	Claim No.	: 305489062
Accident Date	: 01/10/2021	Claim Type	: THIRD PARTY
Assignment Date	: 02/10/2021	Policy No.	:
Survey Date	: 02/10/2021	Finalised Dt.:	:
Survey Report Date	: 12/10/2021		
VEHICLE PARTICULARS			
Vehicle No.	: SHA7663R	Chassis No.	: KMHC851CVLU189584
Registration Date	: 11/03/2020	Engine No.	: OBSCURED
Make	: HYUNDAI	Engine Cap.	: 1580 CC
Model	: IONIQ (G3)	Transmission	: AUTO
		Colour	: BLUE
CONDITION OF VEHICLE DURING SURVEY (VISUAL and STATIC TEST ONLY)			
Foot Brake	: SERVICEABLE	Steering	: SERVICEABLE
Hand Brake	: SERVICEABLE	Modification	: NONE
Mileage	: 207893KM		
<u>TYRES</u>	<u>SIZE</u>	<u>MAKE</u>	<u>BALANCE (mm)</u>
FRONT RH	195/60R16	WESTLAKE	6
FRONT LH	195/60R16	WESTLAKE	6
REAR RH	195/60R16	WESTLAKE	6
REAR LH	195/60R16	WESTLAKE	6
SURVEY CONDUCTED AT			
59 Loyang Drive Singapore 508969			
REMARKS			
[1] Workshop Estimate : S\$ 3,391.80			
[2] Our Adjustment : S\$ 2,683.12			
[3] Repair Period : 2 days			
[4] We have not authorised repairs. This survey was carried out on without prejudice basis.			

**VICOM LTD**  
**SURVEY REPORT**

SHA7663R @ 01/10/2021

**Annex A: Adjustment on Spare Parts**

#	Qty	Vehicle Parts Description	Condition	Workshop Estimate (S\$)	VAC Adjustment (S\$)
1	1	Rear Bumper	Deformed	459.40	459.40
2	1	Rear Bumper Centre Moulding	Snapped	451.25	451.25
3	1	Rear Towing Cover	Snapped	98.80	98.80
4	10	Rear Bumper Clips	Necessary	22.00	22.00
5	1	Rear Bumper Lower Moulding	Snapped	47.50	47.50
6	1	Rear Bumper Stay Lh	Dented	138.10	138.10
7	1	Rear Bumper Beam	Reuse	398.80	0.00
8	1	Rear Bumper Side Bracket	Reuse	55.80	0.00
9	1	Boot Lid Ioniq Emblem	Necessary	31.30	31.30
10	1	Boot Lid Hybrid Emblem	Necessary	24.30	24.30
<b>Subtotal</b>				: 1727.25	1272.65
Less 20 %				345.45	254.53
<b>TOTAL</b>				: 1381.80	1018.12

**SPECIAL NETT ITEM**

1	1	Boot Lid Comfort & Tel No. Sticker	Necessary	60.00	60.00
2	1	Boot Lid App Sticker	Necessary	40.00	40.00
3	1	Rear Bumper Reverse Sensor	Malfunction	180.00	180.00
4	1	Rear Bumper Rubber Mat	Necessary	50.00	50.00
5	2	Rear Fender Advertisement Logo Rh/Lh	Necessary	200.00	200.00
6	1	Boot Lid Advertisement Logo	Necessary	50.00	50.00
<b>TOTAL</b>				: 580.00	580.00

**TOTAL FOR SPARE PARTS** : 1961.80 1598.12

**VICOM LTD**  
**SURVEY REPORT**

SHA7663R @ 01/10/2021

**Annex B: Adjustment on Labour and Spray Painting**

#	Job Description	Workshop Estimate (S\$)	VAC Adjustment (S\$)
1	Labour charges	750.00	525.00
2	Spray painting charges	600.00	500.00
3	Remove/ refix reverse sensor	80.00	60.00
<b>TOTAL FOR LABOUR AND SPRAY PAINTING</b>		<b>1430.00</b>	<b>1085.00</b>

**Summary**

Description	Workshop Estimate (S\$)	VAC Adjustment (S\$)
<b>TOTAL FOR SPARE PARTS</b>	<b>1961.80</b>	<b>1598.12</b>
<b>TOTAL FOR LABOUR AND SPRAY PAINTING</b>	<b>1430.00</b>	<b>1085.00</b>
<b>TOTAL REPAIR COST</b>	<b>3391.80</b>	<b>2683.12</b>

**SURVEY REPORT****Annex C: Conclusion****ASSESSOR'S REPORT**

At the place of inspection, we saw this vehicle sustained rear damage.

The damages seen during our survey were at rear bumper, boot lid and surrounding areas. A fuller detailed description of the damages is in Annex A of this survey report.

**ASSESSOR'S RECOMMENDATION**

Comfortdelgro Engineering Pte Ltd (Loyang) estimated a repair cost of S\$3,391.80. We adjusted it to S\$2,683.12 on a part-by-part basis.

Accordingly, we recommend repairs to this vehicle be carried out on a part-by-part basis at S\$2,683.12.

The repairs would require a period of 2 working days.



Kamarudin Abdul Kadir  
for VICOM Ltd



VICOM ASSESSMENT CENTRE VEHICLE No.: SHA7663R ACCIDENT DATE : 01/10/2021





VICOM ASSESSMENT CENTRE VEHICLE No.: SHA7663R ACCIDENT DATE : 01/10/2021



VICOM ASSESSMENT CENTRE VEHICLE No.: SHA7663R ACCIDENT DATE : 01/10/2021













VICOM ASSESSMENT CENTRE VEHICLE No.: SHA7663R ACCIDENT DATE : 01/10/2021




VICOM ASSESSMENT CENTRE VEHICLE No.: SHA7663R ACCIDENT DATE : 01/10/2021



VICOM ASSESSMENT CENTRE VEHICLE No.: SHA7663R ACCIDENT DATE : 01/10/2021





VICOM ASSESSMENT CENTRE VEHICLE No.: SHA7663R ACCIDENT DATE : 01/10/2021

