

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

AIG Asia Pacific Insurance Pte. Ltd.
AIG Building, 78 Shenton Way, #09-16
Singapore 079120

Our File No: CC3/AIG22008250/TVCE2**Date:** 23/11/2022**REFERENCE**

Insured/Claimant:	CHAN SONG KIA	Policy No:	2070149801	
Date of Loss:	19/08/2022	Nature of Claim:	OD	Claim No: 0859248373SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SMV9108U		
Make & Model:	AUDI A5, 2.0 SPORTBACK (A)	Engine No:	DEM025899
Reg. Date:	27/10/2020 (Man. Year: 2020)	Chassis No:	WAUZZZF57MA005956
Colour:	Black	Odometer:	32242 km
Engine Capacity:	1984 cc		
Market Value/New Car Price:	S\$180,000.00		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:		Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:	

CONDITION OF TYRES

Front Tyre Size:	245/40 R18	Rear Tyre Size:	245/40 R18
Front Left Side:	Pirelli 6 mm	Rear Left Side:	Pirelli 6 mm
Front Right Side:	Pirelli 6 mm	Rear Right Side:	Pirelli 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	23,581.00	10,870.80	12,710.20	53.90
Miscellaneous Items	0.00	0.00	0.00	
Labour	13,594.00	3,414.00	10,180.00	74.89
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	37,175.00	14,284.80	22,890.20	61.57
- Excess (S\$)	700.00	700.00	0.00	0.00
(S\$)	36,475.00	13,584.80	22,890.20	62.76
+ GST 7.00/7.00% (S\$)	2,553.25	950.94	1,602.31	62.76
Nett Amount (S\$)	39,028.25	14,535.74	24,492.51	62.76

INSPECTION

Date of Assignment:	26/08/2022		
Date Inspected:	25/08/2022	Inspected At:	Premium Automobiles Pte Ltd (UBI) 55 Ubi Road 1 Singapore 408699
Estimated Period of Repair:	5.0 days		

Adjuster: MOHD TAUFIKH BIN HAMID**Manager:** VERON CHEN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER	Deformed	2,493.00 FS	*1,994.40 FS
2	2		*FRONT BUMPER SECURING STRIP	Not Necessary	79.00 FS	*- FS
3	1		*FRONT BUMPER GRILLE - CENTER	Broken	219.00 FS	*174.80 FS
4	1		*FRONT BUMPER CLOSING ELEMENT - LOWER CENTRE	Not Necessary	293.00 FS	*- FS
5	1		*FRONT BUMPER SPOILER	Not Necessary	599.00 FS	*- FS
6	1		*FRONT RADIATOR AIR GUIDE - RH	Deformed	72.00 FS	*57.20 FS
7	1		*FRONT BUMPER CLOSING ELEMENT	Not Necessary	293.00 FS	*- FS
8	1		*RADIATOR AIR GUIDE GRILLE - RH	Deformed	151.00 FS	*120.40 FS
9	1		*FRONT BUMPER MOLDING TRIM STRIP - RH	Cut	54.00 FS	*42.64 FS
10	1		*FRONT TRIM - CENTER	Not Necessary	127.00 FS	*- FS
11	1		*RADIATOR GRILLE	Not Necessary	1,881.00 FS	*- FS
12	1		*FRONT BUMPER FOAM FILLER PIECE	Not Necessary	163.00 FS	*- FS
13	1		*FRONT BUMPER CARRIER	Not Necessary	899.00 FS	*- FS
14	1		*FRONT BUMPER GUIDE SECTION - RH	Necessary	41.00 FS	*32.24 FS
15	1		*FRONT BUMPER TOP COVER	Not Necessary	143.00 FS	*- FS
16	1		*CAUTION SIGN STICKER	Not Necessary	16.00 FS	*- FS
17	1		*AIR CONDITIONER STICKER	Not Necessary	9.00 FS	*- FS
18	1		*FRONT BUMPER LOCK CARRIER BRACKET	Not Necessary	154.00 FS	*- FS
19	2		*FRONT BUMPER SUPPORT - LH / RH	Not Necessary	64.00 FS	*- FS
20	1		*FRONT LOW TONE HORN BRACKET - RH	Not Necessary	139.00 FS	*- FS
21	1		*FRONT LOW TONE HORN MOUNT BRACKET	Not Necessary	33.00 FS	*- FS
22	1		*FRONT PARKING AID SENSOR - OUTER	Not Necessary	266.00 FS	*- FS
23	1		*FRONT PARKING AID SENSOR - SIDE	Cut	266.00 FS	*212.00 FS
24	4		*FRONT PARKING AID SEAL RING	Necessary	10.00 FS	*8.00 FS
25	1		*SET FRONT BUMPER WIRING	Not Necessary	449.00 FS	*- FS
26	1		*FRONT FENDER - RH	Bent	1,189.00 FS	*951.20 FS
27	1		*FRONT FENDER ATTACHMENT PARTS	Not Necessary	55.00 FS	*- FS
28	1		*FRONT FENDER CLOSING ELEMENT - RH	Bent	83.00 FS	*65.84 FS
29	1		*FRONT FENDER BRACKET - RH	Necessary	41.00 FS	*32.72 FS
30	1		*FRONT FENDER RIVET (6PCS)	Not Necessary	23.00 FS	*- FS
31	1		*FRONT FENDER DEFORMATION ELEMENT BRACKET - RH	Not Necessary	55.00 FS	*- FS
32	1		*FRONT FENDER BRACE - RH	Bent	132.00 FS	*105.20 FS
33	1		*FRONT FENDER TRIM - RH	Necessary	171.00 FS	*136.40 FS
34	1		*FRONT FENDER LEDGE COVER	Not Necessary	40.00 FS	*- FS
35	1		*FRONT FENDER LEDGE COVER - RH	Not Necessary	18.00 FS	*- FS
36	1		*HEADLIGHT COVER - RH	Not Necessary	49.00 FS	*- FS
37	1		*FRONT WHEEL HOUSING LINER - RH	Torn	299.00 FS	*238.80 FS
38	1		*FRONT WHEEL SPOILER - RH	Broken	82.00 FS	*65.12 FS
39	1		*FRONT WHEEL SPOILER TRIM - RH	Not Necessary	40.00 FS	*- FS
40	1		*FRONT STONE CHIP GUARD - RH	Broken	57.00 FS	*45.28 FS
41	1		*FRONT FENDER INNER LOWER BRACKET - RH	Not Necessary	27.00 FS	*- FS
42	1		*HEADLIGHT - RH	Cracked	8,172.00 FS	*6,537.60 FS
43	1		*HEADLIGHT HOSE	Not Necessary	42.00 FS	*- FS
44	3		*HEADLIGHT COMPENSATING PIECE	Not Necessary	137.00 FS	*- FS
45	1		*LIFT CYLINDER - RH	Not Necessary	217.00 FS	*- FS
46	1		*LIFT CYLINDER BRACKET - RH	Cracked	17.00 FS	*12.88 FS
47	1		*LIFT CYLINDER WASHER HOSE	Not Necessary	107.00 FS	*- FS
48	1		*HEADLIGHT WASHER HOSE	Not Necessary	53.00 FS	*- FS
49	1		*FRONT SHIELD NOISE INSULATION	Not Necessary	640.00 FS	*- FS
50	1		*LOCK CARRIER	Not Necessary	1,127.00 FS	*- FS
51	1		*RADIATOR COOLANT REGULATOR SUPPORT - RH	Not Necessary	43.00 FS	*- FS

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
52	1		*OUTSIDE TEMPERATURE SENSOR BRACKET	Not Necessary	21.00 FS	*- FS
53	1		*FRONT INTER-COOLER HOSE - RH	Not Necessary	413.00 FS	*- FS
54	1		*RADIATOR AIR GUIDE - RH	Not Necessary	36.00 FS	*- FS
55	2		*RADIATOR AIR GUIDE - LH / RH	Not Necessary	38.00 FS	*- FS
56	2		*RADIATOR AIR GUIDE - UPPER / LOWER	Not Necessary	44.00 FS	*- FS
57	1		*FRONT DOOR TRIM - RH	Not Necessary	171.00 FS	*- FS
58	1		*FRONT WINDOW SLOT SEAL TRIM STRIP - RH	Not Necessary	446.00 FS	*- FS
59	1		*FRONT NO PLATE	Not Necessary	60.00 FS	*- FS
60	1		*SUNDRIES	Necessary	500.00 FS	*19.68 FS
61	1		*HORN WIRE CONNECTOR (Supplementary)	Necessary	23.00 FS	*18.40 FS
F=Franchise part. S=SpcNett.						
Total Parts (S\$)					23,581.00	10,870.80

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO REMOVE, CHECK AND TRANSFER FRONT WIRE HARNESS FOR HEADLIGHTS, HORNS, OUTSIDE TEMPERATURE SENSOR, HEADLIGHT WASHER ASSY AND FRONT PARKING AID	New	480.00	480.00
2	TO REMOVE AND TRANSFER RHS HEADLIGHTS CONTROL UNIT AND POWER MODULE	New	450.00	450.00
3	TO REMOVE AND REINSTALL AIRCON CONDENSER, CHARGE AIR COOLER AND RADIATOR. CHECK ELECTRICAL FANS AND CONTROL UNIT. PRESSURISE COOLING SYSTEM	New	1,700.00	0.00
4	TO CARRY OUT VACUUM AND REGAS FOR R1234	New	1,200.00	0.00
5	TO REMOVE AND REINSTALL RHS FRONT DOOR PANEL TRIM. TO REMOVE AND REINSTALL RHS WING MIRROR ASSY TO FACILITATE RESPRAY OF RHS FRONT DOOR	New	380.00	0.00
6	TO DISMANTLE AND RENEW FRONT BUMPER, RHS FRONT FENDER AND RHS HEADLIGHT. TO REPAIR RHS FRONT DOOR. TO RENEW FRONT LOCK CARRIER AND ALIGN TO POSITION. RE-ORGANIZE CRASH MANAGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVED	New	5,500.00	1,000.00
7	TO RESPRAY FRONT BUMPER, RHS FRONT FENDER AND RHS FRONT DOOR	New	3,500.00	1,100.00
8	TO CARRY OUT PRE/POST DIAGNOSTIC CHECK	New	384.00	384.00
Gross Labour Cost (\$\$)			13,594.00	3,414.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >