

**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

**VEHICLE DAMAGE INSPECTION REPORT****Our File No:** CS/AIS22008256/ANY3Q2**Date:** 27/12/2022REFERENCE

Handling Insurer:	Allianz Insurance Singapore Pte. Ltd.	Policy No:	SP2000745952
<b>Claimant Vehicle No :</b>	SLK2031Y	<b>Insured Vehicle No :</b>	SMX7635S
Date of Loss:	18/08/2022	Nature of Claim:	TP
		Claim No:	202222006326

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	<b>SLK2031Y</b>	Engine No:	K20A5820549
Make & Model:	HONDA CIVIC, 2.0 (M)	Chassis No:	FD21400529
Reg. Date:	18/12/2007 (Man. Year: 2007)	Odometer:	211356 km
Colour:	White		
Engine Capacity:	1998 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	<b>Market Value/New Car Price</b>		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	225/45 R17	Rear Tyre Size:	225/45 R17
Front Left Side:	Bridgestone 6 mm	Rear Left Side:	Bridgestone 6 mm
Front Right Side:	Bridgestone 6 mm	Rear Right Side:	Bridgestone 6 mm

*The above values represent the remaining tyre treads depth*

<b>COST OF CLAIMS</b>	<b>Repairer's</b>	<b>Adjuster's</b>	<b>Difference</b>	<b>Diff %</b>
Parts	8,308.40	3,944.64	4,363.76	52.52
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,130.00	1,300.00	830.00	38.97
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Calculated Gross Total (S\$)</b>	<b>10,438.40</b>	<b>5,244.64</b>	<b>5,193.76</b>	<b>49.76</b>
<b>Approved Total (Overridden) (S\$)</b>		<b>4,200.00</b>		
<b>(S\$)</b>	10,438.40	4,200.00	6,238.40	59.76
<b>+ GST 7.00/7.00% (S\$)</b>	730.69	294.00	436.69	59.76
<b>Nett Amount (S\$)</b>	<b>11,169.09</b>	<b>4,494.00</b>	<b>6,675.09</b>	<b>59.76</b>

INSPECTION

Date of Assignment:	25/08/2022	Twincar Automotive Pte Ltd - Kaki Bukit (HQ) 2 KAKI BUKIT AVENUE 2, #01-17 KAKI BUKIT AUTOHUB Singapore 417921
Date Inspected:	25/08/2022 Inspected At:	
Estimated Period of Repair:	5.0 days	

**Adjuster:** ADRIAN LING**Manager:** HUEY YON

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

## REPAIR DETAILS

### Reference

<b>Part Source:</b>	MRM-SG	Version: 1.0 (Last Synchronised: 27 Dec 2022)
<b>Parts:</b>	143	HONDA CIVIC 2.0 (M) (Catalogue:Merimen Singapore 1.0)
<b>Labour:</b>	Repairer's	(Price-denominated Standard List)
<b>Print Code:</b>	(Unsubmitted, no print-code for SLK2031Y)	
<b>Validity:</b>	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
<b>Further Info:</b>	Items/values not in reference catalogue are prefixed with an asterisk *.	

### Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER	Torn	873.90 FL	*873.90 FL
2	1		*FRONT BUMPER LOWER LID GARNISH	Not Necessary	450.00 FL	*- FL
3	1		*FRONT BUMPER SIDE RETAINER L/R	O/S Damaged	57.80 FL	*28.90 FL
4	1		*FRONT RH FENDER INNER SHIELD	Torn	127.40 FL	*127.40 FL
5	1		*FRONT RH FENDER LAMP	Not Necessary	39.40 FL	*- FL
6	1		*FRONT RH HEADLAMP	Cracked	1,100.40 FL	*1,100.40 FL
7	1		*FRONT RH HEADLAMP LOWER BRACKET	Not Necessary	29.10 FL	*- FL
8	1		*FRONT RH KNUCKLE ARM	Not Necessary	295.70 FL	*- FL
9	1		*FRONT RH KNUCKLE ARM BEARING	Damaged	112.40 FL	*112.40 FL
10	1		*FRONT RH LOWER ARM	Bent	450.80 FL	*450.80 FL
11	1		*FRONT RH LOWER ARM BALL JOINT	Not Necessary	93.40 FL	*- FL
12	1		*FRONT RH SIDE MIRROR	Not Necessary	360.40 FL	*- FL
13	1		*FRONT RH STEERING TIE ROD	Not Necessary	87.90 FL	*- FL
14	1		*FRONT RH STEERING TIE ROD END	Not Necessary	82.40 FL	*- FL
15	1		*FRONT RH WHEEL HUB	Damaged	249.50 FL	*249.50 FL
16	1		*SET FRONT BUMPER CLIPS	Necessary	50.00 FS	*30.00 FS
17	1		*FRONT BUMPER STICKER	Necessary	80.00 FS	*30.00 FS
18	1		*FRONT RH FENDER	Dented	1,500.00 FS	*900.00 FS
19	1		*SET FRONT RH FENDER INNER SHIELD CLIPS	Necessary	50.00 FS	*30.00 FS
20	1		*FRONT RH SPORT RIM	Cut	900.00 FS	*600.00 FS
21	1		*FRONT RH TYRE	Not Necessary	400.00 FS	*- FS
22	1		*SET FRONT SHOCK ABSORBER	Not Necessary	1,800.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

<b>Sub Total (\$)</b>	<b>9,190.50</b>	<b>4,533.30</b>
<b>- List Item Discount on L Items 20.00/20.00% (\$)</b>	882.10	588.66
<b>Total Parts (\$)</b>	<b>8,308.40</b>	<b>3,944.64</b>

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b>Labour Items</b>				
1	TO REMOVE ,REINSTALL ELECTRICAL WIRING HARNESS ,CHECK LIGHTING (TO FR)	New	60.00	30.00
2	TO REMOVE ,REINSTALL FRONT SUSPENSION UNDERCARRIAGE PARTS (TO FR)	New	220.00	150.00
3	TO ROAD TEST DRIVING ,CHECK AND RESETTNG WHEEL ALIGNMENTS SYSTEM	New	100.00	80.00
4	TO RE-SPRAY PAINTING ON THE CHARGE BODYPARTS ,REPAIR PORTION ,AND WHERE CONSISTENT TO THE ACCIDENT	New	1,000.00	500.00
5	TO PROVIDE LABOUR ,WORKMANSHIP TO CHARGE THE ABOVE DAMAGED BODYPARTS ,REPAIR ,RE-CONSTRUCT AND RE-ALIGN BODY STRUCTURE BODY ALIGNMENTS AND DAMAGED CONSISTENT TO THE ACCIDENT	New	700.00	500.00
6	TO APPLY ANTI-RUST CHEMICAL ON REPAIRED AND REPLACED PANEL	New	50.00	40.00
<b>Gross Labour Cost (\$\$)</b>			<b>2,130.00</b>	<b>1,300.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >