

National Assessment Centre Services

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933 TEL: 6841 0055 FAX: 6841 6315

Reg. No: 52983356E GST Reg. No. 20-0405911-H



Page No.:1 of 1

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SHD 6752H

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	REPLACEMENT OF PARTS			
1	BUMPER ASSY, FRT	TO REPAIR SEE LABOUR	1,890.50	-
1	BUMPER BRACKET, FRT / RH	NOT NECESSARY	95.00	-
1	BUMPER GRILLE RH	NOT NECESSARY	95.00	-
1	HEAD LAMP RH	NOT NECESSARY	3,957.00	-
	LESS 20% DISCOUNT		-1,207.50	-
			4,830.00	-
	<u>LABOUR</u>			
	PANEL BEATING. INCLUSIVE OF THE REPAIR OF BUMPER ASSY, FRT.		600.00	400.00
	SPRAY PAINTING CHARGE.		400.00	250.00
	WIRING CHARGE.	NOT NECESSARY	60.00	-
			1,060.00	650.00
	GRAND TOTAL		5,890.00	650.00

RECOMMENDED COST OF REPAIRS (CONFIRMED)		650.00

Report Ref No. NS/INC22008257/Tce2

MOHAMAD TAUFIKH

M.MATAI, AMSAE-A

Automotive Assessor

K.K.LAU CPT(RET)

BEng(Hons),B.Bus,MBA,PEng,PE, MInstAEA,MASME,MIRTE

REGD Auto Consultant-SAE, Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.