

## **LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

## ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. FBS 9283S

Qty	Description of Parts	Condition	Estimate By Workshop (\$))	Our Adjusted (\$)
	REPLACEMENT OF PARTS			
1	HANDLE BAR (O/S)	BENT	165.00	165.00
1	SET BALANCER	DENTED	140.00	80.00
1	RH MIRROR	DENTED/CUT	95.00	95.00
1	BRAKE LEVER	DENTED	87.00	80.00
1	FRONT RH FAIRING	DENTED/CUT	180.00	180.00
1	INNER GARNISH PANEL	DENTED	190.00	190.00
1	HEAD LAMP ASSY	MTG CRACKED	450.00	320.00
1	FRONT RH SIGNAL	BROKEN	95.00	95.00
1	RH LEG SHIELD	DENTED	180.00	140.00
1	FORK TUBE RH	BENT	380.00	380.00
1	EXHAUST GUARD - CENTRE	DENTED/CUT	210.00	120.00
1	EXHAUST NOZZLE GUARD	DENTED	190.00	190.00
1	EXHAUST GUARD - FRONT	SERVICEABLE	180.00	-
1	SET FRAME SLIDER	BENT	380.00	295.00
1	FRONT WHEEL SHAFT	SERVICEABLE	180.00	-
1	FRONT RIM	SERVICEABLE	320.00	-
1	LH FRONT SIGNAL	BURNT	95.00	95.00
	LESS 10% DISCOUNT		-351.70	-242.50
			3,165.30	2,182.50
	NETT ITEMS			
1	SET BODY DECAL STICKER (N)	NOT NECESSARY	90.00	-
			90.00	-
	<u>LABOUR</u>			
	TOWING FEE.		60.00	30.00
	LABOUR TO REMOVE/REPLACE NECESSARY PARTS, ALIGN & ETC.		250.00	120.00
	TOUCH UP PAINT WORK.	NOT NECESSARY	280.00	-
	RE-INSTALL FORK TUBE & TOP UP FORK OIL.		150.00	40.00

Report Ref No. CS/SMR22008265/Kcy3m4



## **LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$))	Our Adjusted (\$)
	REPRESS FRONT RIM.	NOT NECESSARY	120.00	-
			860.00	190.00
	GRAND TOTAL		4,115.30	2,372.50

RECOMMENDED COST OF LUMP SUM REPAIRS	1,900.00
(TO ITS PRE-ACCIDENT CONDITION)	

Report Ref No. CS/SMR22008265/Kcy3m4

KONG SENG CHEONG

**Licensed Appraiser**