

## **LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

PRE-REPAIR INSPECTION REPORT						
	LONPAC INSURAN	NCE BHD	Re	ef:	CS3/LPC22008267/Rvy3m4	
	300 BEACH ROAD Dat #17-04/07 THE CONCOURSESINGAPORE 199555			ate:	31/08/2022	
			Co	ode:	LPC2	
1.	. Policy Particulars :- (THIRD PARTY CLAIM)					
	Insured Veh.	XD 5780T	Veh. Inspected		YP 9848G	
	Policy No.		Coverage (\$)		0.00	
	Claim No.	22/22/22/VC05/026195	Excess (\$)		0.00	
	Assign From	GERALD POH	Assign Date		26/08/2022	
2. Vehicle Particulars & Condition						
	Make & Model	MITSUBISHI CANTER FEB21ER	c.c		2998	
	Engine No.	HIDDEN	Year of Reg.		2018	
	Chassis No.	FEB21EA25417	Colour		WHITE	
	Odometer	142221 KM	Steering		IN ORDER	
	Brakes	IN ORDER	Modification		NIL	
	General	FAIR				
3. Conditions of Tyres						
		Size	Make		Balance	
	R/H Front Tyre	195/80 R15C	KENDA		7 mm	
	L/H Front Tyre	195/80 R15C	KENDA		7 mm	
	R/H Rear Tyre	195/80 R15C (D/D)	KENDA		7/7 mm	
	L/H Rear Tyre	195/80 R15C (D/D)	KENDA		7/7 mm	
4. Description of Damages						
	THE VEHICLE SUS	STAINED DAMAGES AT THE REAR PORTION.				
5.	General Information					
	Accident Date	25/08/2022	Inspect Date / Tim	ne	26/08/2022 ( 03:30 PM )	
	Survey held at	4 Penjuru Close Singapore 608574				
	Repairer	AAK LOGISTICS SERVICES PL				
5a.	Remarks					
	A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION. THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE. C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS.					

Report Ref No. CS3/LPC22008267/Rvy3m4

Inspected By

MOHAMMED RASUL BIN MOHD YUNUS

K.K.LAU CPT(RET)

Automotive Assessor

 $BEng(Hons), B. Bus, MBA, PEng, PE, \, MInstAEA, MASME, MIRTE$ 

REGD Auto Consultant-SAE, Licensed Appraiser