

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CC4/AIS22008268/EPA3Q2**Date:** 11/11/2022REFERENCE

Handling Insurer:	Allianz Insurance Singapore Pte. Ltd.	Policy No:	SP2002060017
Claimant Vehicle No :	SMQ4231E	Insured Vehicle No :	SNG8689H
Date of Loss:	24/08/2022	Nature of Claim:	TP
		Claim No:	202222006309KC

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SMQ4231E	Engine No:	G4FGKH749532
Make & Model:	KIA CERATO, 1.6 SUNROOF (A)	Chassis No:	KNAF5416ML5052977
Reg. Date:	15/11/2019 (Man. Year: 2019)	Odometer:	45681 km
Colour:	Red		
Engine Capacity:	1591 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	205/55 R16	Rear Tyre Size:	205/55 R16
Front Left Side:	Bridgestone 4 mm	Rear Left Side:	Bridgestone 4 mm
Front Right Side:	Bridgestone 4 mm	Rear Right Side:	Bridgestone 4 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	2,976.00	1,884.00	1,092.00	36.69
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,580.00	1,580.00	0.00	0.00
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	4,556.00	3,464.00	1,092.00	23.97
+ GST 7.00/7.00% (S\$)	318.92	242.48	76.44	23.97
Nett Amount (S\$)	4,874.92	3,706.48	1,168.44	23.97
+ Loss of Use (3.0 x S\$60.00/day) (S\$)		180.00		
+ Doc/Search Fee (S\$)		2.00		
Nett Liability (S\$)		3,888.48		

INSPECTION

Date of Assignment:	25/08/2022	
Date Inspected:	26/09/2022	Inspected At: Cycle & Carriage KIA Pte Ltd (Pandan Gardens) 209 Pandan Gardens Singapore 609339
Estimated Period of Repair:	3.0 days	

Adjuster: CHEN TSUE YEE**Manager:** CHEW HSIAO TONG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 11 Nov 2022)
Parts:	143	KIA CERATO 1.6 SUNROOF (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SMQ4231E)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*SUNDRY	Necessary	20.00 FS	*20.00 FS
2	1		*COVER -FR BUMPER	Dented	633.00 FS	*633.00 FS
3	1		*GRILLE -FRONT BUMPER	Broken	669.00 FS	*669.00 FS
4	1		*MOULDING -FRONT BUMPER RH	Cut	298.00 FS	*298.00 FS
5	1		*LAMP ASSY -SIDE REPEATER ,RH	Cut	226.00 FS	*226.00 FS
6	1		*AIR DUCT -FR BUMPER ,RH	Not Necessary	14.00 FS	*- FS
7	1		*BRACKET -FR BUMPER UPR SIDE MTG	Not Necessary	31.00 FS	*- FS
8	1		*ABSORBER -FRONT BUMPER ENERGY	Not Necessary	84.00 FS	*- FS
9	1		*STIFFNER -FR BPR LWR	Not Necessary	114.00 FS	*- FS
10	1		*BEAM COMPLETE -FR BUMPER	Not Necessary	686.00 FS	*- FS
11	1		*ORNAMENT -KIA NO.115	Necessary	38.00 FS	*38.00 FS
12	1		*ULTRASONIC SENSOR ASSY -P.A.S	Not Necessary	163.00 FS	*- FS

F=Franchise part. S=SpcNett.

Total Parts (S\$)	2,976.00	1,884.00
--------------------------	-----------------	-----------------

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	RENEW FRT BUMPER ,FRT BUMPER LOWER GRILLE	New	640.00	640.00
2	SPRAY PAINT FOR FRT BUMPER	New	550.00	550.00
3	REMOVE & INSTALL PARKING SENSOR	New	60.00	60.00
4	CHECK WIRING & ELECTRICAL SYSTEM	New	50.00	50.00
5	TO CARRY OUT DIAGNOSTIC CHECK ON ELECTRONIC CONTROL SYSTEM	New	280.00	280.00
Gross Labour Cost (\$\$)			1,580.00	1,580.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >