

Steve

CCV/AIS 22008268/eq.3

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: _____

at Workshop m/s _____

of _____

Insured: _____

Policy No. _____

Claims No. _____

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

Bal. or Market Value: _____

IDAC Accident Report: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: _____ days Res.: Yes or No

Lum Sum: _____ % . . 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____

Veh No: SP133272-12 Yr Regn: 15/11/14
Type: M/Car / M/Cycle / Bus / Van / Lorry / Taxi / Prime Mover /
Truck / Trailer or _____
Make: KIA Cerato c.c. 1591
Colour: Red A/C: Insured / Std / Nil / NA
Sp/Reading: 15681 T/Radio: Insured / Std / Nil / NA
Eng/No: _____
K/No: KNAF5116ML503977
Gen. Cond: Good / Fair / Poor / Burnt
Steering: Good / Jammed / Leaked / Burnt or _____
Brake: Good / Jammed / Leaked / Burnt or _____
Modl: Nil / SVRim / STD A/Rim, or _____
Tyre Size: F: 205/55R16
R: 11

(S) DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
TOYO / YOKO or .

Front		Rear	
R/Bal.	4	R/Bal.	4
L/Bal.	4	L/Bal.	4
D.O.A.	7/18/77	D.O.I.	26/9/77

Survey held at Cycle.
Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

[illegible]

Date/Time, File Pass w?

☐: Prel. Report

☐ : Final Report

 $\therefore$

Date/Time, File Return to?

2)

Report Format :

Lump Sum / L.S.: (\$) .)

Days Of Repair:

Resurvey No. of Trip:

Add Fee: : Site Insp (\$

7: Interview (\$

: Tech, Invs (4)

: Weekend (%)

Survey Fee:

Transportation:

2) Photos

5) Others

TOTAL



CYCLE & CARRIAGE

CYCLE & CARRIAGE KIA PTE LTD
PANDAN GARDENS CUSTOMER SERVICE CENTRE

209 Pandan Gardens Singapore 609339 Tel: 65684555 Fax: 65651240



Movement that inspires

Co Reg No : 199405410K

ESTIMATE

GST Reg No : MR-8500111-X

Invoice Name & Address	Owner Name & Vehicle Info
Ms Choong Chee Chui	Cust No/Name /Ms CHOONG CHEE CHUI
BLK 279 TOH GUAN ROAD	Reg No/Reg Date SMQ4231E / 15/11/201
#15-193	Date In/Mileage / 0
SINGAPORE 600279	Chassis No KNAF5416ML5052977
Contact No Mobile: 98715246	Engine No G4FGKH749532
	Make/Model KIA/CERATO 1.6 A GT LINE H171
	Colour/Trim CR5 RUNWAY RED / WK SATURN BLACK

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No			
CSM00081	Cash	24/08/2022/ 11:37		442 / CocoLu	56342			
Description of Goods / Services					Qty	Unit Price	Disc%	Amount
E PNT88000								640.00
RENEW FRT BUMPER, FRT BUMPER LOWER GRILLE								
E PNT98000								550.00
SPRAY PAINT FOR FRT BUMPER								
E PNT88000								60.00
REMOVE & INSTALL PARKING SENSOR								
A 90000001								50.00
CHECK WIRING & ELECTRICAL SYSTEM								
A 10028901								280.00
TO CARRY OUT DIAGNOSTIC CHECK ON ELECTRONIC CONTROL SYSTEM								
M SUNDRY								20.00
Sundry								
-M COVER-FR BUMPER					1.00	633.00	00.00	633.00
-M GRILLE-FRONT BUMPER					1.00	669.00	00.00	669.00
-M MOULDING-FRONT BUMPER,RH					1.00	298.00	00.00	298.00
-M LAMP ASSY-SIDE REPEATER,RH					1.00	226.00	00.00	226.00
AIR DUCT-FR BUMPER,RH					1.00	14.00	00.00	14.00
BRACKET-FR BUMPER UPR SIDE MTG					1.00	31.00	00.00	31.00
ABSORBER-FRONT BUMPER ENERGY					1.00	84.00	00.00	84.00
STIFFNER-FR BPR LWR					1.00	114.00	00.00	114.00
BEAM COMPLETE-FR BUMPER					1.00	686.00	00.00	686.00
-M ORNAMENT-KIA NO.115					1.00	38.00	00.00	38.00
-M ULTRASONIC SENSOR ASSY-P.A.S					1.00	163.00	00.00	163.00

Estimate

Steve (LKK)

26/9/22, 1:30p

WIK

3 Lys

P/P

by BL y

Steve (LKK)

26/9/22, 1:30p

WIK

3 yrs

P/P

by BL Y

Confirm & accepted by

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation

Authorized signatory and company stamp

	Nett	4,556.00
7% GST on	4556.00	318.92
Total Payable		4,874.92

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required.
Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.