



CYCLE & CARRIAGE

CYCLE & CARRIAGE KIA PTE LTD
PANDAN GARDENS CUSTOMER SERVICE CENTRE

209 Pandan Gardens Singapore 609339 Tel: 65684555 Fax: 65651240



Movement that inspires

ESTIMATE

GST Reg No : MR-8500111-X

Co Reg No : 199405410K

Invoice Name & Address	Owner Name & Vehicle Info	
Ms Choong Chee Chui	Cust No/Name	/Ms CHOONG CHEE CHUI
BLK 279 TOH GUAN ROAD	Reg No/Reg Date	SMQ4231E / 15/11/201
#15-193	Date In/Mileage	/ 0
SINGAPORE 600279	Chassis No	KNAF5416ML5052977
Contact No Mobile: 98715246	Engine No	G4FGKH749532
	Make/Model	KIA/CERATO 1.6 A GT LINE H171
	Colour/Trim	CR5 RUNWAY RED / WK SATURN BLACK

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No			
CSM00081	Cash	24/08/2022/ 11:37		442 / CocoLu	56342			
Description of Goods / Services					Qty	Unit Price	Disc%	Amount
E PNT88000								640.00
RENEW FRT BUMPER, FRT BUMPER LOWER GRILLE								550.00
E PNT98000								60.00
SPRAY PAINT FOR FRT BUMPER								50.00
E PNT88000								280.00
REMOVE & INSTALL PARKING SENSOR								20.00
A 90000001								
CHECK WIRING & ELECTRICAL SYSTEM								
A 10028901								
TO CARRY OUT DIAGNOSTIC CHECK ON ELECTRONIC CONTROL SYSTEM								
M SUNDRY								
Sundry					1.00	633.00	00.00	633.00
M COVER-FR BUMPER					1.00	669.00	00.00	669.00
M GRILLE-FRONT BUMPER					1.00	298.00	00.00	298.00
M MOULDING-FRONT BUMPER,RH					1.00	226.00	00.00	226.00
M LAMP ASSY-SIDE REPEATER,RH					1.00	14.00	00.00	14.00
M AIR DUCT-FR BUMPER,RH					1.00	31.00	00.00	31.00
M BRACKET-FR BUMPER UPR SIDE MTG					1.00	84.00	00.00	84.00
M ABSORBER-FRONT BUMPER ENERGY					1.00	114.00	00.00	114.00
M STIFFNER-FR BPR LWR					1.00	686.00	00.00	686.00
M BEAM COMPLETE-FR BUMPER					1.00	38.00	00.00	38.00
M ORNAMENT-KIA NO.115					1.00	163.00	00.00	163.00
M ULTRASONIC SENSOR ASSY-P.A.S								

Confirm & accepted by

Nett	4,556.00
7% GST on	318.92
Total Payable	4,874.92

Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.