

**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

**VEHICLE DAMAGE INSPECTION REPORT**

ECICS Limited  
10 Eunos Road 8, #09-04A Singapore Post Centre  
Singapore 408600

**Our File No:** CS/ICS22008272/UCY3Q2**Date:** 15/09/2022**REFERENCE**

Insured/Claimant: JEPARKASH RAI S/O CHANDRA SEIKHAR RAI Policy No: MPC22A00113200

Date of Loss: 17/08/2022

Nature of Claim: OD

Claim No: DMPC2200374H

**DESCRIPTION & IDENTIFICATION OF VEHICLE**

Reg No: **SMM7014S**  
 Make & Model: SUBARU FORESTER, 2.0 I-S EYESIGHT AWD CVT SR (A) Engine No: FB20YF36979  
 Reg. Date: 11/07/2019 (Man. Year: 2018) Chassis No: JF1SK7KL5KG006644  
 Colour: Brown Odometer: 65937 km  
 Engine Capacity: 1995 cc  
 Market Value/New Car Price: S\$105,000.00  
 Sum Insured (\$\$): **Market Value/New Car Price**

**CONDITION OF VEHICLE AT THE TIME OF SURVEY**

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes  
 Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

**CONDITION OF TYRES**

Front Tyre Size: 225/50 R18 Rear Tyre Size: 225/50 R18  
 Front Left Side: Bridgestone 7 mm Rear Left Side: Bridgestone 7 mm  
 Front Right Side: Bridgestone 7 mm Rear Right Side: Bridgestone 7 mm

*The above values represent the remaining tyre treads depth*

| <b>COST OF CLAIMS</b>                     | <b>Repairer's</b> | <b>Adjuster's</b> | <b>Difference</b> | <b>Diff %</b> |
|-------------------------------------------|-------------------|-------------------|-------------------|---------------|
| Parts                                     | 11,499.60         | 4,837.80          | 6,661.80          | 57.93         |
| Miscellaneous Items                       | 170.00            | 30.00             | 140.00            | 82.35         |
| Labour                                    | 3,550.00          | 1,270.00          | 2,280.00          | 64.23         |
| Paintwork Labour                          | 0.00              | 0.00              | 0.00              |               |
| Towing                                    | 0.00              | 0.00              | 0.00              |               |
| <b>Calculated Gross Total (\$\$)</b>      | <b>15,219.60</b>  | <b>6,137.80</b>   | <b>9,081.80</b>   | <b>59.67</b>  |
| <b>Approved Total (Overridden) (\$\$)</b> |                   | <b>4,900.00</b>   |                   |               |
| <b>(\$\$)</b>                             | 15,219.60         | 4,900.00          | 10,319.60         | 67.80         |
| <b>+ GST 7.00/7.00% (\$\$)</b>            | 1,065.37          | 343.00            | 722.37            | 67.80         |
| <b>Nett Amount (\$\$)</b>                 | <b>16,284.97</b>  | <b>5,243.00</b>   | <b>11,041.97</b>  | <b>67.80</b>  |

**INSPECTION**

Date of Assignment: 26/08/2022 Present Location: Automobile Integrated Management Pte Ltd (HQ)  
 Automobile Integrated Management Pte Ltd (HQ)  
 Date Inspected: 26/08/2022 Inspected At: 23 Kaki Bukit Ave 4 #04-01, Kaki Bukit (South Wing)  
 Singapore 415933  
 Estimated Period of Repair: 4.0 days

**Adjuster:** MARCUS CHUA**Manager:** CELINE FONG

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

## REPAIR DETAILS

### Reference

**Part Source:** MRM-SG Version: 1.0 (Last Synchronised: 15 Sep 2022)

**Parts:** M1-SUV SUBARU FORESTER 2.0 I-S EYESIGHT AWD CVT SR (A) (Catalogue:Merimen Singapore 1.0)

**Labour:** Repairer's (Price-denominated Standard List)

**Print Code:** (Unsubmitted, no print-code for SMM7014S)

**Validity:** These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page

**Further Info:** Items/values not in reference catalogue are prefixed with an asterisk \*.

### Recommended Parts

| No. | Qty | Part No. | Particulars                                        | Condition                      | Repairer's | Amount      |
|-----|-----|----------|----------------------------------------------------|--------------------------------|------------|-------------|
| 1   | 1   |          | <b>*HEADLAMP LH</b><br>(WCP)                       | Cracked                        | 1,950.00 F | *1,950.00 F |
| 2   | 1   |          | <b>*HEADLAMP LOWER BRACKET LH</b><br>(WCP)         | Cracked                        | 55.00 F    | *55.00 F    |
| 3   | 1   |          | <b>*FRONT FENDER LH</b><br>(WCP)                   | Repair                         | 290.00 F   | *- F        |
| 4   | 1   |          | <b>*FRONT FENDER ARCH GARNISH LH</b><br>(CUT)(WCP) | Not Consistent With The Impact | 155.00 F   | *- F        |
| 5   | 1   |          | <b>*FRONT FENDER INNER COWLING LH</b><br>(WCP)     | Deformed                       | 145.00 F   | *145.00 F   |
| 6   | 1   |          | <b>*FRONT DOOR LH</b><br>(WCP)                     | Repair                         | 680.00 F   | *- F        |
| 7   | 1   |          | <b>*FRONT DOOR INNERTRIM LH</b><br>(WCP)           | Not Necessary                  | 450.00 F   | *- F        |
| 8   | 2   |          | <b>*FRONT DOOR HINGES LH x 2</b><br>(WCP)          | Not Necessary                  | 130.00 F   | *- F        |
| 9   | 1   |          | <b>*FRONT DOOR CHECKER LH</b><br>(WCP)             | Not Necessary                  | 45.00 F    | *- F        |
| 10  | 1   |          | <b>*FRONT DOOR OUTER PANEL LH</b><br>(WCP)         | Not Necessary                  | 420.00 F   | *- F        |
| 11  | 1   |          | <b>*FRONT RIM LH</b><br>(WCP)                      | Warped                         | 680.00 F   | *680.00 F   |
| 12  | 1   |          | <b>*FRONT KNUCKLE ARM LH</b><br>(WCP)              | Not Necessary                  | 250.00 F   | *- F        |
| 13  | 1   |          | <b>*FRONT KNUCKLE ARM LH</b><br>(WCP)              | Not Necessary                  | 380.00 F   | *- F        |
| 14  | 1   |          | <b>*FRONT WHEEL HUB BEARING LH</b><br>(WCP)        | Not Necessary                  | 190.00 F   | *- F        |
| 15  | 1   |          | <b>*FRONT ABSORBER LH</b><br>(WCP)                 | Not Necessary                  | 295.00 F   | *- F        |
| 16  | 1   |          | <b>*FRONT BUMPER</b><br>(WCP)                      | Distorted                      | 420.00 F   | *420.00 F   |
| 17  | 1   |          | <b>*FRONT BUMPER RETAINER LH</b><br>(WCP)          | Cracked                        | 38.00 F    | *38.00 F    |
| 18  | 1   |          | <b>*FRONT FOGLAMP LH</b><br>(WCP)                  | Cracked                        | 270.00 F   | *270.00 F   |
| 19  | 1   |          | <b>*FRONT FOGLAMP COVER LH</b><br>(WCP)            | Scratched                      | 120.00 F   | *120.00 F   |
| 20  | 1   |          | <b>*FRONT BUMPER WASHER NOZZLE</b><br>(WCP)        | Cracked                        | 195.00 F   | *195.00 F   |
| 21  | 1   |          | <b>*FRONT BUMPER WASHER NOZZLE COVER</b><br>(WCP)  | Missing                        | 65.00 F    | *65.00 F    |
| 22  | 1   |          | <b>*FRONT WIPER TANK</b><br>(WCP)                  | Deformed                       | 90.00 F    | *90.00 F    |
| 23  | 1   |          | <b>*FRONT ENGINE UNDERCOVER</b><br>(WCP)           | Not Necessary                  | 165.00 F   | *- F        |
| 24  | 1   |          | <b>*FRONT BUMPER SPONGE</b><br>(WCP)               | Torn                           | 90.00 F    | *90.00 F    |
| 25  | 1   |          | <b>*FRONT BUMPER REINFORCEMENT</b><br>(WCP)        | Bent                           | 280.00 F   | *280.00 F   |
| 26  | 1   |          | <b>*FRONT BONNET</b><br>(WCP)                      | Repair                         | 750.00 F   | *- F        |
| 27  | 1   |          | <b>*FRONT BONNET CHROME GARNISH</b><br>(WCP)       | Not Necessary                  | 420.00 F   | *- F        |

Report was unsubmitted during this print-out.

F=Franchise part.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

| No                         | Qty | Particulars                                                     | Repairer's    | Amount       |
|----------------------------|-----|-----------------------------------------------------------------|---------------|--------------|
| <b>Miscellaneous Items</b> |     |                                                                 |               |              |
| 1                          | 1   | <b>FRONT BUMPER CLIPS</b><br>(1SET)(NECESSARY)                  | 30.00         | 30.00        |
| 2                          | 1   | <b>FRONT DOOR INNERTRIM CLIPS</b><br>(1SET)(NOT NECESSARY)      | 30.00         | 0.00         |
| 3                          | 1   | <b>FRONT FENDER INNERCOWLING CLIPS</b><br>(1SET)(NOT NECESSARY) | 30.00         | 0.00         |
| 4                          | 1   | <b>FRONT GRILLE CLIPS</b><br>(1SET)(NOT NECESSARY)              | 30.00         | 0.00         |
| 5                          | 1   | <b>FRONT NUMBER PLATE WITH CASING</b><br>(1SET)(NOT NECESSARY)  | 50.00         | 0.00         |
| <b>Sub Total (\$\$)</b>    |     |                                                                 | <b>170.00</b> | <b>30.00</b> |

Recommended Labour

| No                              | Particulars                                                                      | Lab.Type | Repairer's      | Amount          |
|---------------------------------|----------------------------------------------------------------------------------|----------|-----------------|-----------------|
| <b>Labour Items</b>             |                                                                                  |          |                 |                 |
| 1                               | <b>TO RENEW DAMAGED PARTS, REPLACE,BEAT ,WELD , REALIGN AND ALIGNE ALL PARTS</b> | New      | 1,600.00        | 550.00          |
| 2                               | <b>TO RESPRAY AFFECTED AREAS</b>                                                 | New      | 1,600.00        | 700.00          |
| 3                               | <b>TO TUFFCOAT AFFECTED AREA</b>                                                 | New      | 200.00          | 0.00            |
| 4                               | <b>WIRING CHECKS ON FRONT HEADLAMP AND FOCUSING</b>                              | New      | 150.00          | 20.00           |
| <b>Gross Labour Cost (\$\$)</b> |                                                                                  |          | <b>3,550.00</b> | <b>1,270.00</b> |

Report was unsubmitted during this print-out.

< END OF ESTIMATES >