



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

TAX INVOICE

LONPAC INSURANCE BHD

300 BEACH ROAD
#17-04/07 THE CONCOURSE
SINGAPORE 199555

INV No. AC2205826

INV Date 20/09/2022

Reference CC4/LPC22008274/Rpa3q2

Code LPC2

PROFESSIONAL SERVICE FEE

Vehicle No. SMT 2308R

Insured Veh. XD 5101D

Claim No. 21/22/22/VC05/026175

Policy No. Z22VC05013154

Accident Date 17/08/2022

Inspection Date 23/08/2022

Description	Total
Survey Inspection	350.00
Digital Photographs	
Transportation	
Subtotal	350.00
GST (7%)	24.50
Grand Total	374.50

We shall be glad if you could forward the payment at your early convenience.

Cheque should be crossed and made payable to **'LKK Auto Consultants Pte Ltd'**

LKK Auto Consultants Pte Ltd

LKM



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
LONPAC INSURANCE BHD 300 BEACH ROAD #17-04/07 THE CONCOURSESINGAPORE 199555			Ref: CC4/LPC22008274/Rpa3q2 Date: 20/09/2022 Code: LPC2	
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	XD 5101D	Veh. Inspected	SMT 2308R	
Policy No.	Z22VC05013154	Coverage (\$)	0.00	
Claim No.	21/22/22/VC05/026175	Excess (\$)	0.00	
Assign From	GERALD	Assign Date	23/08/2022	
2. Vehicle Particulars & Condition				
Make & Model	HYUNDAI AD AVANTE 1.6 GLS (A)	c.c	1591	
Engine No.	HIDDEN	Year of Reg.	2020	
Chassis No.	KMHD841CMLU035107	Colour	GREY	
Odometer	48002 KM	Steering	IN ORDER	
Brakes	IN ORDER	Modification	SPORTS RIM	
General	FAIR			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	195/65 R15	YOKOHAMA	6 mm	
L/H Front Tyre	195/65 R15	YOKOHAMA	6 mm	
R/H Rear Tyre	195/65 R15	YOKOHAMA	6 mm	
L/H Rear Tyre	195/65 R15	YOKOHAMA	6 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE O/S FRONT PORTION. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	17/08/2022	Inspection Date	23/08/2022	
Survey held at	HIN LUNG WORKSHOP BLK 1008 BUKIT MERAH LANE 3 #01-20 SINGAPORE 159722			
5a. Remarks				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:			6 Working Days	



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SMT 2308R

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<u>REPLACEMENT OF PARTS</u>			
1	FRONT BUMPER	TORN	475.00	475.00
1	MOULDING -FRONT BUMPER ,LH	NOT NECESSARY	116.00	-
1	MOULDING -FRONT BUMPER ,RH	NOT NECESSARY	116.00	-
1	LIP ASSY -FRONT BUMPER	CRACKED	64.00	64.00
1	CAP ASSY -FRONT BUMPER	NOT NECESSARY	18.00	-
10	BUMPER CLIPS @\$4.90	NECESSARY	49.00	49.00
1	BRACKET -FRONT BUMPER SIDE LH	NOT NECESSARY	15.00	-
1	BRACKET -FRONT BUMPER SIDE RH	CUT	15.00	15.00
1	BRACKET ASSY -FRONT BUMPER UPPER SUPPORT ,LH	NOT NECESSARY	15.00	-
1	BRACKET ASSY -FRONT BUMPER UPPER SUPPORT ,RH	NOT NECESSARY	15.00	-
1	DUCT ASSY -AIR CURTAIN ,LH	NOT NECESSARY	28.00	-
1	DUCT ASSY -AIR CURTAIN ,RH	NOT NECESSARY	28.00	-
1	ABSORBER -FRONT BUMPER ENERGY	CRACKED	111.00	111.00
1	GRILLE ASSY -RADIATOR	NOT NECESSARY	530.00	-
1	COVER ASSY -RADIATOR GRILLE UPPER	CUT	85.00	85.00
1	STRIP -FRONT BUMPER	NECESSARY	26.00	26.00
1	GRILLE -FRONT BUMPER SIDE ,LH	NOT NECESSARY	34.00	-
1	GRILLE -FRONT BUMPER SIDE ,RH	NOT NECESSARY	34.00	-
10	CLIP @\$4.90	NECESSARY	49.00	49.00
1	MOULDING -FRONT BUMPER LICENSE PLATE	NOT NECESSARY	22.00	-
1	LAMP ASSY -FRONT TURN SIGNAL ,LH	NOT NECESSARY	165.00	-
1	LAMP ASSY -FRONT TURN SIGNAL ,RH	SCRATCHED	165.00	165.00
1	PANEL ASSY -UNDER COVER	NOT NECESSARY	134.00	-
10	CLIP @\$4.90	NOT NECESSARY	49.00	-
1	PANEL ASSY -HOOD	NOT NECESSARY	1,911.00	-
1	PANEL ASSY -FENDER ,RH	BENT	1,227.00	1,227.00
1	LAMP ASSY -SIDE RETAINER RH	NOT NECESSARY	28.00	-
1	PANEL ASSY -FRONT DOOR ,RH	CUT	1,832.00	1,832.00
1	WEATHERSTRIP ASSY -FRONT DOOR SIDE RH	NOT NECESSARY	115.00	-
1	WEATHERSTRIP ASSY -FRONT DOOR BELT OUTSIDE ,RH	NOT NECESSARY	53.00	-

Report Ref No. CC4/LPC22008274/Rpa3q2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	BLACK TAPE -FRONT FOOR FRAME UPPER, RH	NECESSARY	23.00	23.00
1	BLACK TAPE-FRONT DOOR REAR ,RH	NOT NECESSARY	23.00	-
1	GUARD ASSY -FRONT WHEEL ,LH	NOT NECESSARY	86.00	-
1	GUARD ASSY -FRONT WHEEL ,RH	NOT NECESSARY	86.00	-
20	CLIP @\$4.90	NOT NECESSARY	98.00	-
10	RETAINER @\$4.90	NOT NECESSARY	49.00	-
1	FRONT RIM RH	SCRATCHED	697.00	697.00
1	FRONT BUMPER PLATE WITH CASING	SCRATCHED	35.00	35.00
	LESS 20% DISCOUNT		-	-970.60
			8,621.00	3,882.40
	LABOUR			
	REPLACE NEW PARTS ,REMOVE /REFIT ALL ATTACHMENT PARTS TO FACILITATE REPAIR.		1,000.00	600.00
	SPRAY PAINT ON THE EFFECTED AREAS WITH 2K PAINT.		1,000.00	600.00
	CHECK WIRING AND PROPER FUNCTIONING.		100.00	30.00
			2,100.00	1,230.00
GRAND TOTAL			10,721.00	5,112.40
RECOMMENDED COST OF REPAIRS				5,112.40

Report Ref No. CC4/LPC22008274/Rpa3q2

MOHAMMED RASUL BIN MOHD YUNUS

Automotive Assessor

HO LEONG CHUAN

Automotive Assessor

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

PHOTOGRAPHS FOR VEHICLE NO. SMT 2308R

INSPECTION





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

