

HIN LUNG WORKSHOP

Blk 1008 Bukit Merah Lane 3 #01-20, S'pore 159722. Tel: 68583000 Fax: 64760075
Website: www.hinlung.com.sg GST Regn. No: M2-0065859-X

Your Ref:
Our Ref : 0765/08/22
M/s : LONPAC INSURANCE BHD
300, BEACH ROAD #17-04/06 THE CONCOURSE
SINGAPORE 199555

Page: 1
Date: 22/08/2022

Attn : MOTOR CLAIM DEPARTMENT

Dear Sir/Madam,

ACCIDENT REPAIR ON : SMT2308R - AVANTE 1.6 GLS (A) 2020
INSURED : BOLT CAR LEASING PTE LTD
DATE OF ACCIDENT : 17/08/2022
YOUR INSURED VEH NO: XD5101D

APPENDED BELOW ARE THE ESTIMATED COST OF REPAIR & PARTS TO BE REPLACED:-

			S\$	S\$	S\$
REPLACEMENT OF PARTS					
1	FRONT BUMPER <i>turn</i>	1 @	475.00	475.00	
2	MOULDING - FRONT BUMPER, LH <i>Xnn</i>	1 @	116.00	116.00	
3	MOULDING - FRONT BUMPER, RH <i>Xnn</i>	1 @	116.00	116.00	
4	LIP ASSY - FRONT BUMPER <i>ca</i>	1 @	64.00	64.00	
5	CAP ASSY - FRONT BUMPER <i>Xnn</i>	1 @	18.00	18.00	
6	BUMPER CLIPS <i>ca</i>	10 @	4.90	49.00	
7	BRACKET - FRONT BUMPER SIDE LH <i>Xnn</i>	1 @	15.00	15.00	
8	BRACKET - FRONT BUMPER SIDE RH <i>cut</i>	1 @	15.00	15.00	
9	BRACKET ASSY - FRONT BUMPER UPPER SUPPORT, LH <i>Xnn</i>	1 @	15.00	15.00	
10	BRACKET ASSY - FRONT BUMPER UPPER SUPPORT, RH <i>Xnn</i>	1 @	15.00	15.00	
11	DUCT ASSY - AIR CURTAIN, LH <i>Xnn</i>	1 @	28.00	28.00	
12	DUCT ASSY - AIR CURTAIN, RH <i>Xnn</i>	1 @	28.00	28.00	
13	ABSORBER - FRONT BUMPER ENERGY <i>ca</i>	1 @	111.00	111.00	
14	GRILLE ASSY - RADIATOR <i>Xnn</i>	1 @	530.00	530.00	
15	COVER ASSY - RADIATOR GRILLE UPPER <i>cut</i>	1 @	85.00	85.00	
16	STRIP - FRONT BUMPER <i>ca</i>	1 @	26.00	26.00	
17	GRILLE - FRONT BUMPER SIDE, LH <i>Xnn</i>	1 @	34.00	34.00	
18	GRILLE - FRONT BUMPER SIDE, RH <i>Xnn</i>	1 @	34.00	34.00	
19	CLIP <i>ca</i>	10 @	4.90	49.00	
20	MOULDING - FRONT BUMPER LICENSE PLATE <i>Xnn</i>	1 @	22.00	22.00	
21	LAMP ASSY - FRONT TURN SIGNAL, LH <i>Xnn</i>	1 @	165.00	165.00	
22	LAMP ASSY - FRONT TURN SIGNAL, RH <i>sc</i>	1 @	165.00	165.00	
23	PANEL ASSY - UNDER COVER <i>Xnn</i>	1 @	134.00	134.00	
24	CLIP <i>Xnn</i>	10 @	4.90	49.00	
25	PANEL ASSY - HOOD <i>Xnn</i>	1 @	1,911.00	1,911.00	
26	PANEL ASSY - FENDER, RH <i>LI</i>	1 @	1,227.00	1,227.00	
27	LAMP ASSY - SIDE RETAINER, RH <i>Xnn</i>	1 @	28.00	28.00	
28	PANEL ASSY - FRONT DOOR, RH <i>cut</i>	1 @	1,832.00	1,832.00	
29	WEATHERSTRIP ASSY - FRONT DOOR SIDE, <i>Xnn</i>	1 @	115.00	115.00	

HIN LUNG WORKSHOP

Blk 1008 Bukit Merah Lane 3 #01-20, S'pore 159722. Tel: 68583000 Fax: 64760075
Website: www.hinlung.com.sg GST Regn. No: M2-0065859-X

Your Ref:
Our Ref : 0765/08/22

Page: 2
Date: 22/08/2022

APPENDED BELOW ARE THE ESTIMATED COST OF REPAIR & PARTS TO BE REPLACED:-

			S\$	S\$	S\$
	RH				
30	WEATHERSTRIP ASSY - FRONT DOOR BELT	1 @	53.00	53.00	
	OUTSIDE, RH <i>Xⁿⁿ</i>				
31	BLACK TAPE - FRONT FOOR FRAME UPPER,	1 @	23.00	23.00	
	RH <i>nn</i>				
32	BLACK TAPE - FRONT DOOR REAR, RH <i>Xⁿⁿ</i>	1 @	23.00	23.00	
33	GUARD ASSY - FRONT WHEEL, LH <i>Xⁿⁿ</i>	1 @	86.00	86.00	
34	GUARD ASST - FRONT WHEEL, RH <i>Xⁿⁿ</i>	1 @	86.00	86.00	
35	CLIP <i>Xⁿⁿ</i>	20 @	4.90	98.00	
36	RETAINER <i>Xⁿⁿ</i>	10 @	4.90	49.00	
	*SPECIAL NETT				
37	FRONT RIM RH <i>sur / price check?</i>	1 @	697.00	697.00	
38	FRONT BUMPER PLATE WITH CASING <i>sur</i>	1 @	35.00	35.00	

LABOUR CHARGES

- 1 REPLACE NEW PARTS, REMOVE / REFIT ALL
- 1 ATTACHMENT PARTS TO FACILITATE REPAIR
- 1
- 2 SPRAY PAINT ON THE EFFECTED AREAS
- 2 WITH 2K PAINT
- 2
- 3 CHECK WIRING AND PROPER FUNCTIONING

~~1,000.00~~ 600

~~1,000.00~~ 600

~~100.00~~ 30

Nett Total Before GST

10,721.00

Yours faithfully,

[Signature]
(Workshop Manager)

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

Rashid
Hp 90010068
6 days
P/P
23/08/22 @ 1420
Resurvey before paint