

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS/CTI22008278/RCY3Q2**Date:** 30/01/2023**REFERENCE**

Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd.	Policy No:	DMCVSNW00073572201		
Claimant Vehicle No :	SJH7723R	Insured Vehicle No :	YP8273X		
Date of Loss:	24/08/2022	Nature of Claim:	TP	Claim No:	SNM22D206000/C02/CHNGPW

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SJH7723R		Engine No:	R18A1772068
Make & Model:	HONDA STREAM, 1.8 X (A)		Chassis No:	RN61064830
Reg. Date:	22/08/2008 (Man. Year: 2008)		Odometer:	362753 km
Colour:	Grey			
Engine Capacity:	1799 cc			
Market Value/New Car Price:	N/A			
Sum Insured (\$\$):	Market Value/New Car Price			

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	205/65 R15	Rear Tyre Size:	205/65 R15
Front Left Side:	Hankook 6 mm	Rear Left Side:	Hankook 6 mm
Front Right Side:	Hankook 6 mm	Rear Right Side:	Hankook 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	3,244.40	2,724.40	520.00	16.03
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,390.00	1,540.00	850.00	35.56
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (\$\$)	5,634.40	4,264.40	1,370.00	24.31
Approved Total (Overridden) (\$\$)		3,400.00		
(\$\$)	5,634.40	3,400.00	2,234.40	39.66
+ GST 8.00/8.00% (\$\$)	450.75	272.00	178.75	39.66
Nett Amount (\$\$)	6,085.15	3,672.00	2,413.15	39.66

INSPECTION

Date of Assignment:	25/08/2022	
Date Inspected:	26/08/2022	Inspected At: Wah Hong Motors & Credit Pte Ltd (HQ) 38 Toh Guan Road East, #01-57, Enterprise Hub Singapore 608581
Estimated Period of Repair:	5.0 days	

Adjuster: MOHD RASUL**Manager:** CELINE FONG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference		
Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 30 Jan 2023)
Parts:	M1-MPV	HONDA STREAM 1.8 X (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SJH7723R)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*SIDE MIRROR LH	Scratched	587.00 FL	*587.00 FL
2	1		*FRONT DOOR LH	Buckled	984.00 FL	*984.00 FL
3	1		*FRONT DOOR LOCK LH	Bent	237.00 FL	*237.00 FL
4	1		*FRONT DOOR WINDOW REGULATOR LH	Not Necessary	444.00 FL	*- FL
5	1		*FRONT DOOR TAPE	Necessary	49.00 FL	*49.00 FL
6	1		*FRONT DOOR OUTER HANDLE LH	Scratched	133.00 FL	*133.00 FL
7	1		*REAR DOOR LH	Buckled	958.00 FL	*958.00 FL
8	1		*REAR DOOR HINGE UPPER LH	Bent	45.00 FL	*45.00 FL
9	1		*REAR DOOR HINGE LOWER LH	Not Necessary	45.00 FL	*- FL
10	1		*REAR DOOR CHECKER LH	Not Necessary	49.00 FL	*- FL
11	1		*REAR DOOR RUN CHANNEL LH	Not Necessary	51.00 FL	*- FL
12	1		*REAR DOOR VERTICAL GARNISH	Not Necessary	36.00 FL	*- FL
13	1		*REAR DOOR TAPE	Necessary	42.00 FL	*42.00 FL
14	1		*REAR FENDER (LH) (NPA)	Not Necessary	0.00 FL	*- FL
15	1		*B PILLAR (NPA)	Not Necessary	0.00 FL	*- FL
16	1		*ROCKER PANEL (NPA)	Not Necessary	0.00 FL	*- FL
17	1		*RAIN SHIELD TAPE	Necessary	50.00 FS	*30.00 FS
18	1		*REAR DOOR OUTER HANDLE LH	Scratched	133.00 FL	*133.00 FL
19	1		*REAR DOOR GLASS WINDOW SLIDING BRACKET LH	Bent	200.00 FL	*200.00 FL

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (S\$)	4,043.00	3,398.00
- List Item Discount on L Items 20.00/20.00% (S\$)	798.60	673.60
Total Parts (S\$)	3,244.40	2,724.40

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO REMOVE THE AFFECTED PARTS & FITTINGS TO COMMENCE REPAIRS ,PANEL BEAT & RESHAPE THE AFFECTED AREAS AND REPLACE THE DAMAGED PARTS AND COMPONENTS	New	1,000.00	500.00
2	TO SUPPLY PAINT MATERIALS ,EXPANDABLE ITEMS & PUTTY ,RESPRAY PAINT ON PARTS REPLACED & REPAIRED	New	1,000.00	800.00
3	TO REMOVE AND REPAIR /REFIX WIRING SYSTEM AT ACCIDENT DAMAGED AREA AND CHECK FOR ALL ELECTRICAL PROPER FUNCTION	New	90.00	60.00
4	TO PERFORM ANTI-RUST TREATMENT ON AFFECTED AREAS	New	60.00	60.00
5	TO REMOVE AND REFIT /REPLACE FRONT DOOR LH FITTING ,TRIMMINGS ,GARNISH ,WINDOW GLASS AND LOCK MECHANISM	New	120.00	60.00
6	TO REMOVE AND REFIT /REPLACE REAR DOOR LH FITTING ,TRIMMINGS ,GARNISH ,WINDOW GLASS AND LOCK MECHANISM	New	120.00	60.00
Gross Labour Cost (S\$)			2,390.00	1,540.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >