

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS/MSG22008285/DVY3E2**Date:** 02/12/2022REFERENCE

Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd.	Policy No:	1001739357
Claimant Vehicle No :	SNF5940G	Insured Vehicle No :	SMY8393C
Date of Loss:	25/08/2022	Nature of Claim:	TP
		Claim No:	283180

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SNF5940G		
Make & Model:	TOYOTA SIENTA 7-SEATER, 1.5 G CVT (A)	Engine No:	2NR1141973
Reg. Date:	08/06/2022 (Man. Year: 2019)	Chassis No:	NSP1707207678
Colour:	Green	Odometer:	3538 km
Engine Capacity:	1496 cc		
Market Value/New Car Price:	N/A		
Sum Insured (\$\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	185/60 R15	Rear Tyre Size:	185/60 R15
Front Left Side:	Toyo 5 mm	Rear Left Side:	Toyo 5 mm
Front Right Side:	Toyo 5 mm	Rear Right Side:	Toyo 5 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	21,289.44	2,394.82	18,894.62	88.75
Miscellaneous Items	0.00	0.00	0.00	
Labour	7,400.00	1,520.00	5,880.00	79.46
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (\$\$)	28,689.44	3,914.82	24,774.62	86.35
Approved Total (Overridden) (\$\$)		3,100.00		
(\$\$)	28,689.44	3,100.00	25,589.44	89.19
+ GST 7.00/7.00% (\$\$)	2,008.26	217.00	1,791.26	89.19
Nett Amount (\$\$)	30,697.70	3,317.00	27,380.70	89.19

INSPECTION

Date of Assignment: 26/08/2022

Date Inspected: 31/08/2022 Inspected At:

JWG International Pte Ltd (HQ)
 Blk 10, Ang Mo Kio Ind Park 2A,, #03-08 AMK
 AutoPoint
 Singapore 568047

Estimated Period of Repair: 3.0 days

Adjuster: BRYAN TANI**Manager:** VERON CHEN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source: MRM-SG Version: 1.0 (Last Synchronised: 22 Nov 2022)

Parts: M1-MPV TOYOTA SIENTA 7-SEATER 1.5 G CVT (A) (Catalogue:Merimen Singapore 1.0)

Labour: Repairer's (Price-denominated Standard List)

Print Code: (Unsubmitted, no print-code for SNF5940G)

Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*TAILGATE	Dented	1,890.70 FL	*1,445.10 FL
2	1		*TAILGATE WINDSCREEN MOULDING	Necessary	287.90 FL	*130.20 FL
3	1		*TAILGATE WIPER MOTOR	Not Necessary	498.01 FL	*- FL
4	1		*TAILGATE WIPER ARM	Not Necessary	179.80 FL	*- FL
5	1		*TAILGATE CENTER GARNISH	Not Necessary	310.92 FL	*- FL
6	2		*TAILGATE NO. PLATE LAMP LH / RH	Not Necessary	184.20 FL	*- FL
7	1		*TAILGATE REVERSE CAMERA	Not Necessary	782.90 FL	*- FL
8	1		*TAILGATE SWITCH	Not Necessary	285.71 FL	*- FL
9	2		*TAILGATE LAMP LH / RH	Not Necessary	998.40 FL	*- FL
10	1		*TAILGATE LOGO	Necessary	79.80 FL	*79.80 FL
11	1		*TAILGATE LOCK	Damaged	321.10 FL	*265.00 FL
12	1		*TAILGATE INNER TRIM BOARD	Not Necessary	879.90 FL	*- FL
13	1		*TAILGATE WEATHER STRIP	Not Necessary	311.20 FL	*- FL
14	1		*TAILGATE STRIKER LOCK	Not Necessary	59.80 FL	*- FL
15	2		*TAIL LAMP LH / RH	Not Necessary	1,203.60 FL	*- FL
16	2		*TAIL LAMP PANEL LH / RH	Not Necessary	1,102.00 FL	*- FL
17	1		*REAR BUMPER	Distorted / Mtg Broken	879.20 FL	*678.10 FL
18	1		*REAR BUMPER SIDE COVER LH / RH	Not Necessary	822.00 FL	*- FL
19	2		*REAR BUMPER SIDE RETAINER LH / RH	Not Necessary	109.80 FL	*- FL
20	1		*REAR BUMPER CENTER GARNISH	Distorted	398.80 FL	*325.40 FL
21	2		*REAR BUMPER SIDE GARNISH LH / RH	Not Necessary	803.80 FL	*- FL
22	2		*REAR BUMPER REFLECTOR LH / RH	Not Necessary	178.20 FL	*- FL
23	1		*REAR BUMPER TOWING COVER	Not Necessary	82.00 FL	*- FL
24	1		*REAR KEYLESS SENSOR	Mtg Broken	198.40 FL	*189.50 FL
25	1		*REAR KEYLESS BUZZER	Not Necessary	230.90 FL	*- FL
26	1		*REAR END PANEL	Repair	1,009.80 FL	*- FL
27	1		*REAR END PANEL SIDE LH / RH	Not Necessary	963.00 FL	*- FL
28	1		*REAR END PANEL TOP GARNISH	Not Necessary	349.10 FL	*- FL
29	1		*SPARE WHEEL PANEL	Not Necessary	1,689.02 FL	*- FL
30	1		*SPARE WHEEL PANEL TOP BOARD	Not Necessary	590.52 FL	*- FL
31	1		*SPARE WHEEL PANEL TOOL BOX	Not Necessary	311.92 FL	*- FL
32	2		*SPARE WHEEL QUARTER PANEL LH / RH	Not Necessary	1,019.60 FL	*- FL
33	2		*REAR FENDER LH / RH	Not Necessary	3,940.20 FL	*- FL
34	2		*REAR FENDER INNER TRIM LH / RH	Not Necessary	2,005.70 FL	*- FL
35	1		*REAR EXHAUST PIPE	Not Necessary	1,750.30 FL	*- FL
36	1		*REAR EXHAUST MOUNTING	Not Necessary	101.90 FL	*- FL
37	1		*REAR EXHAUST HEAT SHIELD	Not Necessary	215.82 FL	*- FL
38	1		*TAILGATE WINDSCREEN SEALANT	Necessary	80.00 FS	*40.00 FS
39	1		*TAILGATE WINDSCREEN DAMPING SEAL	Not Necessary	30.00 FS	*- FS
40	1		*TAILGATE WINDSCREEN INNER SEAL	Not Necessary	50.00 FS	*- FS
41	1		*TAILGATE LAMP CLIPS	Not Necessary	50.00 FS	*- FS
42	1		*TAILGATE INNER TRIM CLIPS	Not Necessary	50.00 FS	*- FS

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
43	1		*TAILGATE CENTER GARNISH CLIPS	Not Necessary	50.00 FS	*- FS
44	1		*TAIL LAMP CLIPS	Not Necessary	50.00 FS	*- FS
45	1		*REAR BUMPER CLIPS	Necessary	50.00 FS	*20.00 FS
46	1		*REAR END PANEL SEALANT	Not Necessary	80.00 FS	*- FS
47	1		*REAR END PANEL TOP GARNISH CLIPS	Not Necessary	50.00 FS	*- FS
48	1		*REAR FENDER SEALANT	Not Necessary	80.00 FS	*- FS
49	1		*REAR NO. PLATE & CASING	Not Necessary	100.00 FS	*- FS
50	1		*REVERSE SENSOR	Not Necessary	300.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (S\$)	28,045.92	3,173.10
- List Item Discount on L Items 25.00/25.00% (S\$)	6,756.48	778.28
Total Parts (S\$)	21,289.44	2,394.82

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO REMOVE ALL INTERIOR UPHOLSTERLY ITEMS TO FACILIATE REPAIRS	New	400.00	0.00
2	TO REMOVE & PANEL BEAT ALL DAMAGED ABOVE PARTS & PANELS	New	2,400.00	700.00
3	TO RESPRAY NEW PAINTWORK FOR ALL DAMAGED AREAS	New	2,400.00	600.00
4	TO TUFF COAT DAMAGED AREAS	New	200.00	40.00
5	TO RNR TAILGATE MECHANISM TO FACILITATE REPAIRS	New	200.00	60.00
6	TO RNR TAILGATE WINDSCREEN TO FACILITATE REPAIRS	New	400.00	120.00
7	TO RNR EXHAUST & ATTACHMENT PARTS TO FACILITATE REPAIRS	New	200.00	0.00
8	TO CHECK & RE-FIX ALL ELECTRICAL WIRINGS	New	200.00	0.00
9	TO COMPUTERIZE DIAGNOSE FAULT CODES & CONTROL UNITS. RESET ALL MEMORIES TO FACTORY DEFAULT SETTINGS	New	1,000.00	0.00
Gross Labour Cost (\$\$)			7,400.00	1,520.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >