

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com; cs-a@lkkauto.com; admin-a@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CC4/AIS22008291/APA3Q2
Date: 18/05/2023**REFERENCE**

Handling Insurer:	Allianz Insurance Singapore Pte. Ltd.	Policy No:	SP0001040940
Claimant Vehicle No :	SMT9841X	Insured Vehicle No :	SLD1074S
Date of Loss:	18/08/2022	Nature of Claim:	TP
		Claim No:	202222006238

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SMT9841X	Engine No:	27091031937423
Make & Model:	MERCEDES-BENZ GLA180, 1.6 (A)	Chassis No:	WDC1569422J680243
Reg. Date:	27/07/2020 (Man. Year: 2019)	Odometer:	23114 km
Colour:	Black		
Engine Capacity:	1595 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	235/50 R18	Rear Tyre Size:	235/50 R18
Front Left Side:	Falken 6 mm	Rear Left Side:	Falken 6 mm
Front Right Side:	Falken 6 mm	Rear Right Side:	Falken 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	12,166.11	8,109.04	4,057.07	33.35
Miscellaneous Items	0.00	0.00	0.00	
Labour	4,550.00	1,300.00	3,250.00	71.43
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	16,716.11	9,409.04	7,307.07	43.71
Approved Total (Overridden) (S\$)		7,500.00		
(S\$)	16,716.11	7,500.00	9,216.11	55.13
+ GST 8.00/8.00% (S\$)	1,337.29	600.00	737.29	55.13
Nett Amount (S\$)	18,053.40	8,100.00	9,953.40	55.13
+ Loss of Use (7.0 x S\$60.00/day) (S\$)		420.00		
+ Doc/Search Fee (S\$)		7.45		
Nett Liability (S\$)		8,527.45		

INSPECTION

Date of Assignment:	23/08/2022	MG Solution Pte Ltd (HQ)
Date Inspected:	23/08/2022 Inspected At:	23 Kaki Bukit Avenue 4 #02-03B, VICOM Inspection Centre Singapore 415933
Estimated Period of Repair:	5.0 days	

Adjuster: ADRIAN LING**Manager:** CHEW HSIAO TONG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS**Reference**

Part Source: MRM-SG	Version: 1.0 (Last Synchronised: 18 May 2023)
Parts: M1-SUV	MERCEDES-BENZ GLA180 1.6 (A) (Catalogue:Merimen Singapore 1.0)
Labour: Repairer's	(Price-denominated Standard List)
Print Code: (Unsubmitted, no print-code for SMT9841X)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*TAILGATE	Dented	2,055.60 FL	*2,055.60 FL
2	1		*TAILGATE LOGO	Necessary	92.50 FL	*92.50 FL
3	1		*TAILGATE EMBLEM GLAI	Necessary	66.30 FL	*66.30 FL
4	1		*TAILGATE EMBLEM 180	Necessary	54.80 FL	*54.80 FL
5	1		*TAILGATE LAMP	Cut	560.50 FL	*560.50 FL
6	1		*TAILGATE WINDSCREEN MOULDING	Necessary	182.20 FL	*182.20 FL
7	1		*REAR BUMPER	Deformed	1,588.20 FL	*1,386.00 FL
8	1		*REAR BUMPER SIDE RETAINER	N/S Damaged	280.40 FL	*140.20 FL
9	1		*REAR BUMPER CHROME	Cracked	266.30 FL	*266.30 FL
10	1		*REAR BUMPER INNER GARNISH	Cracked	311.20 FL	*311.20 FL
11	1		*REAR BUMPER DIFFUSER	Deformed	820.00 FL	*820.00 FL
12	1		*REAR BUMPER LOWER LID	Deformed	1,055.20 FL	*595.00 FL
13	1		*REAR BUMPER REINFORCEMENT	Dented	710.00 FL	*645.00 FL
14	1		*REAR BUMPER SIDE BRACKET	N/S Damaged	260.00 FL	*130.00 FL
15	1		*TAILLAMP	Cracked	833.50 FL	*833.50 FL
16	1		*REAR FENDER WHEEL ARCH LH	Cracked	280.50 FL	*280.50 FL
17	1		*REAR EXHAUST PIPE	Not Necessary	1,822.60 FL	*- FL
18	1		*REAR EXHAUST PIPE INSULATOR	Not Necessary	222.30 FL	*- FL
19	1		*REAR EXHAUST PIPE CHROME LH	N/S Dented	823.00 FL	*316.00 FL
20	2		*REAR EXHAUST PIPE BRACKET	Not Necessary	511.80 FL	*- FL
21	1		*REVERSE SENSOR	N/S Damaged	641.00 FL	*250.00 FL
22	1		*REAR NUMBER PLATE	Not Necessary	50.00 FS	*- FS
23	1		*SET REAR BUMPER CLIP	Necessary	22.00 FS	*22.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (S\$)	13,509.90	9,007.60
- List Item Discount on L Items 10.00/10.00% (S\$)	1,343.79	898.56
Total Parts (S\$)	12,166.11	8,109.04

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO PANEL BEAT ,WELD ,CUT ,KNOCK ,STRAIGHTEN ,ADJUST GRAZE JOIN	New	1,400.00	500.00
2	TO PUTTY SPRAY PAINT ,POLISH ,WAX AFFECTED PARTS AND PANELS	New	1,400.00	500.00
3	TUFF COAT	New	250.00	40.00
4	WIRING CHECK	New	120.00	30.00
5	REMOVE AND REFIX CUSHION SEAT /UPHOLSTERY AND ROOF LINNING TO FACILITATE REPAIR	New	250.00	0.00
6	CONDUCT WATER LEAKAGE TEST	New	80.00	0.00
7	TO TRANSFER REAR WINDSCREEN	New	140.00	120.00
8	TRANSFER BOOTLID MECHANISM	New	120.00	60.00
9	DIAGNOSTICS REVERSE SENSOR AND DISTANCE SETTING	New	160.00	50.00
10	TO REMOVE AND REFIX REAR EXHAUST PIPE	New	280.00	0.00
11	TO CHECK DIAGNOSTICS OF VEHICLE MANAGEMENT /CONTROL UNITS ,RESET MEMORIES TO	New	350.00	0.00
Gross Labour Cost (S\$)			4,550.00	1,300.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >