

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com; cs-a@lkkauto.com; admin-a@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CC4/III22008292/GPA3Q2**Date:** 18/07/2023REFERENCE

Handling Insurer:	India International Insurance Pte Ltd	Policy No:	D22MFL0003549
Claimant Vehicle No :	SMX7895H	Insured Vehicle No :	SND766L
Date of Loss:	17/08/2022	Nature of Claim:	TP
		Claim No:	MFL2022D0004759

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SMX7895H	Engine No:	2ZR2H28980
Make & Model:	TOYOTA PRIUS, 1.8 5DR HATCHBACK (A)	Chassis No:	JTDKB3FU903092982
Reg. Date:	29/01/2021 (Man. Year: 2020)	Odometer:	144411 km
Colour:	White		
Engine Capacity:	1798 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	195/65 R15	Rear Tyre Size:	195/65 R15
Front Left Side:	Firenza 6 mm	Rear Left Side:	Firenza 6 mm
Front Right Side:	Firenza 6 mm	Rear Right Side:	Firenza 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	25,001.20	7,885.67	17,115.53	68.46
Miscellaneous Items	0.00	0.00	0.00	
Labour	5,830.00	3,000.00	2,830.00	48.54
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	30,831.20	10,885.67	19,945.53	64.69
Approved Total (Overridden) (S\$)		8,700.00		
(S\$)	30,831.20	8,700.00	22,131.20	71.78
+ GST 8.00/8.00% (S\$)	2,466.50	696.00	1,770.50	71.78
Nett Amount (S\$)	33,297.70	9,396.00	23,901.70	71.78
+ Loss of Use (9.0 x S\$100.00/day) (S\$)		900.00		
+ Doc/Search Fee (S\$)		7.45		
Nett Liability (S\$)		10,303.45		

INSPECTION

Date of Assignment:	23/08/2022	
Date Inspected:	23/08/2022 Inspected At:	My Car Consultant Pte Ltd (Jalan Lam Huat) (HQ) 60 Jalan Lam Huat, Carros Centre #05-21 Singapore 737869
Estimated Period of Repair:	9.0 days	

Adjuster: XING GUO QIANG**Manager:** CHEW HSIAO TONG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference		
Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 28 Apr 2023)
Parts:	144	TOYOTA PRIUS 1.8 5DR HATCHBACK (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SMX7895H)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*BONNET LOCK	Not Necessary	312.00 FL	*- FL
2	1		*FRONT BUMPER	Repair	798.00 FL	*- FL
3	1		*FRONT BUMPER LOWER	Not Necessary	651.00 FL	*- FL
4	1		*FRONT BUMPER LOGO	Not Necessary	68.00 FL	*- FL
5	2		*FRONT BUMPER SIDE RETAINER	Not Necessary	116.00 FL	*- FL
6	2		*FRONT BUMPER BRACKET	Not Necessary	104.00 FL	*- FL
7	1		*FRONT BUMPER SPONGE	Not Necessary	215.00 FL	*- FL
8	1		*FRONT BUMPER REINFORCEMENT	Not Necessary	412.00 FL	*- FL
9	2		*FRONT BUMPER FOGLAMP	Not Necessary	624.00 FL	*- FL
10	2		*FRONT BUMPER TOWING COVER	Not Necessary	84.00 FL	*- FL
11	1		*FRONT BUMPER LOWER GRILLE CENTRE	Not Necessary	259.00 FL	*- FL
12	1		*FRONT BUMPER UNDER COVER	Not Necessary	214.00 FL	*- FL
13	1		*FRONT GRILLE	Not Necessary	498.00 FL	*- FL
14	1		*FRONT SUPPORT PANEL	Not Necessary	898.00 FL	*- FL
15	1		*FRONT SUPPORT PANEL TOP GARNISH	Not Necessary	184.00 FL	*- FL
16	2		*HEADLAMP	Not Necessary	5,182.00 FL	*- FL
17	2		*HEADLAMP LOWER BRACKET	Not Necessary	84.00 FL	*- FL
18	1		*TAILGATE	Buckled	1,359.00 FL	*1,147.00 FL
19	1		*TAILGATE WEATHERSTRIP	Twisted	212.00 FL	*212.00 FL
20	1		*TAILGATE OUTER GARNISH	Bent	521.00 FL	*521.00 FL
21	1		*TAILGATE LOGO	Necessary	95.50 FL	*95.50 FL
22	1		*TAILGATE EMBLEM PRIUS T	Necessary	89.40 FL	*89.40 FL
23	1		*TAILGATE EMBLEM HYBRID	Necessary	82.30 FL	*82.30 FL
24	2		*TAILGATE NUMBER PLATE LAMP	Not Necessary	1,174.00 FL	*- FL
25	1		*TAILGATE DETECTOR	Not Necessary	321.00 FL	*- FL
26	1		*TAILGATE LOCK	Bent	312.00 FL	*312.00 FL
27	1		*TAILGATE WINDSCREEN MOULDING	Necessary	198.00 FL	*198.00 FL
28	1		*TAILGATE LOWER GLASS	Smashed	689.00 FL	*689.00 FL
29	1		*TAILGATE LOWER GLASS MOULDING	Necessary	159.00 FL	*159.00 FL
30	1		*TAILGATE LOWER GLASS TRIM	Cut	312.00 FL	*312.00 FL
31	1		*TAILGATE INNER TRIM BOARD	Broken	459.00 FL	*350.00 FL
32	1		*TAILGATE INNER HANDLE	Not Necessary	38.00 FL	*- FL
33	1		*REAR BUMPER	Deformed	658.00 FL	*658.00 FL
34	2		*REAR BUMPER SIDE RETAINER	Cut (1 PCS ONLY)	224.00 FL	*112.00 FL
35	1		*REAR BUMPER REINFORCEMENT	Bent	350.50 FL	*350.50 FL
36	2		*REAR BUMPER REINFORCEMENT BRACKET	Bent	502.00 FL	*502.00 FL
37	1		*REAR BUMPER TOW COVER	Missing	52.00 FL	*52.00 FL
38	2		*REAR BUMPER BRACKET	Not Necessary	228.00 FL	*- FL
39	1		*REAR BUMPER LIP	Torn	728.90 FL	*654.00 FL
40	1		*REAR BUMPER LAMP TOP	N/S Cracked / O/SNot Necessary	1,024.00 FL	*512.00 FL
41	1		*REAR BUMPER REFLECTOR	N/S Cut / O/S Not Necessary	136.00 FL	*68.00 FL
42	1		*REAR BUMPER UNDER COVER	Not Necessary	298.00 FL	*- FL
43	1		*REAR FENDER LH	Repair	898.00 FL	*- FL
44	2		*REAR FENDER COWLING	Torn (1 PCS ONLY)	396.40 FL	*198.20 FL
45	2		*REAR FENDER INNER TRIM	Crumpled (1 PCS ONLY)	1,218.00 FL	*481.00 FL
46	1		*TAILAMP	N/S Cracked /O/SNot Necessary	1,396.00 FL	*570.00 FL

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
47	2		*TAILLAMP LOWER BRACKET	Not Necessary	164.00 FL	*- FL
48	1		*REAR END PANEL	Buckled	687.00 FL	*687.00 FL
49	1		*REAR END PANEL TOP GARNISH	Deformed	212.00 FL	*212.00 FL
50	1		*REAR FLOOR PANEL	Repair	1,259.00 FL	*- FL
51	1		*REAR FLOOR PANEL TOP BOARD	Crumpled	325.00 FL	*325.00 FL
52	1		*REAR FLOOR PANEL TOP SIDE TRAY	Not Necessary	221.00 FL	*- FL
53	1		*REAR FLOOR PANEL TOP SPONGE	Not Necessary	411.00 FL	*- FL
54	1		*REAR EXHAUST PIPE	Not Necessary	989.00 FL	*- FL
55	1		*REAR EXHAUST PIPE HEAT SHIELD	Bent	312.00 FL	*312.00 FL
56	1		*FRONT NUMBER PLATE	Bent	50.00 FS	*40.00 FS
57	1		*SET FRONT BUMPER CLIPS	Not Necessary	50.00 FS	*- FS
58	1		*SET FRONT FENDER COWLING CLIP	Not Necessary	50.00 FS	*- FS
59	1		*SET FRONT SUPPORT TOP GARNISH CLIP	Not Necessary	30.00 FS	*- FS
60	1		*REAR BUMPER CLIPS	Necessary	80.00 FS	*30.00 FS
61	1		*REAR TAILGATE INNER TRIM BOARD CLIPS	Necessary	80.00 FS	*30.00 FS
62	1		*REAR WINDSCREEN SEALANT	Necessary	80.00 FS	*20.00 FS
63	1		*REAR WINDSCREEN INNER SEAL	Necessary	80.00 FS	*20.00 FS
64	1		*REAR WINDSCREEN LOWER GLASS SEALANT	Necessary	80.00 FS	*20.00 FS
65	1		*SET REAR FENDER INNER TRIM CLIPS	Necessary	50.00 FS	*30.00 FS
66	1		*REAR NUMBER PLATE	Necessary	50.00 FS	*20.00 FS
67	1		*REAR NUMBER PLATE GARNISH	Necessary	50.00 FS	*20.00 FS
68	1		*REAR REVERSE SENSOR	Damaged	250.00 FS	*200.00 FS
69	1		*REAR REVERSE CAMERA	Not Necessary	350.00 FS	*- FS
70	1		*REAR END PANEL TOP GARNISH CLIPS	Necessary	80.00 FS	*20.00 FS
71	1		*REAR END PANEL SEALANT	Necessary	60.00 FS	*40.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$)	30,884.00	10,350.90
- List Item Discount on L Items 20.00/25.00% (\$)	5,882.80	2,465.23
Total Parts (\$)	25,001.20	7,885.67

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO CHECK REAR ELECTRICAL WIRING	New	150.00	30.00
2	REMOVE AND REFIR AIRCON AND RADIATOR	New	150.00	0.00
3	REALIGN HEADLAMP	New	50.00	0.00
4	RESET TROUBLE CODE	New	300.00	0.00
5	TO REMOVE AND RENEW REVERSE SENSOR	New	150.00	40.00
6	TO REMOVE AND REFIT REAR GLASS	New	150.00	100.00
7	TO REMOVE AND REFIT REAR LOWER GLASS	New	100.00	50.00
8	REMOVE AND RENEW REAR GARNISH /UPHOLSTERY	New	200.00	60.00
9	REMOVE AND RENEW TAILGATE MECHANISM	New	80.00	60.00
10	REMOVE AND RENEW REAR EXHAUST SILENCER	New	150.00	0.00
11	TO RESPRAY UNDERCOATING }	New	150.00	60.00
12	APPLY ANTI RUST ON AFFECTED AREAS }	New	200.00	0.00
13	SPRAY PAINTING ON AFFECTED AREAS	New	2,000.00	1,400.00
14	PANEL BEATING ON AFFECTED AREAS	New	2,000.00	1,200.00
Gross Labour Cost (S\$)			5,830.00	3,000.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >