

Auto Insure Pte Ltd (HQ) (Co.Reg.No.201437380M)

6 Marsiling Lane

Singapore 739145

Tel: 3157 2626 Fax: 6368 0081 Email: claims01@autoinsure.com.sg

TP INSURER: Allianz Insurance Singapore Pte. Ltd. (HQ)
POPULAR RENT A CAR PTE LTD

Singapore

PARTICULARS OF CLAIM

Claim Type:	THIRD PARTY	Ref. No:	M5823
Policy No:		Date of Loss:	06/08/2022
Vehicle Reg. No.:	GBG662D	Driveable?	YES
Party At Fault:	UNKNOWN		
Make/Model:	TOYOTA HIACE, 3.0 (A)	Vehicle Reg. Date:	31/05/2017
Vehicle Colour:	METALLIC WHITE	Gen Condition:	FAIR
Engine No:	1KD2664257	Chassis No:	JTFHT02P000210013
Odometer:	0 KM		
Paint Type:	METALLIC 2K		
Total Loss?	NO		
Est. Duration of Repair (day)	4		
Present Location:	AUTO INSURE PTE LTD (HQ) (WOODLANDS)		

COST OF CLAIMS

	Amount
Parts	3,982.00
Miscellaneous Items	75.00
Labour	1,200.00
Paintwork Labour	1,000.00
Towing	0.00
Gross Total (S\$)	6,257.00
+ GST 7.00% (S\$)	437.99
Nett Amount (S\$)	6,694.99

This claim is handled by: MARVYN CHUA HONG LENG

Generated using Merimen e-Claims Internet Estimation & Adjusting System

REPAIR DETAILS

Reference

Part Source: (Last Synchronised: 12 Aug 2022)

Parts: N/A TOYOTA HIACE 3.0 (A) (Model not available in database)

Labour: Repairer's (Price-denominated Standard List)

Print Code: Auto Insure Pte Ltd (HQ)/GBG662D/12/08/2022 11:40

Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Estimates on Parts

No.	Qty	Part No.	Particulars	%Disc	%Depr	Amount
1	1		*FRONT BUMPER / Cut	0.00	0.00	*205.00 F
2	1		*FRONT BUMPER SIDE RETAINER LH ?	0.00	0.00	*60.00 F
3	1		*FRONT STEP PANEL LH / Bmc	0.00	0.00	*90.00 F
4	1		*FRONT STEP PANEL GARNISH LH / P's.	0.00	0.00	*15.00 F
5	1		*FRONT DOOR LH / BT	0.00	0.00	*720.00 F
6	1		*FRONT FENDER LH / Repair	0.00	0.00	*90.00 F
7	1		*REAR DOOR LH / Repair	0.00	0.00	*720.00 F
8	1		*REAR FENDER LH / Repair	0.00	0.00	*600.00 F
9	1		*B PILLAR OUTER LH / Repair	0.00	0.00	*520.00 F
10	1		*FUEL FILLER FLAP / Repair	0.00	0.00	*90.00 F
11	1		*SIDE MIRROR LH / Repair	0.00	0.00	*150.00 F
12	1		*SILL PANEL LH / Repair	0.00	0.00	*360.00 F

F=Franchise part.

Sub Total (S\$)

3,620.00

+ Margin on L,N Items 10.00% (S\$)

362.00

Total Parts (S\$)

3,982.00

Auto Insure Pte Ltd (HQ)/GBG662D/12/08/2022 11:40, Not valid without Reference section.
Generated using Merimen e-Claims IEAS

Estimates on Miscellaneous Items

No	Qty	Particulars	Amount
Miscellaneous Items			
1	1	FRONT BUMPER CLIPS	50.00
2	1	FRONT DOOR COMPANY STICKER LH	25.00
Sub Total (S\$)			75.00

Estimates on Labour

No	Particulars	Lab.Type	Amount
Paintwork Labour			
1	LABOUR FOR SPRAY PAINTING	New	1,000.00
Labour Items			
2	LABOUR FOR PANEL BEATING	New	1,200.00
Gross Labour Cost (S\$)			2,200.00

Auto Insure Pte Ltd (HQ)/GBG662D/12/08/2022 11:40. Not valid without Reference section.

Generated using Merimen e-Claims IEAS

< END OF ESTIMATES >

5 Days.

Lumpsum Repair

after repair photos

Gino Qiang

8288 0282

Gino Qiang @ lkk Auto. com

23/8/22.

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary part(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature

Date