

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CC6/AIG22008297/APA3Q2**Date:** 06/02/2023REFERENCE

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	2070138780
Claimant Vehicle No :	SJY419B	Insured Vehicle No :	SMV3950T
Date of Loss:	16/08/2022	Nature of Claim:	TP
		Claim No:	7472892313SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SJY419B	Engine No:	LTA1601709
Make & Model:	AUDI A5, 2.0 TFSI QUATTRO (A)	Chassis No:	WAUZZZ8F2AN023047
Reg. Date:	29/07/2010 (Man. Year: 2010)	Odometer:	160032 km
Colour:	White		
Engine Capacity:	1984 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	255/35 R19	Rear Tyre Size:	255/35 R19
Front Left Side:	Habilead 6 mm	Rear Left Side:	Habilead 6 mm
Front Right Side:	Habilead 6 mm	Rear Right Side:	Habilead 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	9,012.40	4,348.80	4,663.60	51.75
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,250.00	910.00	1,340.00	59.56
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	11,262.40	5,258.80	6,003.60	53.31
Approved Total (Overridden) (S\$)		4,200.00		
Nett Amount (S\$)	11,262.40	4,200.00	7,062.40	62.71
+ Car Rental (4.0 x S\$130.00/day) (S\$)		520.00		
+ Doc/Search Fee (S\$)		7.45		
Nett Liability (S\$)		4,727.45		

INSPECTION

Date of Assignment:	18/08/2022	Hua Meng Spray Painting Workshop (HQ)
Date Inspected:	18/08/2022 Inspected At:	No 1 Kaki Bukit Avenue 6, #01-61 Autobay@Kaki Bukit
Estimated Period of Repair:	4.0 days	Singapore 417883

Adjuster: ADRIAN LING**Manager:** CHEW HSIAO TONG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT RH FENDER	Dented	1,449.60 F	*1,208.00 FL
2	1		*FRONT RH DOOR	Dented	3,666.00 F	*3,155.00 FL
3	1		*FRONT RH DOOR TOP HINGE	Not Necessary	201.60 F	*- FL
4	1		*FRONT RH DOOR LOWER HINGE	Not Necessary	201.60 F	*- FL
5	1		*FRONT RH DOOR STOPPER	Not Necessary	430.80 F	*- FL
6	1		*FRONT RH DOOR WEATHER STRIP	Necessary	562.80 F	*469.00 FL
7	1		*ROCKER PANEL	Repair	2,220.00 F	*- FL
8	1		*REAR FENDER INNER SHIELD	Not Necessary	280.00 F	*- FL

F=Franchise part. L=ListItemDisc.

Sub Total (\$\$)	9,012.40	4,832.00
- List Item Discount on L Items 0.00/10.00% (\$\$)	0.00	483.20
Total Parts (\$\$)	9,012.40	4,348.80

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	REMOVE & REINSTALL DOOR GLASS	New	150.00	80.00
2	REMOVE,REPLACE & REPAIR CONSISTENT TO THE ACCIDENT	New	1,000.00	400.00
3	RESPRAY PAINTING	New	1,000.00	400.00
4	TUFF KOTE	New	100.00	30.00
Gross Labour Cost (\$\$)			2,250.00	910.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >