

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com; cs-a@lkkauto.com; admin-a@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CC4/AIS22008298/DPA3Q2**Date:** 15/05/2023REFERENCE

Handling Insurer:	Allianz Insurance Singapore Pte. Ltd.	Policy No:	SP2001003390
Claimant Vehicle No :	SH7718A	Insured Vehicle No :	SLA5503K
Date of Loss:	20/08/2022	Nature of Claim:	TP
		Claim No:	202222006260

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SH7718A	Engine No:	G4LEKU296075
Make & Model:	HYUNDAI AE IONIQ HEV, 1.6 DCT (A)	Chassis No:	KMHC851CVKU164422
Reg. Date:	02/07/2019 (Man. Year: 2019)	Odometer:	428455 km
Colour:	Blue		
Engine Capacity:	1580 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	195/65 R15	Rear Tyre Size:	195/65 R15
Front Left Side:	West Lake 5 mm	Rear Left Side:	West Lake 5 mm
Front Right Side:	West Lake 5 mm	Rear Right Side:	West Lake 5 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	12,604.39	7,166.32	5,438.07	43.14
Miscellaneous Items	0.00	0.00	0.00	
Labour	5,730.00	1,670.00	4,060.00	70.86
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	18,334.39	8,836.32	9,498.07	51.80
+ GST 7.00/7.00% (S\$)	1,283.41	618.54	664.87	51.80
Nett Amount (S\$)	19,617.80	9,454.86	10,162.94	51.80
+ Loss of Use (10.0 x S\$50.00/day) (S\$)		500.00		
+ Car Rental (10.0 x S\$125.19/day) (S\$)		1,251.90		
+ Doc/Search Fee (S\$)		7.45		
+ Other Costs (S\$)		80.00		
Nett Liability (S\$)		11,294.21		
Global Sum Settlement (S\$)		11,200.00		

INSPECTION

Date of Assignment:	23/08/2022	
Date Inspected:	24/08/2022	Inspected At: Bifrost Auto Pte Ltd (sin Ming) (HQ) Blk 9 Sector C, #01-42 Sin Ming Industrial Estate Singapore 575644
Estimated Period of Repair:	8.0 days	

Adjuster: BRYAN TANI**Manager:** CHEW HSIAO TONG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference		
Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 15 May 2023)
Parts:	143	HYUNDAI AE IONIQ HEV 1.6 DCT (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SH7718A)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR DOOR (RH)	Dented	2,147.90 FL	*2,147.90 FL
2	1		*REAR DOOR RUBBER (RH)	Serviceable	280.00 FL	*- FL
3	1		*REAR DOOR OUTER MOULDING (RH)	Serviceable	125.30 FL	*- FL
4	1		*REAR DOOR OUTER HANDLE (RH)	Not Necessary	124.80 FL	*- FL
5	1		*REAR DOOR CHANNEL (RH)	Serviceable	358.30 FL	*- FL
6	1		*REAR DOOR GEAR /REGULATOR (RH)	Not Necessary	367.84 FL	*- FL
7	1		*REAR DOOR POWER MOTOR (RH)	Not Necessary	256.80 FL	*- FL
8	1		*REAR DOOR LOCK ASSY	Not Necessary	306.40 FL	*- FL
9	1		*REAR DOOR 1/4 GLASS RUBBER (RH)	Serviceable	124.90 FL	*- FL
10	1		*REAR DOOR 1/4 GLASS PILLAR (RH)	Not Necessary	86.70 FL	*- FL
11	1		*REAR DOOR HINGE UPPER (RH)	Not Necessary	173.88 FL	*- FL
12	1		*REAR DOOR HINGE LOWER (RH)	Not Necessary	170.50 FL	*- FL
13	1		*REAR DOOR CHECK (RH)	Not Necessary	85.92 FL	*- FL
14	1		*REAR DOOR PROTECTOR (RH)	Necessary	166.20 FL	*166.20 FL
15	1		*REAR BUMPER	Mtg Broken	459.40 FL	*459.40 FL
16	1		*REAR BUMPER SIDE RETAINER (RH)	Serviceable	85.80 FL	*- FL
17	1		*REAR BUMPER COVER CLIPS	Necessary	22.00 FL	*22.00 FL
18	1		*REAR FENDER (RH)	Dented	1,768.30 FL	*1,768.30 FL
19	1		*REAR FENDER SHIELD REAR PIECE (RH)	Not Necessary	173.60 FL	*- FL
20	1		*REAR FENDER SHIELD FRT PIECE (RH)	Not Necessary	165.50 FL	*- FL
21	1		*REAR FENDER AIR-DUCT (RH)	Not Necessary	87.30 FL	*- FL
22	1		*REAR FENDER TRIM BOARD (RH)	Not Necessary	788.75 FL	*- FL
23	1		*ASSY BSD BLIND SPOT RADAR (RH)	Not Necessary	1,784.40 FL	*- FL
24	1		*REAR TYRE RIM (RH)	Distorted	1,124.20 FL	*1,124.20 FL
25	1		*REAR WHEEL HUP-CAP (RH)	Cut	346.40 FL	*346.40 FL
26	1		*REAR WHEELBEARING & HUB ASSY	Damaged	554.00 FL	*554.00 FL
27	1		*REAR TRAILING ARM (RH)	Distorted	265.40 FL	*265.40 FL
28	1		*REAR ASSIST (RH)	Distorted	227.90 FL	*227.90 FL
29	1		*REAR SHOCK ABSORBER (RH)	Distorted	230.50 FL	*230.50 FL
30	1		*REAR SHOCK ABSORBER MOUNTING (RH)	Not Necessary	133.10 FL	*- FL
31	1		*REAR ABSORBER STOPPER (RH)	Not Necessary	137.60 FL	*- FL
32	1		*REAR ABSORBER COVER (RH)	Not Necessary	175.60 FL	*- FL
33	1		*STABILIZER BAR	Not Necessary	387.30 FL	*- FL
34	1		*STABILIZER LINK (RH)	Not Necessary	147.30 FL	*- FL
35	1		*REAR UPPER ARM (RH)	Distorted	239.50 FL	*239.50 FL
36	1		*REAR LOWER ARM (RH)	Distorted	393.10 FL	*393.10 FL
37	1		*REAR KNUCKLE ARM (RH)	Distorted	538.10 FL	*538.10 FL
38	1		*REAR DOOR ADVERTISEMENT LOGO (RH)	Necessary	100.00 FS	*100.00 FS
39	1		*REAR DOOR COMFORTDELGRO & APPS STICKER (RH)	Necessary	80.00 FS	*80.00 FS
40	1		*REAR BUMPER ADVERTISEMENT LOGO	Necessary	50.00 FS	*50.00 FS
41	1		*REAR BUMPER RUBBER MAT	Necessary	50.00 FS	*50.00 FS
42	1		*REAR FENDER ADVERTISEMENT LOGO (RH)	Necessary	100.00 FS	*100.00 FS
43	1		*REAR TYRE (RH)	Not Necessary	216.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (S\$)15,606.498,862.90

- List Item Discount on L Items 20.00/20.00% (S\$)3,002.101,696.58

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
					Total Parts (S\$)	12,604.39
						7,166.32
Report was unsubmitted during this print-out.						

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	PANEL BEATING	New	1,800.00	700.00
2	SPRAY PAINTING CHARGE	New	1,600.00	600.00
3	WIRING CHARGE	New	100.00	0.00
4	TUFF KOTE	New	100.00	20.00
5	TOWING CHARGE	New	80.00	0.00
6	REMOVE/REFIX CUSHION & UPHOLSTERY REAR	New	150.00	80.00
7	REMOVE /REFIX UNDERCARRIAGE (RR)	New	400.00	150.00
8	TRANSFER OF DOOR MECHANISM REAR	New	80.00	60.00
9	RE-SET REAR POWER WINDOW SYSTEM	New	200.00	0.00
10	FOUR WHEEL ALIGNMENT	New	120.00	60.00
11	DIAGNOSTIC & RESETTING TO ERASE FAULT CODE	New	550.00	0.00
12	DIAGNOSTIC & RESETTING ADAS OPTICAL SENSOR	New	550.00	0.00
Gross Labour Cost (\$\$)			5,730.00	1,670.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >