

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CC6/AIG22008302/UPA3Q2**Date:** 07/02/2023REFERENCE

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	2100453526
Claimant Vehicle No :	GBJ2184M	Insured Vehicle No :	SLA4484M
Date of Loss:	23/08/2022	Nature of Claim:	TP
		Claim No:	3643057684SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	GBJ2184M		
Make & Model:	TOYOTA DYNA 150, 3.0 D 5MT (M)	Engine No:	1KD2838967
Reg. Date:	18/02/2019 (Man. Year: 2018)	Chassis No:	JTFAT35Y70K212420
Colour:	Silver	Odometer:	113789 km
Engine Capacity:	2982 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	195 R15	Rear Tyre Size:	155 R12 (D)
Front Left Side:	Bridgestone 6 mm	Rear Left Side:	Bridgestone 6/6 mm
Front Right Side:	Bridgestone 6 mm	Rear Right Side:	Bridgestone 6/6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	4,145.00	2,410.00	1,735.00	41.86
Miscellaneous Items	0.00	0.00	0.00	
Labour	750.00	500.00	250.00	33.33
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	4,895.00	2,910.00	1,985.00	40.55
+ GST 7.00/7.00% (S\$)	342.65	203.70	138.95	40.55
Nett Amount (S\$)	5,237.65	3,113.70	2,123.95	40.55
+ Loss of Use (3.0 x S\$100.00/day) (S\$)		300.00		
Nett Liability (S\$)		3,413.70		

INSPECTION

Date of Assignment:	01/09/2022		
Date Inspected:	01/09/2022	Inspected At:	Jin Auto Services Pte Ltd (Defu) Blk 14 Defu Lane 10, #01-410/412 Singapore 539195
Estimated Period of Repair:	3.0 days		

Adjuster: MARCUS CHUA**Manager:** CHEW HSIAO TONG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR CARGO BOX DOOR N/S	Dented	1,200.00 FS	*900.00 FS
2	1		*REAR CARGO BOX DOOR O/S	Dented	1,200.00 FS	*900.00 FS
3	1		*REAR CARGO BOX LOWER MEMBER	Repair	600.00 FS	*- FS
4	1		*REAR STEP PANEL ASSY	Bent	800.00 FS	*600.00 FS
5	1		*REAR LICENCE PLATE	Serviceable	20.00 FS	*- FS
6	1		*REAR LICENCE PLATE BRACKET	Repair	115.00 FS	*- FS
7	1		*SET REAR REVERSE SENSOR	Serviceable	200.00 FS	*- FS
8	1		*70KM/H STICKER	Necessary	10.00 FS	*10.00 FS

F=Franchise part. S=SpcNett.

Total Parts (S\$)	4,145.00	2,410.00
-------------------	----------	----------

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	LABOUR FOR PANEL BEATING & REPLACING PARTS	New	500.00	400.00
2	TO PUTTY & SPRAY PAINTING	New	200.00	100.00
3	TO R&R REAR REVERSE SENSOR	New	50.00	0.00
Gross Labour Cost (S\$)			750.00	500.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >