

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CC4/AIS22008303/APA3Q2**Date:** 04/11/2022**REFERENCE**

Handling Insurer:	Allianz Insurance Singapore Pte. Ltd.	Policy No:	SP2001130805-01
Claimant Vehicle No :	SKB460P	Insured Vehicle No :	SJV8406B
Date of Loss:	22/08/2022	Nature of Claim:	TP
		Claim No:	N/A

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SKB460P	Engine No:	1ZR080008
Make & Model:	TOYOTA COROLLA ALTIS, 1.6 (A)	Chassis No:	MR053REE104114394
Reg. Date:	26/04/2011 (Man. Year: 2011)	Odometer:	127156 km
Colour:	Blue		
Engine Capacity:	1598 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	195/65 R15	Rear Tyre Size:	195/65 R15
Front Left Side:	Continental 6 mm	Rear Left Side:	Continental 6 mm
Front Right Side:	Continental 6 mm	Rear Right Side:	Continental 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	4,340.47	3,252.92	1,087.55	25.06
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,460.00	1,780.00	680.00	27.64
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	6,800.47	5,032.92	1,767.55	25.99
Approved Total (Overridden) (S\$)		4,000.00		
(S\$)	6,800.47	4,000.00	2,800.47	41.18
+ GST 7.00/7.00% (S\$)	476.03	280.00	196.03	41.18
Nett Amount (S\$)	7,276.50	4,280.00	2,996.50	41.18
Global Sum Settlement (S\$)		0.00		

INSPECTION

Date of Assignment:	25/08/2022	Twincar Automotive Pte Ltd - Kaki Bukit (HQ)
Date Inspected:	25/08/2022 Inspected At:	2 KAKI BUKIT AVENUE 2, #01-17 KAKI BUKIT AUTOHUB
Estimated Period of Repair:	6.0 days	Singapore 417921

Adjuster: ADRIAN LING**Manager:** CHEW HSIAO TONG*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 03 Nov 2022)
Parts:	143	TOYOTA COROLLA ALTIS 1.6 (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SKB460P)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BOOTLID	Buckled	925.40 FL	*754.00 FL
2	1		*REAR BOOTLID 1.6 EMBLEM	Necessary	35.80 FL	*35.80 FL
3	1		*REAR BOOTLID ALTIS EMBLEM	Necessary	49.10 FL	*49.10 FL
4	1		*REAR BOOTLID COROLLA EMBLEM	Necessary	49.10 FL	*49.10 FL
5	1		*REAR BOOTLID DUAL EMBLEM	Necessary	39.20 FL	*39.20 FL
6	1		*REAR BOOTLID LOGO EMBLEM	Necessary	61.60 FL	*61.60 FL
7	1		*REAR BOOTLID VVT-I EMBLEM	Necessary	43.10 FL	*43.10 FL
8	2		*REAR BOOTLID HINGES L/R	Not Necessary	137.40 FL	*- FL
9	1		*REAR BOOTLID LH REFLECTOR LAMP (LH)	Cracked	175.80 FL	*175.80 FL
10	1		*REAR BOOTLID LH REFLECTOR LAMP GASKET SEAL	Necessary	29.80 FL	*29.80 FL
11	1		*REAR BOOTLID MECHANISM LOCK	Not Necessary	111.80 FL	*- FL
12	4		*REAR BOOTLID RUBBER GUIDE STOPPER	Not Necessary	40.00 FL	*- FL
13	1		*REAR BOOTLID WEATHERSTRIP	Cut	194.20 FL	*194.20 FL
14	1		*REAR BUMPER	Deformed	556.40 FL	*556.40 FL
15	2		*REAR BUMPER CORNER RETAINER L/R	Not Necessary	69.60 FL	*- FL
16	1		*REAR BUMPER LH BRACKET	Dented	92.00 FL	*92.00 FL
17	1		*REAR BUMPER LH END SEAL COVER	Not Necessary	49.30 FL	*- FL
18	1		*REAR BUMPER LH REFLECTOR	Cracked	39.30 FL	*39.30 FL
19	1		*REAR BUMPER SIDE RETAINER L/R	N/S Damaged	145.80 FL	*72.90 FL
20	1		*REAR BUMPER SPONGE	Cracked	142.60 FL	*142.60 FL
21	1		*REAR END PANEL	Dented	670.00 FL	*670.00 FL
22	1		*REAR END PANEL INNER TOP GARNISH	Deformed	213.80 FL	*213.80 FL
23	1		*REAR LH FENDER INNER UPHOLSTERY TRIM	Not Necessary	370.30 FL	*- FL
24	1		*REAR LH TAILLAMP	Cracked	375.50 FL	*375.50 FL
25	1		*REAR LH TAILLAMP GASKET SEAL	Necessary	35.20 FL	*35.20 FL
26	1		*REAR LH TAILLAMP LOWER BRACKET	Not Necessary	80.70 FL	*- FL
27	1		*REAR SPARE TYRE INNER TOP UPHOLSTERY BOARD	Torn	294.50 FL	*294.50 FL
28	1		*SET REAR BOOTLID CHROME MOULDING CLIPS	Not Necessary	30.00 FS	*- FS
29	1		*SET REAR BUMPER CLIPS	Necessary	50.00 FS	*30.00 FS
30	1		*SET REAR BUMPER END COVER CLIPS	Not Necessary	30.00 FS	*- FS
31	1		*REAR BUMPER REVERSE SENSOR	Necessary	250.00 FS	*200.00 FS
32	1		*SET REAR END PANEL INNER TOP GARNISH CLIPS	Necessary	30.00 FS	*10.00 FS
33	1		*REAR END PANEL SEALANT	Necessary	80.00 FS	*60.00 FS
34	2		*SET REAR FENDER INNER UPHOLSTERY TRIM CLIPS L/R	Not Necessary	60.00 FS	*- FS
35	2		*SET REAR TAILLAMP CLIPS L/R	Necessary	40.00 FS	*10.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	5,597.30	4,233.90
- List Item Discount on L Items 25.00/25.00% (\$\$)	1,256.83	980.98
Total Parts (\$\$)	4,340.47	3,252.92

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO REMOVE ,REINSTALL ELECTRICAL WIRING HARNESS ,CHECK LIGHTING AND REWIRE FOR PARKING SENSOR	New	60.00	60.00
2	TO REMOVE ,REINSTALL ROOF TOP TRIM UPHOLSTERY CUSHION SEAT ,TRIM GARNISH ,TRIM LINER CARPET (TO FR)	New	120.00	60.00
3	TO RE-SPRAY PAINTING ON THE CHARGE BODYPARTS ,REPAIR PORTION ,AND WHERE CONSISTENT TO THE ACCIDENT	New	1,100.00	800.00
4	TO PROVIDE LABOUR ,WORKMANSHIP TO CHARGE THE ABOVE DAMAGED BODYPARTS ,REPAIR ,RECOSTRUCT AND RE- ALIGN BODY STRUCTURE BODY ALIGNMENTS AND DAMAGED CONSISTENT TO THE ACCIDENT	New	1,100.00	800.00
5	TO APPLY ANTI -RUST CHEMICAL ON REPAIRED AND REPLACED PANEL	New	80.00	60.00
Gross Labour Cost (\$)			2,460.00	1,780.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >