



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SNE 4130P

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<u>REPLACEMENT OF PARTS</u>			
1	TAILGATE (CONSISTENT)	NOT NECESSARY	1,359.00	-
1	TAILGATE LOGO (CONSISTENT)	NOT NECESSARY	95.50	-
1	TAILGATE EMBLEM PRIUST(CONSISTENT)	NOT NECESSARY	89.40	-
1	TAILGATE EMBLEM HYBRID(CONSISTENT)	NOT NECESSARY	82.30	-
1	TAILGATE DETECTOR (CONSISTENT)	NOT NECESSARY	321.00	-
1	REAR BUMPER (CONSISTENT)	DEFORMED	658.00	549.00
1	REAR BUMPER SIDE RETAINER LH (CONSISTENT)	NOT NECESSARY	112.00	-
1	REAR BUMPER REINFORCEMENT (CONSISTENT)	NOT NECESSARY	350.50	-
1	REAR BUMPER LIP (CONSISTENT)	DEFORMED	728.90	728.90
1	REAR BUMPER REFLECTOR LH (CONSISTENT)	NOT NECESSARY	68.00	-
1	REAR END PANEL (CONSISTENT)	TO REPAIR SEE LABOUR	612.00	-
1	REAR END PANEL TOP GARNISH (CONSISTENT)	NOT NECESSARY	212.00	-
	LESS 20% DISCOUNT		-937.72	-
	LESS 25% DISCOUNT		-	-319.48
			3,750.88	958.42
	<u>SPECIAL NETT ITEMS</u>			
1	REAR BUMPER CLIPS (SN)(CONSISTENT)	NECESSARY	80.00	30.00
1	REAR REVERSE SENSOR (SN)(CONSISTENT)	NOT WORKING	250.00	200.00
1	REAR END PANEL TOP GARNISH CLIPS (SN) (CONSISTENT)	NOT NECESSARY	80.00	-
1	REAR END PANEL SEALANT (SN)(CONSISTENT)	NOT NECESSARY	60.00	-
			470.00	230.00
	<u>LABOUR</u>			
	TO CHECK REAR ELECTRICAL WIRING .	NOT NECESSARY	150.00	-
	TO REMOVE AND RENEW REVERSE SENSOR .		150.00	30.00
	REMOVE AND RENEW REAR GARNISH /UPHOLSTERY .		200.00	60.00
	APPLY ANTI RUST ON AFFECTED AREAS .	NOT NECESSARY	100.00	-
	SPRAY PAINTING ON AFFECTED AREAS .		600.00	250.00

Report Ref No. CC4/ASM22008309/Tpa3q2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	PANEL BEATING ON AFFECTED AREAS .INCLUSIVE OF THE REPAIR OF REAR END PANEL .		600.00	250.00
			1,800.00	590.00
GRAND TOTAL			6,020.88	1,778.42
RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)				1,400.00

Report Ref No. CC4/ASM22008309/Tpa3q2

MOHAMAD TAUFIKH

M.MATAI, AMSAE-A

Automotive Assessor

HO LEONG CHUAN

Automotive Assessor

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.