

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CC6/AIG22008310/KPA3Q2**Date:** 07/11/2022REFERENCE

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	1900029962
Claimant Vehicle No :	SMH7091U	Insured Vehicle No :	SJB9001J
Date of Loss:	27/07/2022	Nature of Claim:	TP
		Claim No:	3623708289SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SMH7091U		
Make & Model:	HONDA FIT, 1.5 HYBRID (A)	Engine No:	LEB1444660
Reg. Date:	30/01/2019 (Man. Year: 2018)	Chassis No:	GP51336962
Colour:	Metallic Black	Odometer:	254055 km
Engine Capacity:	1496 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	195/50 R15	Rear Tyre Size:	195/50 R15
Front Left Side:	Triangle 5 mm	Rear Left Side:	Firenza 8 mm
Front Right Side:	Triangle 5 mm	Rear Right Side:	Firenza 8 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	2,019.36	504.64	1,514.72	75.01
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,970.00	450.00	1,520.00	77.16
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	3,989.36	954.64	3,034.72	76.07
Approved Total (Overridden) (S\$)		750.00		
(S\$)	3,989.36	750.00	3,239.36	81.20
+ GST 7.00/7.00% (S\$)	279.26	52.50	226.76	81.20
Nett Amount (S\$)	4,268.62	802.50	3,466.12	81.20
+ Loss of Use (4.0 x S\$60.00/day) (S\$)		240.00		
+ Doc/Search Fee (S\$)		2.00		
Nett Liability (S\$)		1,044.50		

INSPECTION

Date of Assignment:	26/08/2022	Optima Werkz Pte Ltd (HQ)
Date Inspected:	26/08/2022 Inspected At:	10 Ang Mo Kio Industrial Park 2A, #01-05/06 AMK
		Autopoint
		Singapore 568047
Estimated Period of Repair:	2.0 days	

Adjuster: KENNETH KONG**Manager:** CHEW HSIAO TONG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR TAILGATE	Repair	947.40 FL	*- FL
2	1		*REAR TAILGATE FIT EMBLEM	Not Necessary	42.90 FL	*- FL
3	1		*REAR TAILGATE HYBRID EMBLEM	Not Necessary	58.50 FL	*- FL
4	1		*REAR TAILGATE WEATHERSTRIP	Serviceable	102.30 FL	*- FL
5	1		*REAR WINDSCREEN MOULDING	Not Necessary	110.80 FL	*- FL
6	1		*REAR BUMPER	Buckled	568.30 FL	*568.30 FL
7	1		*REAR BUMPER SIDE BRACKET RH	Serviceable	28.80 FL	*- FL
8	1		*REAR BUMPER REFLECTOR RH	Serviceable	40.90 FL	*- FL
9	1		*REAR BUMPER LOWER GARNISH COVER RH	Serviceable	86.80 FL	*- FL
10	1		*REAR END PANEL (NPA)	Repair	0.00 FL	*- FL
11	1		*REAR WINDSCREEN SEALANT	Not Necessary	80.00 FS	*- FS
12	1		*REAR BUMPER CLIPS	Necessary	50.00 FS	*50.00 FS
13	1		*REAR BUMPER REVERSE SENSOR	Serviceable	300.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	2,416.70	618.30
- List Item Discount on L Items 20.00/20.00% (\$\$)	397.34	113.66
Total Parts (\$\$)	2,019.36	504.64

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	LABOUR CHARGES TO REMOVE ,REPLACE ,REFIX REPAIR & READJUST REAR ACCIDENT AREAS & ETC	New	700.00	200.00
2	LABOUR CHARGES FOR PAINTING & TO SUPPLY PAINT & FURNISHING MATERIALS AT REAR TAILGATE ,REAR BUMPER ,REAR END PANEL & ETC	New	700.00	200.00
3	LABOUR CHARGES TO REMOVE & REFIX REAR WINDSCREEN GLASS ,REAR WINDSCREEN MOULDING ,REAR WINDSCREEN SEALANT & ETC	New	150.00	0.00
4	LABOUR CHARGES TO REMOVE & REINSTALLED REAR TAILGATE INNER MECHANISM & ETC .BACK TO ORIGINAL OPERATIONS	New	120.00	0.00
5	LABOUR CHARGES TO REMOVE & REPLACE REAR BUMPER REVERSE SENSOR & ETC	New	120.00	50.00
6	TO DIAGNOSIS FAULT CODE & RESET MEMORY	New	100.00	0.00
7	TO CHECK WIRING & ELECTRICAL SYSTEM	New	80.00	0.00
Gross Labour Cost (\$\$)			1,970.00	450.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >