

GBF 8213
Reinspect.

ANNEX A

REPAIR DETAILS

Recommended Parts

No	Qty	Description	Condition	Repairer's Amount	Adjuster's Amount
1	1	Rear bumper assy <i>CRA - #</i>	warped/dented	\$ 1,260.00	\$ 1,260.00 <i>600 ✓</i>
2	1 set	Rear bumper bracket <i>X NN</i>	necessary	\$ 172.00	\$ 172.00 <i>X</i>
3	2	Rear bumper retainer <i>X NN</i>	necessary	\$ 150.00	\$ 150.00 <i>X</i>
4	1	Rear tailgate assy <i>X Dent</i>	bent/dented	\$ 1,878.00	\$ 1,878.00 <i>X 2</i>
5	1	Rear tailgate centre logo <i>NEC ✓</i>	necessary	\$ 68.00	\$ 68.00 <i>✓</i>
6	1	Rear tailgate lock assy <i>X NN</i>	serviceable	\$ 251.00	\$ - <i>X</i>
7	1	Rear left taillamp <i>CRA X N/E</i>	cracked	\$ 885.00	\$ 885.00 <i>X</i>
8	1	Rear right taillamp <i>X NN</i>	reuse	\$ 885.00	\$ - <i>X</i>
9	1	Rear left taillamp inner seal <i>NN X</i>	necessary	\$ 88.00	\$ 88.00 <i>X</i>
10	1	Rear end lower inner panel <i>X R</i>	repair	\$ 1,275.00	\$ - <i>X</i>
11	1	Rear end lower outer panel <i>X R</i>	bent/dented	\$ 1,125.00	\$ 1,125.00 <i>X</i>
12	1	Rear windscreen glass moulding <i>NN X</i>	necessary	\$ 188.00	\$ 188.00 <i>X</i>
				\$ 8,225.00	\$ 5,814.00
Less 25%				\$ 2,056.25	\$ 1,453.50
				\$ 6,168.75	\$ 4,360.50

Special Nett Items

1	1	Rear no plate <i>X NN</i>	necessary	\$ 100.00	\$ 80.00 <i>X</i>
2	1	Rear tailgate '70km/h' sticker <i>NEC ✓</i>	necessary	\$ 50.00	\$ 30.00 <i>✓</i>
3	1 set	Rear tailgate company sticker <i>NEC ✓</i>	necessary	\$ 300.00	\$ 250.00 <i>100</i>
4	1	Rear windscreen glass sealant <i>NN X</i>	necessary	\$ 100.00	\$ 80.00 <i>X</i>
5	1	Rear end lower outer panel sealant <i>X NN</i>	necessary	\$ 100.00	\$ 80.00 <i>X</i>
6	10	Rear bumper clips <i>NEC ✓</i>	necessary	\$ 60.00	\$ 50.00 <i>20 ✓</i>
7	2	Rear bumper reverse sensor <i>X NN</i>	malfunction	\$ 300.00	\$ 250.00 <i>X</i>
				\$ 1,010.00	\$ 820.00

Total parts

\$ 7,178.75 \$ 5,180.50

ANNEX B

REPAIR DETAILS

Recommended Labour

No	Description	Repairer's Amount	Adjuster's Amount
1	Labour for panel beating, cut, weld, straighten rear affected area and replace rear damaged parts.	\$ 1,000.00	\$ 800.00 500
2	To putty and spray painting rear portion.	\$ 1,000.00	\$ 800.00 500
3	To check rear lighting and wiring.	\$ 50.00	\$ 30.00 30
4	To remove and install rear inner garnish and trim to facilitate the repair.	\$ 140.00	\$ 120.00 X
5	To apply anti rust proofing to rear affected area.	\$ 140.00	\$ 120.00 30
6	To remove and install rear windscreen glass to facilitate the repair.	\$ 140.00	\$ 120.00 X m
7	To remove and install rear bumper reverse sensor.	\$ 80.00	\$ 60.00 30
8	Towing service.	\$ 100.00	\$ 80.00 40
Total labour :		\$ 2,650.00	\$ 2,130.00

ANNEX C

REPAIR DETAILS

Adjusted Repair Cost

	Repairer's Amount	Adjuster's Amount
Total parts :	\$ 7,178.75	\$ 5,180.50
Total labour :	\$ 2,650.00	\$ 2,130.00
Total repair cost :	\$ 9,828.75	\$ 7,310.50

Adjusted Repair Cost (Lump Sum Repair)

\$ 5,800.00