



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

DAMAGE ASSESSMENT REPORT

INCOME INSURANCE LTD

Ref: CS/INC22008325/Kqy3m4

73 BRAS BASAH ROAD
#05-01 NTUC TRADE UNION HOUSESINGAPORE
189556

Date: 19/10/2022

ATTN: ENG HUEY HUEY

Code: INC

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	YQ 1831B	Veh. Inspected	GBK 9836P
Policy No.		Coverage (\$)	0.00
Claim No.	MT/1183165-002	Excess (\$)	0.00
Assign From	ANNIE KOH	Assign Date	29/08/2022

2. Vehicle Particulars & Condition

Make & Model	TOYOTA DYNA (M)	c.c	2982
Engine No.	HIDDEN	Year of Reg.	2021
Chassis No.	JTFAT35Y70K216399	Colour	SILVER
Odometer	49280 KM	Steering	IN ORDER
Brakes	IN ORDER	Modification	NIL
General	GOOD		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre	195 R15X8	MAXXIS	9 mm
L/H Front Tyre	195 R15X8	MAXXIS	9 mm
R/H Rear Tyre	155 R12X8 (D)	BRIDGESTONE	2/2 mm
L/H Rear Tyre	155 R12X8 (D)	BRIDGESTONE	2/2 mm

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION.

DAMAGES SEE DETAILS.

5. General Information

Accident Date	04/08/2022	Inspect Date / Time	29/08/2022 (11:58 AM)
Survey held at	TAT HENG MOTOR WORKS BLK 10, ANG MO KIO INDUSTRIAL PARK 2A #02-09, ANG MO KIO POINT, SINGAPORE 568047		

5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS.
B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR:	4 Working Days
-------------------------------------	----------------