

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

| DAMAGE ASSESSMENT REPORT | | | | | |
|------------------------------------|--|---|----------------|-------|-------------------------|
| | INCOME INSURAN | ICE LTD | | Ref: | CS/INC22008326/Kvy3e2 |
| | 73 BRAS BASAH F #05-01 NTUC TRA 189556 | ROAD DE UNION HOUSESINGAPORE | | Date: | 29/09/2022 |
| | ATTN: CYNTHIA A | NG | | Code: | INC |
| 1. | Policy Particulars :- THIRD PARTY CLAIM | | | | |
| | Insured Veh. | SLA 887K | Veh. Inspected | | SDS 8900C |
| | Policy No. | | Coverage (\$) | | 0.00 |
| | Claim No. | MT/1185691-002 | Excess (\$) | | 0.00 |
| | Assign From | ANNIE KOH | Assign Date | | 29/08/2022 |
| 2. Vehicle Particulars & Condition | | | | | |
| | Make & Model | TOYOTA ALTIS (A) | c.c | | 1598 |
| | Engine No. | HIDDEN | Year of Reg. | | 2006 |
| | Chassis No. | MR053ZEC107118760 | Colour | | METALLIC GREY |
| | Odometer | - | Steering | | IN ORDER |
| | Brakes | IN ORDER | Modification | | STANDARD ALLOY RIM |
| | General | GOOD | | | |
| 3. Conditions of Tyres | | | | | |
| | | Size | Make | | Balance |
| | R/H Front Tyre | 185/70 R14 | DUNLOP | | 9 mm |
| | L/H Front Tyre | 185/70 R14 | DUNLOP | | 9 mm |
| | R/H Rear Tyre | 185/70 R14 | DUNLOP | | 9 mm |
| | L/H Rear Tyre | 185/70 R14 | DUNLOP | | 9 mm |
| 4. | Description of Damages | | | | |
| | THE VEHICLE SUSTAINED DAMAGES AT THE O/S FRONT BODY. | | | | |
| | DAMAGES SEE DETAILS. | | | | |
| | | | | | 1. |
| 5. | General Information | | | | |
| | Accident Date | 24/08/2022 | Inspect Date / | Time | 29/08/2022 (11:05 AM) |
| | Survey held at | MBM WHEELPOWER PTE LTD | - | | |
| | | 176 SIN MING DRIVE #06-09 SIN MING AUTOCARE SINGAPORE 575721 | | | |
| 5a. | Remarks | | | | |
| | A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS. | | | | |
| 5b. | Estimate Days of Repair | | | | |
| | ESTIMATED NORMAL PERIOD FOR REPAIR: 6 Working Days | | | | |