

**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

**VEHICLE DAMAGE INSPECTION REPORT****Our File No:** CC6/III22008335/APA3Q2**Date:** 17/02/2023REFERENCE

Handling Insurer: India International Insurance Pte Ltd Policy No: D22MPC0002769  
**Claimant Vehicle No :** SLP5819X **Insured Vehicle No :** SLS2960Z  
 Date of Loss: 27/08/2022 Nature of Claim: TP Claim No: MPC2022D0004792

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SLP5819X**  
 Make & Model: MAZDA 3, 1.5 HATCHBACK DELUXE EU6 (A) Engine No: P520449607  
 Reg. Date: 09/06/2017 (Man. Year: 2017) Chassis No: JM6BN24A8H0156867  
 Colour: Bronze Odometer: 80576 km  
 Engine Capacity: 1496 cc  
 Market Value/New Car Price: N/A  
 Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes  
 Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 205/60 R16 Rear Tyre Size: 205/60 R16  
 Front Left Side: Michelin 6 mm Rear Left Side: Michelin 6 mm  
 Front Right Side: Michelin 6 mm Rear Right Side: Michelin 6 mm

*The above values represent the remaining tyre treads depth*

| <b>COST OF CLAIMS</b>                           | <b>Repairer's</b> | <b>Adjuster's</b> | <b>Difference</b> | <b>Diff %</b> |
|-------------------------------------------------|-------------------|-------------------|-------------------|---------------|
| Parts                                           | 12,942.80         | 7,195.60          | 5,747.20          | 44.40         |
| Miscellaneous Items                             | 0.00              | 0.00              | 0.00              |               |
| Labour                                          | 4,080.00          | 2,870.00          | 1,210.00          | 29.66         |
| Paintwork Labour                                | 0.00              | 0.00              | 0.00              |               |
| Towing                                          | 0.00              | 0.00              | 0.00              |               |
| <b>Calculated Gross Total (S\$)</b>             | <b>17,022.80</b>  | <b>10,065.60</b>  | <b>6,957.20</b>   | <b>40.87</b>  |
| <b>Approved Total (Overridden) (S\$)</b>        |                   | <b>8,000.00</b>   |                   |               |
| <b>Nett Amount (S\$)</b>                        | <b>17,022.80</b>  | <b>8,000.00</b>   | <b>9,022.80</b>   | <b>53.00</b>  |
| <b>+ Loss of Use (8.0 x S\$60.00/day) (S\$)</b> |                   | 480.00            |                   |               |
| <b>Nett Liability (S\$)</b>                     |                   | <b>8,480.00</b>   |                   |               |

INSPECTION

Date of Assignment: 31/08/2022  
 Date Inspected: 31/08/2022 Inspected At: ADVANCE AUTO GARAGE (23 KAKI BUKIT) (HQ)  
 25 KAKI BUKIT AVE 4 #04-01 VICOM KAKI BUKIT  
 Singapore 415933  
 Estimated Period of Repair: 7.0 days

**Adjuster:** ADRIAN LING**Manager:** CHEW HSIAO TONG

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

## REPAIR DETAILS

### Reference

|                      |                                                                                                                                                                              |                                                                        |
|----------------------|------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|------------------------------------------------------------------------|
| <b>Part Source:</b>  | MRM-SG                                                                                                                                                                       | Version: 1.0 (Last Synchronised: 22 Nov 2022)                          |
| <b>Parts:</b>        | 144                                                                                                                                                                          | MAZDA 3 1.5 HATCHBACK DELUXE EU6 (A) (Catalogue:Merimen Singapore 1.0) |
| <b>Labour:</b>       | Repairer's                                                                                                                                                                   | (Price-denominated Standard List)                                      |
| <b>Print Code:</b>   | (Unsubmitted, no print-code for SLP5819X)                                                                                                                                    |                                                                        |
| <b>Validity:</b>     | These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page |                                                                        |
| <b>Further Info:</b> | Items/values not in reference catalogue are prefixed with an asterisk *.                                                                                                     |                                                                        |

### Recommended Parts

| No. | Qty | Part No. | Particulars                            | Condition            | Repairer's | Amount       |
|-----|-----|----------|----------------------------------------|----------------------|------------|--------------|
| 1   | 1   |          | *REAR BUMPER                           | Distorted            | 1,124.50 F | *1,124.50 FL |
| 2   | 1   |          | *REAR BUMPER CLIPS                     | Necessary            | 50.00 FS   | *30.00 FS    |
| 3   | 1   |          | *REAR BUMPER SIDE HOLDER               | O/S Damaged          | 128.60 F   | *64.30 FL    |
| 4   | 1   |          | *REAR BUMPER REFLECTOR RH              | Cracked              | 58.80 F    | *58.80 FL    |
| 5   | 1   |          | *REAR BUMPER REINFORCEMENT             | Dented               | 564.20 F   | *564.20 FL   |
| 6   | 1   |          | *REAR BUMPER TOW COVER                 | Deformed             | 43.50 F    | *43.50 FL    |
| 7   | 4   |          | *REVERSE SENSOR                        | Damaged (2 PCS ONLY) | 1,276.00 F | *638.00 FL   |
| 8   | 4   |          | *REVERSE SENSOR HOLDER                 | Necessary            | 80.00 F    | *80.00 FL    |
| 9   | 1   |          | *REAR END PANEL                        | Dented               | 676.30 F   | *676.30 FL   |
| 10  | 1   |          | *REAR END PANEL TOP GARNISH            | Deformed             | 105.10 F   | *105.10 FL   |
| 11  | 1   |          | *REAR END PANEL TOP GARNISH CLIPS      | Necessary            | 20.00 FS   | *20.00 FS    |
| 12  | 1   |          | *REAR END PANEL SEALANT                | Necessary            | 60.00 FS   | *60.00 FS    |
| 13  | 1   |          | *TAILLAMP RH                           | Cracked              | 926.00 F   | *926.00 FL   |
| 14  | 1   |          | *TAILLAMP PANEL RH                     | Buckled              | 489.10 F   | *489.10 FL   |
| 15  | 1   |          | *TAILGATE                              | Dented               | 1,332.20 F | *1,332.20 FL |
| 16  | 1   |          | *TAILGATE LOCK                         | Damaged              | 321.20 F   | *321.20 FL   |
| 17  | 1   |          | *TAILGATE WEATHERSTRIPE                | Cut                  | 368.20 F   | *368.20 FL   |
| 18  | 1   |          | *TAILGATE OUTER GARNISH                | Cracked              | 427.90 F   | *427.90 FL   |
| 19  | 1   |          | *TAILGATE OUTER GARNISH CLIPS          | Necessary            | 30.00 FS   | *30.00 FS    |
| 20  | 1   |          | *TAILGATE REFLECTOR RH                 | Not Necessary        | 586.50 F   | *- FL        |
| 21  | 1   |          | *TAILGATE INNER TRIM BOARD             | Cracked              | 585.40 F   | *585.40 FL   |
| 22  | 1   |          | *TAILGATE INNER TRIM BOARD CLIPS       | Necessary            | 30.00 FS   | *30.00 FS    |
| 23  | 1   |          | *TAILGATE GLASS MOULDING               | Necessary            | 165.20 F   | *165.20 FL   |
| 24  | 1   |          | *TAILGATE GLASS SEALANT                | Necessary            | 60.00 FS   | *60.00 FS    |
| 25  | 1   |          | *MAZDA LOGO                            | Necessary            | 75.60 F    | *75.60 FL    |
| 26  | 1   |          | *MAZDA WORDING                         | Necessary            | 68.90 F    | *68.90 FL    |
| 27  | 1   |          | *SKYACTIV EMBLEM                       | Necessary            | 69.90 F    | *69.90 FL    |
| 28  | 1   |          | *REAR RH FENDER                        | Repair               | 1,284.20 F | *- FL        |
| 29  | 1   |          | *REAR RH FENDER INNER TRIM BOARD       | Cracked              | 485.20 F   | *485.20 FL   |
| 30  | 1   |          | *REAR RH FENDER INNER TRIM BOARD CLIPS | Necessary            | 30.00 FS   | *30.00 FS    |
| 31  | 1   |          | *SPARE TYRE PANEL TOP BOARD            | Not Necessary        | 308.60 F   | *- FL        |
| 32  | 1   |          | *REAR EXHAUST PIPE                     | Not Necessary        | 1,075.80 F | *- FL        |
| 33  | 1   |          | *REAR EXHAUST PIPE MOUNTING            | Not Necessary        | 35.90 F    | *- FL        |

F=Franchise part. S=SpcNett. L=ListItemDisc.

|                                                         |                  |                 |
|---------------------------------------------------------|------------------|-----------------|
| <b>Sub Total (\$)</b>                                   | <b>12,942.80</b> | <b>8,929.50</b> |
| <b>- List Item Discount on L Items 0.00/20.00% (\$)</b> | <b>0.00</b>      | <b>1,733.90</b> |
| <b>Total Parts (\$)</b>                                 | <b>12,942.80</b> | <b>7,195.60</b> |

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

| No                             | Particulars                   | Lab.Type | Repairer's      | Amount          |
|--------------------------------|-------------------------------|----------|-----------------|-----------------|
| <b>Labour Items</b>            |                               |          |                 |                 |
| 1                              | PANEL BEATING                 | New      | 1,500.00        | 1,200.00        |
| 2                              | SPRAY PAINTING                | New      | 1,400.00        | 1,100.00        |
| 3                              | WIRING                        | New      | 100.00          | 30.00           |
| 4                              | TO SPRAY TUFF COAT            | New      | 150.00          | 100.00          |
| 5                              | TO REMOVE UPHOLSTERY          | New      | 150.00          | 80.00           |
| 6                              | TO REMOVE REVERSE SENSOR      | New      | 100.00          | 60.00           |
| 7                              | TO REMOVE REAR CAMERA         | New      | 100.00          | 50.00           |
| 8                              | TO REMOVE VIDEO RECORDER      | New      | 100.00          | 50.00           |
| 9                              | TO TRANSFER TAILGATE FITTINGS | New      | 150.00          | 80.00           |
| 10                             | TO REMOVE TAILGATE GLASS      | New      | 180.00          | 120.00          |
| 11                             | TO REMOVE EXHAUST PIPE        | New      | 150.00          | 0.00            |
| <b>Gross Labour Cost (S\$)</b> |                               |          | <b>4,080.00</b> | <b>2,870.00</b> |

Report was unsubmitted during this print-out.

< END OF ESTIMATES >