

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS/MSG22008337/UQY3M4**Date:** 04/10/2022REFERENCE

Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd.	Policy No:	1001468650
Claimant Vehicle No :	GBJ9636E	Insured Vehicle No :	YN6239U
Date of Loss:	04/08/2022	Nature of Claim:	TP
		Claim No:	281455

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	GBJ9636E		
Make & Model:	MITSUBISHI CANTER, 3.0 D FEA01BR2SDEK (CBU)	Engine No:	4P10D70192
Reg. Date:	29/10/2019 (Man. Year: 2019)	Chassis No:	FEA01BA30281
Colour:	White	Odometer:	123263 km
Engine Capacity:	2998 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	195 R15	Rear Tyre Size:	195 R15 (D/D)
Front Left Side:	Austone 5 mm	Rear Left Side:	Austone 5/5 mm
Front Right Side:	Austone 5 mm	Rear Right Side:	Austone 5/5 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	889.60	541.32	348.28	39.15
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,130.00	610.00	520.00	46.02
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	2,019.60	1,151.32	868.28	42.99
Approved Total (Overridden) (S\$)		900.00		
Nett Amount (S\$)	2,019.60	900.00	1,119.60	55.44

INSPECTION

Date of Assignment:	29/08/2022	
Date Inspected:	29/08/2022 Inspected At:	LIU'S BROTHER AUTO ENGINEERING WORKSHOP (HQ) BLK 1 KAKI BUKIT AVE 6, #01-01 AUTO BAY @ KAKI BUKIT SINGAPORE 417883
Estimated Period of Repair:	3.0 days	

Adjuster: MARCUS CHUA**Manager:** SHIAU CHAN*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

REPAIR DETAILS

Reference

Part Source: (Last Synchronised: 04 Oct 2022)

Parts: N/A MITSUBISHI CANTER 3.0 D FEA01BR2SDEK (CBU) (M) (Model not available in database)

Labour: Repairer's (Price-denominated Standard List)

Print Code: (Unsubmitted, no print-code for GBJ9636E)

Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount	
1	1		*REAR LH TAIL LAMP	Cracked	239.60 F	*175.10 FL	
2	1		*SET REVERSE SENSOR	Shorted	220.00 FS	*200.00 FS	
3	1		*REAR LH 70 KM/H STICKER	Necessary	15.00 FS	*10.00 FS	
4	1		*REAR LH 12PAX STICKER	Not Necessary	15.00 FS	*- FS	
5	1		*REAR LH CORPORATE ADVERTISEMENT & ARTWORK	Necessary	400.00 FS	*200.00 FS	
					Sub Total (S\$)	889.60	585.10
					- List Item Discount on L Items 0.00/25.00% (S\$)	0.00	43.78
					Total Parts (S\$)	889.60	541.32

F=Franchise part. S=SpcNett. L=ListItemDisc.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO CHECK ALL WIRING & ELECTRICAL COMPONENT FOR PROPER FUNCTION	New	30.00	10.00
2	LABOR FOR PANEL BEATING, CUT, WELD, STRAIGHTEN & REPLACING PARTS ETCS	New	500.00	300.00
3	TO PUTTY & SPRAY PAINTING & INCLUDING TOUCH UP PAINT ON ACCIDENT AFFECTED AREAS	New	600.00	300.00
			Gross Labour Cost (\$\$)	610.00
			1,130.00	610.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >