

**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

**VEHICLE DAMAGE INSPECTION REPORT****Our File No:** CC6/AIG22008339/UPA3Q2**Date:** 25/10/2022REFERENCE

|                              |                                      |                             |              |
|------------------------------|--------------------------------------|-----------------------------|--------------|
| Handling Insurer:            | AIG Asia Pacific Insurance Pte. Ltd. | Policy No:                  | 7210142684   |
| <b>Claimant Vehicle No :</b> | SNE4147S                             | <b>Insured Vehicle No :</b> | SLU1571J     |
| Date of Loss:                | 29/08/2022                           | Nature of Claim:            | TP           |
|                              |                                      | Claim No:                   | 6167910161SG |

DESCRIPTION & IDENTIFICATION OF VEHICLE

|                             |                                   |             |                   |
|-----------------------------|-----------------------------------|-------------|-------------------|
| Reg No:                     | <b>SNE4147S</b>                   |             |                   |
| Make & Model:               | NISSAN QASHQAI, 1.2 DIG-T (A)     | Engine No:  | HRA2398879A       |
| Reg. Date:                  | 17/06/2017 (Man. Year: 2017)      | Chassis No: | VSKDDAC13U0099736 |
| Colour:                     | White                             | Odometer:   | 44628 km          |
| Engine Capacity:            | 1197 cc                           |             |                   |
| Market Value/New Car Price: | N/A                               |             |                   |
| Sum Insured (\$\$):         | <b>Market Value/New Car Price</b> |             |                   |

CONDITION OF VEHICLE AT THE TIME OF SURVEY

|                          |                         |                      |                          |                         |
|--------------------------|-------------------------|----------------------|--------------------------|-------------------------|
| General Condition:       | Steering (Serviceable): | Yes                  | Footbrake (Serviceable): | Yes                     |
| Handbrake (Serviceable): | Yes                     | Engine Modification: | No                       | Pre-accident Condition: |

CONDITION OF TYRES

|                   |              |                  |              |
|-------------------|--------------|------------------|--------------|
| Front Tyre Size:  | 225/45 R17   | Rear Tyre Size:  | 225/45 R17   |
| Front Left Side:  | Pirelli 6 mm | Rear Left Side:  | Pirelli 6 mm |
| Front Right Side: | Pirelli 6 mm | Rear Right Side: | Pirelli 6 mm |

*The above values represent the remaining tyre treads depth*

| <b>COST OF CLAIMS</b>                             | <b>Repairer's</b> | <b>Adjuster's</b> | <b>Difference</b> | <b>Diff %</b> |
|---------------------------------------------------|-------------------|-------------------|-------------------|---------------|
| Parts                                             | 25,481.20         | 13,687.86         | 11,793.34         | 46.28         |
| Miscellaneous Items                               | 0.00              | 0.00              | 0.00              |               |
| Labour                                            | 5,650.00          | 3,890.00          | 1,760.00          | 31.15         |
| Paintwork Labour                                  | 0.00              | 0.00              | 0.00              |               |
| Towing                                            | 0.00              | 0.00              | 0.00              |               |
| <b>Calculated Gross Total (\$\$)</b>              | <b>31,131.20</b>  | <b>17,577.86</b>  | <b>13,553.34</b>  | <b>43.54</b>  |
| <b>Approved Total (Overridden) (\$\$)</b>         |                   | <b>14,000.00</b>  |                   |               |
| <b>(\$\$)</b>                                     | 31,131.20         | 14,000.00         | 17,131.20         | 55.03         |
| <b>+ GST 7.00/7.00% (\$\$)</b>                    | 2,179.18          | 980.00            | 1,199.18          | 55.03         |
| <b>Nett Amount (\$\$)</b>                         | <b>33,310.38</b>  | <b>14,980.00</b>  | <b>18,330.38</b>  | <b>55.03</b>  |
| <b>+ Loss of Use (16.0 x S\$60.00/day) (\$\$)</b> |                   | 960.00            |                   |               |
| <b>+ Doc/Search Fee (\$\$)</b>                    |                   | 2.00              |                   |               |
| <b>Nett Liability (\$\$)</b>                      |                   | <b>15,942.00</b>  |                   |               |
| <b>Global Sum Settlement (\$\$)</b>               |                   | <b>15,900.00</b>  |                   |               |

INSPECTION

|                             |            |               |                                                                                           |
|-----------------------------|------------|---------------|-------------------------------------------------------------------------------------------|
| Date of Assignment:         | 29/08/2022 |               |                                                                                           |
| Date Inspected:             | 29/08/2022 | Inspected At: | Fastech Auto Pte Ltd (HQ)<br>1 Kaki Bukit Ave 6, #01-46/48/50 Autobay<br>Singapore 417883 |
| Estimated Period of Repair: | 14.0 days  |               |                                                                                           |

---

**Adjuster:** MARCUS CHUA

**Manager:** CHEW HSIAO TONG

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

# REPAIR DETAILS

## Recommended Parts

| No. | Qty | Part No. | Particulars                           | Condition          | Repairer's | Amount       |
|-----|-----|----------|---------------------------------------|--------------------|------------|--------------|
| 1   | 1   |          | *REAR WINDSCREEN MOULDING             | Necessary          | 118.00 F   | *118.00 FL   |
| 2   | 1   |          | *TAILGATE                             | Dented             | 1,915.00 F | *1,485.80 FL |
| 3   | 1   |          | *TAILGATE REAR LOGO                   | Necessary          | 80.00 F    | *65.00 FL    |
| 4   | 1   |          | *TAILGATE PULSAR EMBLEM               | Necessary          | 105.00 F   | *102.00 FL   |
| 5   | 1   |          | *TAILGATE OUTER HANDLE                | Cracked            | 245.00 F   | *182.00 FL   |
| 6   | 1   |          | *TAILGATE INNER LOCK                  | Bent               | 299.00 F   | *172.30 FL   |
| 7   | 1   |          | *TAILGATE WEATHERSTRIP                | Twisted            | 285.00 F   | *178.60 FL   |
| 8   | 1   |          | *TAILGATE INNER TRIM BOARD            | Deformed / Cracked | 605.00 F   | *306.80 FL   |
| 9   | 2   |          | *TAILGATE REFLECTORS                  | Cracked            | 840.00 F   | *610.00 FL   |
| 10  | 1   |          | *TAILGATE LICENCE PLATE LAMP          | Not Necessary      | 65.00 F    | *- FL        |
| 11  | 1   |          | *REAR BUMPER                          | Dented             | 886.00 F   | *886.00 FL   |
| 12  | 1   |          | *REAR BUMPER SPONGE                   | Torn               | 188.00 F   | *188.00 FL   |
| 13  | 1   |          | *REAR BUMPER BEAM                     | Bent               | 583.10 F   | *583.10 FL   |
| 14  | 2   |          | *REAR BUMPER BRACKETS                 | Bent               | 290.00 F   | *290.00 FL   |
| 15  | 2   |          | *REAR BUMPER SIDE RETAINERS           | Bent               | 90.00 F    | *90.00 FL    |
| 16  | 1   |          | *REAR END PANEL                       | Dented             | 715.00 F   | *715.00 FL   |
| 17  | 1   |          | *REAR END PANEL TOP GARNISH           | Twisted            | 282.00 F   | *242.90 FL   |
| 18  | 1   |          | *REAR END PANEL ANTENNA SENSOR        | Not fitted         | 308.00 F   | *- FL        |
| 19  | 2   |          | *TAILLAMPS                            | Cracked            | 1,300.00 F | *880.00 FL   |
| 20  | 2   |          | *TAILLAMP HOUSING PANELS              | Repair             | 850.00 F   | *- FL        |
| 21  | 1   |          | *REAR FLOOR PANEL                     | Repair             | 981.00 F   | *- FL        |
| 22  | 1   |          | *REAR FLOOR PANEL TOP BOARD           | Torn               | 485.00 F   | *485.00 FL   |
| 23  | 1   |          | *BONNET                               | Repair             | 1,485.00 F | *- FL        |
| 24  | 1   |          | *BONNET LOCK                          | Bent               | 182.00 F   | *182.00 FL   |
| 25  | 2   |          | *BONNET HINGES                        | Not Necessary      | 180.00 F   | *- FL        |
| 26  | 1   |          | *FRONT BUMPER                         | Deformed / Torn    | 1,099.00 F | *1,094.00 FL |
| 27  | 2   |          | *FRONT BUMPER SIDE RETAINERS          | Bent               | 90.00 F    | *90.00 FL    |
| 28  | 1   |          | *FRONT BUMPER CENTRE GRILLE           | Not Necessary      | 135.00 F   | *- FL        |
| 29  | 1   |          | *FRONT BUMPER SPONGE                  | Torn               | 208.00 F   | *176.00 FL   |
| 30  | 1   |          | *FRONT BUMPER BEAM                    | Bent               | 455.00 F   | *454.00 FL   |
| 31  | 1   |          | *SET FRONT BUMPER CLIPS               | Necessary          | 35.00 F    | *35.00 FL    |
| 32  | 1   |          | *FRONT GRILLE                         | Cracked            | 688.20 F   | *422.70 FL   |
| 33  | 1   |          | *FRONT GRILLE CHROME MOULDING         | Cracked            | 250.00 F   | *250.00 FL   |
| 34  | 2   |          | *HEADLAMPS                            | Holder Cracked     | 3,900.00 F | *3,160.00 FL |
| 35  | 1   |          | *FRONT SUPPORT PANEL                  | Bent               | 752.00 F   | *411.20 FL   |
| 36  | 1   |          | *FRONT SUPPORT PANEL TOP GARNISH      | Not Necessary      | 211.00 F   | *- FL        |
| 37  | 1   |          | *CONDENSER                            | Bent / Punctured   | 1,011.00 F | *820.00 FL   |
| 38  | 1   |          | *CONDENSER SIDE GARNISH               | Not Necessary      | 166.00 F   | *- FL        |
| 39  | 1   |          | *RADIATOR                             | Not Necessary      | 1,088.90 F | *- FL        |
| 40  | 1   |          | *RADIATOR FAN ASSY                    | Not Necessary      | 850.00 F   | *- FL        |
| 41  | 1   |          | *REAR WINDSCREEN SEALANT              | Necessary          | 50.00 FS   | *40.00 FS    |
| 42  | 1   |          | *REAR WINDSCREEN INNER SEAL           | Necessary          | 50.00 FS   | *40.00 FS    |
| 43  | 1   |          | *SET TAILGATE INNER TRIM BOARD CLIPS  | Necessary          | 35.00 FS   | *35.00 FS    |
| 44  | 1   |          | *SET REAR BUMPER CLIPS                | Necessary          | 35.00 FS   | *35.00 FS    |
| 45  | 1   |          | *SET REAR BUMPER LOWER CARBON STICKER | Not fitted         | 200.00 FS  | *- FS        |
| 46  | 1   |          | *REAR END PANEL SEALANT               | Necessary          | 50.00 FS   | *50.00 FS    |
| 47  | 1   |          | *REAR LICENCE PLATE                   | Cracked            | 50.00 FS   | *40.00 FS    |
| 48  | 1   |          | *SET REAR REVERSE CAMERA              | Not Necessary      | 380.00 FS  | *- FS        |
| 49  | 1   |          | *SET REAR BUMPER REVERSE SENSOR       | Shorted            | 280.00 FS  | *200.00 FS   |
| 50  | 1   |          | *FRONT LICENCE PLATE                  | Cracked            | 50.00 FS   | *40.00 FS    |

F=Franchise part. S=SpcNett. L=ListItemDisc.

Report was unsubmitted during this print-out.

| No. | Qty | Part No. | Particulars | Condition | Repairer's                                       | Amount    |           |
|-----|-----|----------|-------------|-----------|--------------------------------------------------|-----------|-----------|
|     |     |          |             |           | Sub Total (\$)                                   | 25,481.20 | 15,155.40 |
|     |     |          |             |           | - List Item Discount on L Items 0.00/10.00% (\$) | 0.00      | 1,467.54  |
|     |     |          |             |           | Total Parts (\$)                                 | 25,481.20 | 13,687.86 |

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

| No                              | Particulars                                 | Lab.Type | Repairer's      | Amount          |
|---------------------------------|---------------------------------------------|----------|-----------------|-----------------|
| <b>Labour Items</b>             |                                             |          |                 |                 |
| 1                               | TO CHECK WIRING                             | New      | 50.00           | 30.00           |
| 2                               | TO DISMANTLE & REPLACED REAR REVERSE SENSOR | New      | 80.00           | 50.00           |
| 3                               | TO DISMANTLE & REFIX REAR WINDSCREEN        | New      | 120.00          | 120.00          |
| 4                               | TO TRANSFER TAILGATE MECHANISM              | New      | 100.00          | 60.00           |
| 5                               | TO DISMANTLE & REFIX CUSHION UPHOLSTERY     | New      | 120.00          | 80.00           |
| 6                               | TO SPRAY RUST PROOFING                      | New      | 100.00          | 90.00           |
| 7                               | TO RESET & DIAGNOSTIC SYSTEM                | New      | 180.00          | 60.00           |
| 8                               | TO REFILL AIR CON GAS                       | New      | 120.00          | 100.00          |
| 9                               | LABOUR FOR PANEL BEATING & REPLACED PARTS   | New      | 2,280.00        | 1,500.00        |
| 10                              | TO PUTTY & SPRAY PAINTING                   | New      | 2,500.00        | 1,800.00        |
| <b>Gross Labour Cost (\$\$)</b> |                                             |          | <b>5,650.00</b> | <b>3,890.00</b> |

Report was unsubmitted during this print-out.

< END OF ESTIMATES >