

2 Kaki Bukit Ave 2, #02-19/22 AutoHub @ Kaki Bukit, Singapore 417921

Email: ryderautoworkshop@gmail.com

Tel: 67418277 Fax: 67468277

ESTIMATE OF REPAIR

Veh# : GBK4533X

Accident Date : 26/822

Location : JUNCTION OF TUAS SOUNT AVE 2 & TUAS SOUTH AVE 3

3P:

YP1717D

TPEQ. Aline
FEA01BA30419.
Model: MITSUBISHI CANTER FEA
3/8/2020

S/Nos.	Qty	Description	List \$	S/Nett \$	Nett \$
1	1 pc	Front bumper <i>Disl'd</i>	845.60	✓	
2	1 pc	Front bumper bracket <i> Bent</i>	265.60	✓	
3	2pcs	Front bumper o/s & n/s garnish <i> Rtd Disl'd</i>	360.20	✓	
4	2pcs	Front o/s & n/s head lamp <i>2</i>	1,139.00	<i>569.50</i>	
5	2pcs	Front o/s & n/s signal lamp <i>2 o/s could</i>	639.00	<i>319.50</i>	
6	2pcs	Front o/s & n/s reflector lamp <i>1</i>	492.00	<i>246.</i>	
7	1 pc	Front panel (inner) <i> Keys</i>	2,473.30	+	
8	1 pc	Front panel (outter) <i> Distorted</i>	1,577.50	<i>1455</i>	
9	1 pc	Front o/s corner panel <i> could</i>	594.00	✓	
10	1 pc	Front grill <i> could</i>	710.20	✓	
11	8pcs	Front grill clips <i> 7</i>		64.00	<i>30</i>
12	1 pc	Front grill emblem <i> 7</i>	83.40	✓	
13	1 pc	Front grill FUSO emblem <i> New</i>	65.40	✓	
14	1 pc	Front heater <i> 2</i>	3517.20	+	
15	1 pc	Front cooling coil <i> 1</i>	2100.40	+	
16	1 pc	Front dash board <i> 1</i>		+	
17	1 pc	Front windscreen moulding <i> New</i>	245.60	✓	
18	1 pc	Front n/s side mirror bracket garnish <i> New</i>	85.60	+	
19	1pc	Front o/s door <i> Distorted</i>	1,310.75	✓	
20	1pc	Front o/s door weatherstrip <i> w/</i>	261.20	✓	
21	1pc	Front o/s door inner board <i> Deformed</i>	701.70	✓	
22	8pcs	Front o/s door inner board clips <i> New</i>		40.00	<i>30.</i>
23	1pc	Front o/s & door step fabric <i> Del'd</i>	151.30	✓	
24	2 pcs	Front o/s door hinges (Upper & Lower) <i> Not New</i>	226.80	✗	
25	1pc	Front o/s door lock <i> Jammed</i>	365.50	✓	
26	1pc	Front o/s door actuator <i> 2 Not Nec</i>	541.20	X	
27	1pc	Front o/s door checker <i> 1</i>	110.00	X	
28	1pc	Front o/s door window regulator <i> Bunc</i>	383.40	✓	
29	1pc	Front o/s door window motor <i> New</i>	485.40	+	
30	1pc	Front o/s door window seal (Outer) <i> New</i>	452.80	✗	
31	1pc	Front o/s door wheel arch garnish <i> Del'd</i>	220.00	✓	
32	1 pc	Front o/s door company sticker <i> New</i>		30.00	✓

33	1 pc	Front o/s wheel housing panel <i>distorted</i>	810.40	<i>✓</i>	
34	1pc	Front o/s A pillar <i>Repair</i>	1,578.40	<i>X</i>	
35	1pc	Front cabin floor panel <i>Repair</i>		<i>+</i>	
36	1pc	Front cabin mounting <i>Not New</i>	742.40	<i>X</i>	
37	1 pc	Front dashboard <i>Not New</i>	1,889.20	<i>X</i>	
38	1 pc	Front dashboard bracket <i>Not New</i>	369.70	<i>X</i>	
39	1 pc	Brake pump <i>Not New</i>	589.60	<i>X</i>	
40	1 pc	Brake servo <i>Not New</i>	1,024.70	<i>X</i>	
41	1 pc	Brake oil <i>Not New</i>		80.00	<i>X</i>
42	1 pc	Brake pedal bracket	564.70	<i>+</i>	
43	1 pc	Clutch pump	571.20	<i>+</i>	
44	1 pc	Clutch pedal bracket	381.10	<i>+</i>	
45	1 pc	Front reg. no. plate bracket <i>Best</i>		31.00	<i>✓</i>
<i>S N: 121</i>			Sub-Total:	28,925.45	245.00 0.00
				10%	0% 0%
			After Less %:	26,032.91	245.00 0.00
Labour					
1		To dismantle, refit & repair damaged parts	2,200.00	<i>1200</i>	
2		To spray painting	1,600.00	<i>1100</i>	
3		To remove and replace front dash board & wiring	500.00	<i>X</i>	
4		To remove and refit front windscreen	150.00	<i>120</i>	
5		TO remove and refit upholstery to facilitate repair	200.00	<i>80</i>	
6		To remove and replace front o/s door <i>Fittings</i>	100.00	<i>80</i>	
7		To remove and replace front brake servo, clutch & bleeding	200.00	<i>X</i>	
8		To check for fault code and resetting	180.00	<i>+</i>	
9		To check for wheel alignment	180.00	<i>+</i>	
10		To re-seal anti-rust	50.00	<i>✓</i>	
11		To check wiring	50.00	<i>30</i>	
			Sub-Total:	5,410.00	
			Total:	31,687.91	
			After Less 20%:	25,350.32	

Chan

Chan San Choon
Director
DipEng, AAE MIMI,MSAE(Aust)

Adrian G
A/S 29/08/22
12 Days



LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed **and** is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

GBK4533X ESTIMATEPg2

2 Kaki Bukit Ave 2, #02-19/22 AutoHub @ Kaki Bukit, Singapore 417921

Email: ryderautoworkshop@gmail.com

Tel: 67418277 Fax: 67468277

ESTIMATE OF REPAIR

Veh# : GBK4533X

Model: MITSUBISHI CANTER FEA

Accident Date : 26/822

3/8/2020

Location JUNCTION OF TUAS SOUNT AVE 2 & TUAS SOUTH AVE 3

3P:

YP1717D

S/Nos.	Qty	Description	List \$	S/Nett \$	Nett \$
1	1 pc	Front o/s A pillar panel lower <i>Detached</i>	245.60	✓	
2	1 pc	Front o/s Air box <i>Detached</i>	350.00	✓	
3	1 pc	Front o/s head lamp bracket <i>New</i>	80.10	X.	
4	1 pc	Front o/s door handle <i>Cracked</i>	180.20	✓	
5	1 pc	Front o/s door air vent <i>Damaged</i>	80.00	✓	
6	1 pc	Blower <i>New</i>	3,230.60	X	
7	1 pc	Heater <i>Cracked</i>	2,650.50	✓ 1850	
8	1 pc	Front steering coupling <i>3M</i> <i>2850.80</i>	850.20	X	
9	1 pc	Front steering joint <i>3M</i>	3,400.20	X.	
10	1 pc	Front steering cover <i>Detached</i> <i>2138.10</i>	145.00	✓	
11	1 pc	Front steering cover seal <i>New</i>	30.00	✓	
Sub-Total:			11,242.40	0.00	0.00
			25%	0%	0%
After Less %:			8,431.80	0.00	0.00
Labour					
1		To remove and replace front blower & heater		500.00 <i>200.</i>	
Sub-Total:				500.00	
Total:				8,931.80	
After Less 20%:				7,145.44	

Chan

Chan San Choon
Director
DipEng, AAE MIMI,MSAE(Aust)

Supplementary: 2338.10

